	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-015-21419
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		K-4540
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	WHITE BABY COM.
	Gas Well X Other	8. Well Number
15.0		9. OGRID Number
2. Name of Operator	OL OR A DO	162683
CIMAREX ENERGY CO. OF CO. 3. Address of Operator	DLORADO	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701		WHITE CITY; PENN (GAS)
	oo, Midding, Texas 19701	WIII 2 CT 1, 12 W (CT 2)
4. Well Location	1000 Cat Care the COLITII line and 1000	feet from the WEST line
Unit Letter K :	1980 feet from the SOUTH line and 1980	
Section 16	Township 24S Range	26E NMPM EDDY County
THE PROPERTY OF THE PARTY OF TH	11. Elevation (Show whether DR, RKB, RT, GR, e.	ic.)
	3,415' - GR	是一直的 1
12 (11-	A anista Dan ta Indianta Natura of Natio	a Panart or Other Date
12. Check	Appropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF II	NTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		
TEMPORARILY ABANDON		RILLING OPNS. P AND A
PULL OR ALTER CASING		and the control of th
DOWNHOLE COMMINGLE		tify OCD 24 hrs. prior to any work
	do	
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
		Completions: Attach wellbore diagram of
proposed completion or re	ecompletion.	
1) SET 5-1/2" CIRP @		
1) SET 5-1/2" CIBP @ 11,100'; PUMP 45 SXS. CMT. @ 11,100'-10,762' (T/MRRW.). WOC & tag 2) SET 5-1/2" CIBP @ 10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CIRC. WELL W/ M.L.F. WOC & tag		
2) SET 5-1/2" CIBP @	11,100'; PUMP 45 SXS. CMT. @ 11,100'-10,762' (T	/MRRW.). WOC & tag RC, WELL W/ M.L.F, WOC & tag
2) SET 5-1/2" CIBP @	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CI	/MRRW.). WOC & tag RC. WELL W/ M.L.F. WOC & tag
2) SET 5-1/2" CIBP @	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CI 7. @ 8,508'-8,328' (T/WLCP.).	/MRRW.). WOC & tag RC. WELL W/ M.L.F. WOC & tag
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CI 7. @ 8,508'-8,328' (T/WLCP.).	RC. WELL W/ M.L.F. (WOC & tag)
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CM PUMP 50 SXS. CMT 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.).	RC. WELL W/ M.L.F. (WOC & tag) OC X TAG CMT. PLUG.
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CM PUMP 50 SXS. CMT PUMP 45 SXS. CMT 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG	RC. WELL W/ M.L.F. (WOC & tag) OC X TAG CMT. PLUG. CMT. PLUG.
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CM PUMP 50 SXS. CMT PUMP 45 SXS. CMT PERF. X ATTEMPT 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13	RC. WELL W/ M.L.F. (WOC & tag) OC X TAG CMT. PLUG. CMT. PLUG. 1-3/8" CSG.SHOE); WOC X TAG CMT. PLUG.
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CM PUMP 50 SXS. CMT PUMP 45 SXS. CMT PERF. X ATTEMPT PERF. X CIRC. TO S 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6	CMT. PLUG. CMT. PLUG. 3'-3'.
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CMT PUMP 50 SXS. CMT PUMP 45 SXS. CMT PERF. X ATTEMPT PERF. X CIRC. TO S DIG OUT X CUT OF 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6 FF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI	CMT. PLUG. CMT. PLUG. 3'-3'.
 SET 5-1/2" CIBP @ PUMP 25 SXS. CMT CUT X PULL 5-1/2" PUMP 100 SXS. CMT PUMP 50 SXS. CMT PUMP 45 SXS. CMT PERF. X ATTEMPT PERF. X CIRC. TO S DIG OUT X CUT OF 	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6	CMT. PLUG. CMT. PLUG. 3'-3'.
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6 FF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI	CMT. PLUG. CMT. PLUG. 3'-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CM 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W C. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6 FF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI	CMT. PLUG. CMT. PLUG. 3'-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CM 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE (2. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W (2. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG (TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 65'F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. OURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE CL	CMT. PLUG. CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CM 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE (2. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W (2. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG (TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 65'F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. OURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE CL	CMT. PLUG. CMT. PLUG. 3'-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. FOURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF	OC X TAG CMT. PLUG. CMT. PLUG. G-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE (2. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W (2. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG (TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 65'F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. OURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE CL	OC X TAG CMT. PLUG. CMT. PLUG. G-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. FOURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF	OC X TAG CMT. PLUG. CMT. PLUG. G-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CM 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attaches I hereby certify that the information	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURIFINSTALL DRY HOLE MARKER. FURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED COOP OF THE CLOSED	OC X TAG CMT. PLUG. CMT. PLUG. 6-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21 dge and belief.
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURI INSTALL DRY HOLE MARKER. FOURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF	OC X TAG CMT. PLUG. CMT. PLUG. G-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache I hereby certify that the information SIGNATURE	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURIFINSTALL DRY HOLE MARKER. SURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE C	OC X TAG CMT. PLUG. CMT. PLUG. 6-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21 dge and belief.
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache I hereby certify that the information SIGNATURE	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). C. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURIFINSTALL DRY HOLE MARKER. SURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE C	OC X TAG CMT. PLUG. CMT. PLUG. 6-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21 dge and belief. DATE: 03/19/20
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache I hereby certify that the information SIGNATURE Type or print name: DAVID A. I For State Use Only	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURIFINSTALL DRY HOLE MARKER. SURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE	OC X TAG CMT. PLUG. CMT. PLUG. G-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21 dge and belief. DATE: 03/19/20 GRO-RES.COM PHONE: 432.687.3033
2) SET 5-1/2" CIBP @ 3) PUMP 25 SXS. CMT 4) CUT X PULL 5-1/2" 5) PUMP 100 SXS. CMT 6) PUMP 50 SXS. CMT 7) PUMP 45 SXS. CMT 8) PERF. X ATTEMPT 9) PERF. X CIRC. TO S 10) DIG OUT X CUT OF PLATE TO CSGS. X DURING THIS PROCED CONTENTS TO THE RE ***See Attache Type or print name: DAVID A. 1	10,000'; PUMP 25 SXS. CMT. @ 10,000'-9,800'; CE C. @ 8,508'-8,328' (T/WLCP.). CSG. @ +/-5,465'. T. @ 5,515'-5,230' (5-1/2" CSG.CUT, T/BNSG.); W. G. @ 3,498'-3,368' (T/DLWR.). T. @ 1,695'-1,585' (B/SALT/ANHY.); WOC X TAG. TO SQZ. 90 SXS. CMT. @ 515'-326' (T/ANHY., 13 SURF., FILLING ALL ANNULI, 45 SXS. CMT. @ 6F WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURIFINSTALL DRY HOLE MARKER. SURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM OF THE CLOSED OF THE	OC X TAG CMT. PLUG. CMT. PLUG. 6-3/8" CSG.SHOE); WOC X TAG CMT. PLUG. 3'-3'. F. ON ALL ANNULI; WELD ON STEEL STEM W/ A STEEL TANK AND HAUL Be Plugged by 4/2/21 dge and belief. DATE: 03/19/20



