District I 1625 N. French Dr., Hobbs, NM 88240		New Mexico		Form C-10		
1023 14. 1 (Chell D1., 110003, 1414) 602-40	Energy, Minerals a	and Natural Resourc	es WELL API NO	October 13, 200	9	
District Il	OIL CONCEDA	ATION DIVISION		30-015-21398		
1301 W. Grand Ave., Artesia, NM 88210 District III		St. Francis Dr.	7. Indica	te Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410			STATE	⊠ FEE □		
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa re	, NM 87505	7. State (Oil & Gas Lease No.		
87505					į	
	ICES AND REPORTS ON		7. Lease Name	or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPL	OSALS TO DRILL OR TO DEEP ICATION FOR PERMIT" (FORN	EN OR PLUG BACK TO A A C-101) FOR SUCH	`	SRO SWD		
PROPOSALS.)	ionition for the state of the s					
1. Type of Well: Oil Well	Gas Well Other SW	RECEIVE	ED 8. Well Number	ет 102		
2. Name of Operator		NOV 15 20	9. OGRID Nur		=	
COG Operating LLC				229137		
3. Address of Operator	NA 00010	NMOCD ARTI	SIA 10. Pool name			
2208 W. Main Street, Artesia, 4. Well Location	NM 88210		S'	WD; Devonian	_	
4. Well Location Unit Letter G :	1980 feet from the	Month line and	1000 6-4-6	, the East line		
Section 16	Township 26S					
Section 10	11. Elevation (Show who		NMPM	Eddy County		
	11. Lievation (Bnow with	3024' GR	n, etc.)			
12. Check Appropriate Box t	o Indicate Nature of N	otice, Report or Ot	ther Data			
NOTICE OF I	NTENTION TO:	1	SUBSEQUENT R	EPORT OF		
PERFORM REMEDIAL WORK		REMEDIAL		ALTERING CASING	1	
TEMPORARILY ABANDON	CHANGE PLANS		E DRILLING OPNS.	P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL	☐ CASING/C	EMENT JOB			
DOWNHOLE COMMINGLE						
OTHER:		OTHER:	Repair Casing Leal			
13. Describe proposed or complete	d operations. (Clearly state	e all pertinent details, a	and give pertinent dates,	including estimated date of	f	
starting any proposed work). Scompletion or recompletion.	DEE RULE 19.13.7.14 NW	ac. For Multiple Con	npietions: Attach wellb	ore diagram of proposed		
completion of recompletion.						
10/10/11 to 11/1/11 MIRU WSU.	POOH w/4 1/2" csg. RIH w	RBP & set @ 14390'	. Dump 3 sx sand on to	of RBP. Set pkr @ 6261	Tect	
csg to 1000# for 10 mins. Ok. Loa	d 2 7/8" x 7" annulus & tes	t to 1500# for 10 mins	s. Ok. Bled down. Res	test down the to 1500# I	. 1031	
in 15 mine Pressured to 200# I a	in 15 mins. Pressured to 200#. Lost 500# in 15 mins. Rls pkr & reset @ 14345'. Test RBP to 1500#. Ok. Start pulling uphole looking for leak. Isolated leak between 11466-11528'. Leave pkr @ 11466'. Tested annulus to 4500# for 15 mins. Holding. Rls pkr & POOH w/pkr.					
in 15 mins. Pressured to 200#. Los leak. Isolated leak between 11466-	11528'. Leave pkr @ 1146	& reset @ 14345. 1	est RBP to 1500#. Ok.	Start pulling uphole looking	st 300# g for	
leak. Isolated leak between 11466-	11528'. Leave pkr @ 1146	6'. Tested annulus to	est RBP to 1500#. Ok. 4500# for 15 mins. Ho	Start pulling uphole looking. Rls pkr & POOH w	st 300# g for pkr.	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 'OC. RIH & tag @ 11415'.	66'. Tested annulus to 16'. Sting into rtnr on . Test csg to 2000#. (est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr	Start pulling uphole looking. Rls pkr & POOH wat 50 bbls cmt down tbg. To. Test csg to 2000# for 30	ost 300# g for pkr. iled in mins.	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. or RBP on 463 jts 2 7/8" tb	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wt 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64	ost 300# g for pkr. iled in mins.	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. or RBP on 463 jts 2 7/8" tb	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wt 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64	ost 300# g for pkr. iled in mins.	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. or RBP on 463 jts 2 7/8" tb	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wt 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64	ost 300# g for pkr. iled in mins.	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. or RBP on 463 jts 2 7/8" tb	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Ris pkr & POOH wit 50 bbls cmt down tbg. To Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.67. Turn well to production.	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. or RBP on 463 jts 2 7/8" tb	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wt 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" tb csg to 3000# for 15 mins.	66'. Tested annulus to 06'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to 1	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH w t 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64 Turn well to production.	ost 300# g for /pkr. illed in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" tb csg to 3000# for 15 mins.	66'. Tested annulus to 06'. Sting into rtnr on . Test csg to 2000#. (g. Wash sand off RB	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.67 Turn well to production. RECEIVER	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" tb csg to 3000# for 15 mins.	66'. Tested annulus to 06'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to 1	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH w t 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 1/2" P-110 11.64 Turn well to production.	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" tb csg to 3000# for 15 mins.	66'. Tested annulus to 06'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to 1	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.67 Turn well to production. RECEIVER	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" tb csg to 3000# for 15 mins.	6'. Tested annulus to 06'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to 1	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spook. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok.	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.67 Turn well to production. RECEIVER	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" ASIX pkr. Set @ 14395'. Test Spud Date:	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" to csg to 3000# for 15 mins.	6'. Tested annulus to 6'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to l Rig Release Date:	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok.	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/4 ½" P-110 11.64 Turn well to production. RECEIVER 15 2	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test	11528'. Leave pkr @ 1146 on RBP. Set CICR @ 1140 OC. RIH & tag @ 11415'. for RBP on 463 jts 2 7/8" to csg to 3000# for 15 mins.	6'. Tested annulus to 06'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to 1	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok.	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.67 Turn well to production. RECEIVER	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test Spud Date: Thereby certify that the information about SIGNATURE Type or print name Stormi Day	on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. For RBP on 463 jts 2 7/8" to csg to 3000# for 15 mins.	6'. Tested annulus to 6'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB) Ok. Test annulus to l Rig Release Date:	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok.	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/4 ½" P-110 11.64 Turn well to production. RECEIVER 15 2	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test Spud Date: Thereby certify that the information about SIGNATURE Type or print name Stormi Dav For State Use Only	on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. For RBP on 463 jts 2 7/8" to csg to 3000# for 15 mins.	6'. Tested annulus to 6'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB Ok. Test annulus to 1 Rig Release Date: best of my knowledge a E Regulatory Ana il address: sdavis@cc	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok. nd belief. lyst	Start pulling uphole looking. Rls pkr & POOH wit 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.64 Turn well to production. RECEIVENTAL PHONE: 575-748-6946	ost 300# g for pkr. iled in mins. csg &	
leak. Isolated leak between 11466-MIRU WL. Dump 6 more sx sand w/158 sx. Circ 33 sx to surface. W Good test. RIH w/retrieving head f 7" AS1X pkr. Set @ 14395'. Test Spud Date: Type or print name Stormi Day For State Use Only	on RBP. Set CICR @ 1146 OC. RIH & tag @ 11415'. For RBP on 463 jts 2 7/8" to csg to 3000# for 15 mins.	6'. Tested annulus to 6'. Sting into rtnr on Test csg to 2000#. (g. Wash sand off RB Ok. Test annulus to 1 Rig Release Date: best of my knowledge a E Regulatory Ana il address: sdavis@cc	est RBP to 1500#. Ok. 4500# for 15 mins. Ho 366 jts 2 7/8" tbg. Spo Ok. Drill out cmt & rtnr P. POOH w/workstring 000# for 15 mins. Ok. nd belief. lyst	Start pulling uphole looking. Rls pkr & POOH with 50 bbls cmt down tbg. Ta. Test csg to 2000# for 30. RIH w/ 4 ½" P-110 11.64 Turn well to production. RECEIVENTAL NOV 15 2 NMOCD ARTE 11/2/11	ost 300# g for pkr. iled in mins. csg &	