Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

i.	Lease	Serial	No.
	NIME	വദേ	282R

SUNDRY NOTICES AND REPORTS ON WELLS

abandoned we	is form for proposals to dr.	4			
	III. USE TORM 3 160-3 (APD)	for such proposals.	6. 1	f Indian, Allottee or Tribe Name	
SUBMIT IN TRI	PLICATE - Other instruction	ons on reverse side.	7. I	f Unit or CA/Agreement, Name and/or No.	
1. Type of Well  ☑ Gas Well ☐ Oth	har		8. Well Name and No. GOLDEN SPUR 25 FBS 3H		
Name of Operator     CONOCOPHILLIPS COMPAN	Contact: KF	RISTINA MICKENS	9. API Well No. 30-015-41230-00-X1		
3a. Address 3300 N "A" ST BLDG 6	31	b. Phone No. (include area code Ph: 832-486-2022	e) 10.	10. Field and Pool, or Exploratory RED HILLS	
MIDLAND, TX 79710-1810					
4. Location of Well (Footage, Sec., T				11. County or Parish, and State	
Sec 25 T26S R31E SWSW 46	55FSL 530FWL		}	EDDY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPO	RT, OR OTHER DATA	
TYPE OF SUBMISSION		ТҮРЕ О	TYPE OF ACTION		
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (S	Start/Resume)	
_	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	□ Well Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily	Abandon	
· ·	☐ Convert to Injection	□ Plug Back	■ Water Dispos	sal	
Currently, we are able to injec	t 2 bpm down the 5-1/2" casi	on the Golden Spur 25 FB ing and receive ~1.5 bpm	returns up the	Accepted to tecolo	
Currently, we are able to inject 9-5/8" x 5-1/2" annulus. The coreturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilliand we will trip in hole with a pis found, we plan to remediate with the 5-1/2" casing, laying core	t 2 bpm down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a ps plans to move in a Well Spacker so that we can determent the casing by backing off be	ing and receive ~1.5 bpm "casing is 3,965' and there above 3,965'. Also the 9-5 Service Unit to the Golden nine where the leak is. Or elow the failed joint. We were the leak is.	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ice the leak rill trip out	NMOCD 765 2013	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying c	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225: For CONOCOPHIL	ring and receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden nine where the leak is. Or elow the failed joint. We will then run in the hole case of the second part of the secon	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"	RECEIVED  NOV 0 5 2013  Tem   NMOCD ARTESIA	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying c	t 2 bpm down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a ps plans to move in a Well Spacker so that we can determent the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225	ing and receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden nine where the leak is. Or elow the failed joint. We were will then run in the hole case of the by christopher walls by Christopher Walls	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"	NOV 0 5 2013  RECEIVED  NOV 0 5 2013  Rem MMOCD ARTESIA  CRW0153SE)	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying complete the complete that the foregoing is Commit Name(Printed/Typed) KRISTINA	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225: For CONOCOPHIL ted to AFMSS for processing	ing and receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden nine where the leak is. Or elow the failed joint. We were will then run in the hole captured by the BLM welles COMPANY, sent to the CHRISTOPHER WALLS	returns up the ewere full /8" shoe is  SEE ATT/ CONDITION Spur 25 FBS 3H ince the leak with 5-1/2"  Il Information System Carlsbad on 11/01/2013 (140) ATORY SPECIAL	NOV 0 5 2013  RECEIVED  NOV 0 5 2013  Rem NMOCD ARTESIA  CRW0153SE)  LIST	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying c	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL true to AFMSS for processing MICKENS	receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden in where the leak is. Or elow the failed joint. We will then run in the hole cases are to the company, sent to the by CHRISTOPHER WALLS.  Title REGUL  Date 10/31/2	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"  Il Information Syste Carlsbad on 11/01/2013 (140) ATORY SPECIA	NOV 0 5 2013  REMINISTRATES A CRW0153SE)	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying complete the second se	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL true to AFMSS for processing MICKENS	ing and receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden nine where the leak is. Or elow the failed joint. We were will then run in the hole captured by the BLM welles COMPANY, sent to the CHRISTOPHER WALLS	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"  Il Information Syste Carlsbad on 11/01/2013 (140) ATORY SPECIA	NOV 0 5 2013  RECEIVED  NOV 0 5 2013  Rem NMOCD ARTESIA  CRW0153SE)  LIST	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying commit the foregoing is  Commit Name(Printed/Typed) KRISTINA  Signature (Electronic S	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL true to AFMSS for processing MICKENS	receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden in where the leak is. Or elow the failed joint. We will then run in the hole cases are to the company, sent to the by CHRISTOPHER WALLS.  Title REGUL  Date 10/31/2	returns up the ewere full /8" shoe is SEE ATT/ CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"  Il Information Syste Carlsbad on 11/01/2013 (140) ATORY SPECIA	NOV 0 5 2013  RECEIVED  NOV 0 5 2013  Rem NMOCD ARTESIA  CRW0153SE)  LIST	
9-5/8" x 5-1/2" annulus. The or returns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilliand we will trip in hole with a pis found, we plan to remediate with the 5-1/2" casing, laying of the committed of the commit	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL ted to AFMSS for processing MICKENS  THIS SPACE FOR  d. Approval of this notice does not intable title to those rights in the subct operations thereon.	reasing and receive ~1.5 bpm reasing is 3,965' and there above 3,965'. Also the 9-5 received Unit to the Golden in the where the leak is. Or elow the failed joint. We will then run in the hole received by the BLM Wester of the property of	returns up the ewere full /8" shoe is  SEE ATT / CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"  III Information System Carlsbad on 11/01/2013 (140 ATORY SPECIA)  OFFICE USE	RECEIVED  NOV 0 5 2013  Rem MMOCD ARTESIA  CRW0153SE) LIST  APPROVED  NOV 1 2013  /S/ Chris Walls  UREAU OF LAND MANAGEMENT	
9-5/8" x 5-1/2" annulus. The creturns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilli and we will trip in hole with a p is found, we plan to remediate with the 5-1/2" casing, laying complete the second se	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the solution of the solution of the solution of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL ted to AFMSS for processing MICKENS  MICKENS  THIS SPACE FOR  d. Approval of this notice does not intable title to those rights in the subct operations thereon.  U.S.C. Section 1212, make it a crin	ing and receive ~1.5 bpm casing is 3,965' and there above 3,965'. Also the 9-5 dervice Unit to the Golden inner where the leak is. Or elow the failed joint. We will then run in the hole case to be companied by the BLM Wester of the companied by the BLM Wester o	returns up the ewere full /8" shoe is  SEE ATT / CONDITI Spur 25 FBS 3H ace the leak with 5-1/2"  Ill Information System Carlsbad on 11/01/2013 (140 ATORY SPECIA)  OFFICE USE  Buillfully to make to	RECEIVED  NOV 0 5 2013  Rem MMOCD ARTESIA  CRW0153SE) LIST  APPROVED  NOV 1 2013  /s/ Chris Walls  UREAU OF LAND MANAGEMENT	
9-5/8" x 5-1/2" annulus. The or returns during the cement job at 6,635'.  Monday, 11/4/13 ConocoPhilliand we will trip in hole with a pis found, we plan to remediate with the 5-1/2" casing, laying of the foregoing is commit to the foregoing is committed by the for	t 2 bpm-down the 5-1/2" casicalculated TOC on the 5-1/2" so we believe the failure is a specific part of the solution of the solution of the solution of the casing by backing off bedown any damaged joints. We true and correct.  Electronic Submission #225. For CONOCOPHIL ted to AFMSS for processing MICKENS  MICKENS  THIS SPACE FOR  d. Approval of this notice does not intable title to those rights in the subct operations thereon.  U.S.C. Section 1212, make it a crin	reasing and receive ~1.5 bpm reasing is 3,965' and there above 3,965'. Also the 9-5 received Unit to the Golden in the where the leak is. Or elow the failed joint. We will then run in the hole received by the BLM We will then run in the hole received by CHRISTOPHER WALLS Title REGUL  Date 10/31/2  FEDERAL OR STATE  Title  Title  Title  Title  Office  The for any person knowingly and any matter within its jurisdiction.	returns up the ewere full /8" shoe is  SEE ATT / CONDITI Spur 25 FBS 3H lice the leak rill trip out with 5-1/2"  Ill Information System Carlsbad on 11/01/2013 (140 ATORY SPECIA)  OFFICE USE  Willfully to make to	NOV 0 5 2013  REM MOCD ARTESIA  CRW0153SE) LIST  APPROVED  NOV 1 2013  /s/ Chris Walls  UREAU OF LAND MANAGEMENT  any JAPAINICAL SELECTION OF LAND MANAGEMENT  AND JAPAINICAL SELECTION OF LAND MANAGEMEN	

## Additional data for EC transaction #225203 that would not fit on the form

## 32. Additional remarks, continued

casing to the top of the 5-1/2" casing in the well and screw the casing back together. Of course the remediation plan may change depending on where exactly the failure occurred.

If everything goes as planned we should have the leak identified by Wed 1.1/6/13.

Conditions of Approval Golden Spur 25 FBS 3H 3001541230

- 1. Approved to run the same casing as previously installed.
- 2. If casing cannot be replaced and an alternate remedial method is required, the operator must receive approval from the BLM for the change in plans.

CRW 110113