Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NMOCD ARTESIA

NOV 13 2013 OCD Artesia

RECEIVED

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM0275360 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. DRAG B COM 2		
2. Name of Operator Contact: CINDY H MURILLO					9. API Well No.		
CHEVRON USA INCORPORA			30-015-20782-00-S1				
15 SMITH ROAD P			Phone No. (include area code) 575-263-0431 575-391-6679		10. Field and Pool, or Exploratory CARLSBAD		
4. Location of Well (Footage, Sec., T		11. County or Parish, and State					
Sec 19 T23S R27E NEŅW 66		EDDY COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF 1	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	□ Dee	pen	☐ Production (Start/Resume)		☐ Water Shut-Off	
_	☐ Alter Casing	☐ Frac	cture Treat	□ Reclamation		■ Well Integrity	
Subsequent Report	☐ Casing Repair	_	v Construction	□ Recomplete		☐ Other	
☐ Final Abandonment Notice	☐ Change Plans		g and Abandon	☐ Temporarily Abandon			
	Convert to Injection		g Back				
13. Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involvectesting has been completed. Final Aldetermined that the site is ready for form the complete of the complete of the 10/04/13 MIRU & All P&A Equ SDFD. 10/7/13 Rig up slickline, RIH clean location, secure well SD 10/9/13 Stand by for coil tbg. 10/10/13 Rig up coil tbg, RIH until 9200', well went on vaccing RIH w/gauge ring, collar location utside, clean location, secure 10/11/13 RUWL, RIH cut tbg in Derrick, lay down remainder,	ally or recomplete horizontally, it will be performed or provide to operations. If the operation respondence in the operation is particular, and the file inal inspection.) The above well with Procedural proceduration in the inal inspection. The above well with Procedural proceduration in the inspection. The above well with Proceduration in the inspection in the inspection in the inspection. The above well with Proceduration in the inspection in the inspe	give subsurface the Bond No. o cults in a multiple donly after all re: ady to NDWI cker set @ 1 11800', 10' t, rig down co 0'. POOH w/NUBOP, Woldstein 1450 POOH,	locations and measin file with BLM/BI/le completion or recrequirements, included. H. Clean location 1700', rig down below packer, will togunit and rewireline. Wireline rk tubing free, PRIH w/dump ba	ared and true vol. Required su completion in a ding reclamation and secure slickline, e had circulatease. RUW e failure, set to COH w/tbg, ilor and dum	ertical depths of all pertir bsequent reports shall be new interval, a Form 316 in, have been completed, well. DUE recepted as to plage attornity under bond in the restoration is rack 10625' in ap 35' cement	inent markers and zones. filed within 30 days for 4 shall be filed once and the operator has AMATION ging of the well bore, 19 rebained waift	
	mmitted to AFMSS for proc	ISA INCORPO	RATED, sent to NE CARRASCO	the Carlsbad on 10/28/2013	1 3 (13JA0687S) A	Copied for record	
Name (Printed/Typed) CINDY H	MURILLO		Title PERMI	TTING SPE	CIALIST	NMOCD	
Signature (Electronic S	Submission)		Date 10/21/2	2013			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
_Approved By ACCEPTED			JAMES A AMOS TitleSUPERVISOR EPS			Date 11/08/2013	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carlsba	d			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #223806 that would not fit on the form

32. Additional remarks, continued

on top of CIBP RDWL. RIH w/packer & 3000 of kill string. Clean location, Secure well. 10/14/13 RIH w/tbg & packer to 10613', Rig up test CIBP,, 500 PSI OK, Rig up pump and circulate MLF to surface, Rig up pump and spot 35 sx cement f/10613 to 10269, POOH w/tbg to 9219' set packer. Rig Up rotary wireline, RIH perf @9700, RDWL. Rig Up Pump and pressure up to 1500 psi, could not pump into , RIH w/tbg to 9765', Rig up pump circulate MLD to surface and spot 30 sx cement f/9765 to 9465, POOH w/ packer & set @ 9259", RWL, Rotary, we made 6 misfire runs, set different truck up for in the am. Clean location, Secure well.SDFD.

10/15/13 RUWL, Rotary, RIH Perf @9700', POOH, RDWL. RIg up pump & pressure up to 1500 psi, Could not pump in to perfs, notify BLM, Ken Said drop 50' below and spot 35 sx cement f/ 9750' to 9430', POOH w/tbg to 8500' set packer WOC, WOC,RIH w/WL, Tag TOC 9314m Perf @9913 RDWL, Rig Up pump and pressure up to 1800 psi, notify BLM, Got OK to drop 50' below Perf and spot 35 sx cement, RIH to 8972', RIg up pump and spot 35 sx cement F/8972 to 8650' POOH w/tbg to 5081',Set packer, WOC, Tag TOC first thing in the morning. Clean location, Secure well, SDFD.

10/16/13 RUWL, RIH Tag TOC 8640', Find hole in csg @6100 +or-, Notify BLM & Got OK to Sqz 100 sx, WOC and tag, Set packer @ 5500', test csg above packer, test good, est inj rate, sqz 100 sx cement and displace to 5800' WOC.RUWL, RIH tag TOC @5214, POOH set packer @1500', RUWL, RIH Perf @2133' RDWL, Rig up pump and sqz 120 sx f/2133' to 1700'm got approval from BLM to combine plugs, clean location, secure well, SDFD, WOC overnight, we will tag and complete in the AM.

10/17/13 RIG tag TOC @1648', POOH laying down tbg, RUWL, RIH perf @545 RDWLm Rig up Pump, break circulation, circulate 300 sx cement to surface job complete, NDBOP, Top well off with cement, Rig down Rig and all P&A equipment, get everything ready to move. Clean location, secure well. SDFD.