Office District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 DIL CONSERVATION DIVISION 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 South St. Francis Dr. 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Sundar Fe, NM Sundar Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztee, NM 87410 Santa Fe, NM 87505 District IV - (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Sundar Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	30-015-21896
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV - (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	5. Indicate Type of Lease
1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	STATE FEE
SUNDRY NOTICES AND REPORTS ON WELLS	6. State Oil & Gas Lease No.
	7. Lease Name or Unit Agreement Name
	Jackson GM
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other	1
2. Name of Operator	9. OGRID Number
Yates Petroleum Corporation	025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	Eagle Creek; Atoka-Morrow, East
4. Well Location	
	650 feet from the West line
Section 24 Township 17S Range 25E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3,468' GR	
12. Check Appropriate Box to Indicate Nature of Notice, F	Report or Other Data
NOTICE OF INTENTION TO: SUBS	EQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS	
PULL OR ALTER CASING I MULTIPLE COMPL CASING/CEMENT	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com	
proposed completion or recompletion.	
Yates Petroleum Corporation plans to Plug and Abandon this well as follows:	
. MIRU WSU and all necessary safety equipment. POOH with production equipment. 2. Set a 4-1/2" CIBP at 8,070'. Cap it with 25 sx class "H" cement from 7,732' to 8,070'. Free p	point and cut the casing at $\pm/7300$, POOH
Set a plug from 50' below the casing stub up to 6,921', this will place a plug across the casing stu	
olug if necessary.	e and the californ top. We're and tag, reset the
5. Spot a 50 sx class "C" plug from 5,265' to 5,425'. This will put a plug across the WC top. W	OC and tag, reset the plug if necessary.
Spate $AO_{\text{max}} = \frac{1}{2} \log \frac{4C^{2}}{12} \log \frac{4C^{2}}{12} + \frac{1}{2} \log \frac{4C^{2}}{12} + \frac{1}{2$	OC and tag, reset the plug if necessary.
4. Spot a 40 sx class "C" plug from 4,060' to 4,210'. This will put a plug across the Abo top. W	
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary.	
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate	casing shoe. WOC and tag, reset the plug if
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary.	
 5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh 	
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary.	oe and form the surface plug. WOC and tag,
 5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. 6. Remove all surface equipment and weld dry hole marker per regulations. 	
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. CODITIONS OF APPROVAL ATTACHED 	oe and form the surface plug. WOC and tag,
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing she eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Chematics attached ONDITIONS OF APPROVAL ATTACHED 	Def 0 2 2013
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Chematics attached ONDITIONS OF APPROVAL ATTACHED 	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Remove all surface equipment and weld dry hole marker per regulations. CONDITIONS OF APPROVAL ATTACHED Rig Release Date of the providing work is completed by a set of the providing of the provided of the provided	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing she eset the plug if necessary. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Rig Release 5 Cubese users Report of Well which may be found at OCD Web Pa 8. Forms. www.cmnrd.state.nm.us/ocd.	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 ding receipt 1 Plugging) ge under MMOCD ARTESIA
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Remove all surface equipment and weld dry hole marker per regulations. CONDITIONS OF APPROVAL ATTACHED Rig Release Date of the providing work is completed by a set of the providing of the provided of the provided	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 ding receipt 1 Plugging) ge under MMOCD ARTESIA
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing she eset the plug if necessary. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Rig Release 5 Cubese users Report of Well which may be found at OCD Web Pa 8. Forms. www.cmnrd.state.nm.us/ocd.	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 ding receipt 1 Plugging) ge under MMOCD ARTESIA
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment equipment and weld dry hole marker per regulations. 9. Rig ReleaseDate for the second at OCD Web Pa 8. Sport of Well bore of the second at OCD Web Pa 8. Sport of Well bore of the best of my knowledge 1. Sport of the best of my knowledge	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 ding receipt 1 Plugging) ge under MMOCD ARTESIA
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment and weld dry hole marker per regulations. 8. Remove all surface equipment equipment and weld dry hole marker per regulations. 9. Rig ReleaseDate for the second at OCD Web Pa 8. Sport of Well bore of the second at OCD Web Pa 8. Sport of Well bore of the best of my knowledge 1. Sport of the best of my knowledge	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 IPlugging) ge under and benef. Chnician DATE November 27, 2013
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate eccessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Conditional state and work is completed by https://www.cmnrd.state.nm.us/ocd. Fignature Additional State and Conditional State and Conditiona	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 IPlugging) ge under and benef. Chnician DATE November 27, 2013
5. Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. 5. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate necessary. 7. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing she eset the plug if necessary. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulations. 7. Remove all surface equipment and weld dry hole marker per regulatory Reporting Text 7. Regulatory Reporting Text 7. TITLE Regulatory Reporting Text 7. Remove all address: laura@yatespetroleum 7. Remove all surface equipment and watts Secondary Secondar	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 DEC 0 2 2013 IPlugging) ge under and benef. Chnician DATE November 27, 2013 Com PHONE: <u>575-748-4272</u>
 Spot a 40 sx class "C" plug from 2,450' to 2,600'. WOC and tag, reset the plug if necessary. Spot a 40 sx class "C" plug from 1,145' to 1,295'. This will put a plug across the intermediate eccessary. Spot a 100 sx class "C" plug from 0' to 368'. This will put a plug across the surface casing sh eset the plug if necessary. Remove all surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulations. Conditional surface equipment and weld dry hole marker per regulati	oe and form the surface plug. WOC and tag, RECEIVED DEC 0 2 2013 IPlugging) ge under and benef. Chnician DATE November 27, 2013



