Submit 1 Copy To Appropriate District	State of New Me	xico		Form	n C-103
Office <u>i</u> <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		·····	Revised July	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.		Ţ	
<u>District 11</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		<u>30-015-33606</u>		
District III - (505) 334-6178			5. Indicate Type of Lease STATE STATE FEE		
1000 Rio Bražos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM					
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	- <i>,,</i> ,	7. Lease Name or U	nit Agreement	Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			SOUTH CULE		
	CATION FOR PERMIT" (FORM C-101) FO	RSUCH			
ROPOSALS.) . Type of Well: Oil Well 🛛 Gas Well 🗌 Other			8. Well Number 10		
. Name of Operator			9. OGRID Number		
VANGUARD PERMIAN LLC			258350		
3. Address of Operator			10. Pool name or Wildcat LOVING BRUSHY CANYON, EAST		
1209 SOUTH MAIN ST, LOVING	J10N, NM 88260	•	LOVING BRUSHY	CANYON, EA	451
4. Well Location					
	30feet from theSOUTH				line
Section 23	Township 23S	Range 28E	NMPM	EDDY	County
	11. Elevation (Show whether DR,	ккв, к <i>і</i> , <i>G</i> К, etc.			
12 Check	Appropriate Box to Indicate Na	ature of Notice	Report or Other D	ata	
	Appropriate Box to indicate Na	ature of Notice,	Report of Other Da	ala	
NOTICE OF IN	NTENTION TO:	SUB	SEQUENT REPO	DRT OF:	
PERFORM REMEDIAL WORK 🛛		REMEDIAL WOR		TERING CAS	ING 🔲
	•			AND A	
PÜLL OR ALTER CASING		CASING/CEMEN	т ЈОВ	•	
	na an an Albana an Albana an Albana an Albana Anna an Albana an Albana an Albana an Albana	an a subara.			
CLOSED-L'OOP SYSTEM			t i to t en ant was eastern	· · · ·	· · · · · · · · · · · · · · · · · · ·
OTHER:	pleted operations. (Clearly state all p	OTHER:	d give pertinent dates	including estir	nated date
	ork). SEE RULE 19.15.7.14 NMAC				
proposed completion or re		,			
	-		· · · ·		
			TREAL	IVED	
		· · · ·	HELE		
			EER 2	4 2014	
	SEE ATTAC	HMENT	TED A	AFOIA	
			DOMNA	ARTESIA	2
			10101 cm		
				1	
Spud Date: ²	Rig Release Da	ite:			
16.77 - 28 - 19 19				La jora d	
978212 			محمد با با الله ما المحمد الم	an an Antonia Indone I (1)	
I hereby certify that the information	above is true and complete to the be	est of my knowledg	ge and belief.		
Marine Marine Idea	A		· · · · · ·	0.01.11	
SIGNATURE UN HCW	TITLEAGEN	· ·	DATE	2-21-14	
Type or print name GAYE H	EARD E-mail address:gheard@			-2727	i i
For State Use Only		omeportsme.com_			
	there I	"Geolo	naist"	n 111	71/11
APPROVED BY:	1/10/1020 TITLE	JEVI	DATE	L-24-	2014
Conditions of Approval (if any):	· /				/
				. * :	
	-			te a c	•
		1 A.		·	

VANGUARD PERMIAN LLC

SOUTH CULEBRA BLUFF 23 #10

API# 30-015-33606 Sec 23 T23S R28E

Here is the procedure: MIRU completion rig and test anchors. 1. Kill well with 2% KCL water, if necessary. Unseat pump and POOH w/ rods and 2. pump. ND WH and NU BOP. Release TAC and POOH w/ tubing. 3. MU 3-1/8" casing guns set at 4 spf, 120° phasing (0.38" hole, 39.5" 4. penetration). 5. Perforate as follows: 5963' - 5972' (9', 36 shots) а. 5996' - 6028' (32', 128 shots) b. 6082' - 6094' (6', 48 shots) c. 6166' - 6170' (4', 16 shots), total 228 shots d. RD wireline. 6. PU a 5-1/2" Arrowset I packer and RIH to ~5950'. Load tubing/hole with 2 % KCl 7. and set packer. Test csg/packer down backside to 3500 psi. MIRU pump truck and test lines to 3500 psi. 8. Pump 4000 gals 15% NEFE acid with rock salt. . 9. Pump 500 gal then pump 4000 lbs rock salt over next 3000 gals. a. Pump last 500 gals and flush to 6164'. b. Record ISIP, 5 min, 10 min and 30 min. c. RU swabber and swab well in to test acid job. Recover load and report fluid/gas 10. entry. Load hole and release packer, POOH and lay out 2-7/8" tubing. 11. MI wireline w/ packoff. RIH CBP, GR/CCL & correlate to the Halliburton Spectral 12. Density/Neutron/GR log dated 5/27/2005 Set CBP at ~5920' and test CBP to 1500 psi, dump sand on top. 13. MU 3-1/8" casing guns set at 2 spf, 120° phasing (0.38" hole, 39.5" penetration). 14. Perforate as follows: 15. 5790' - 5794' (4', 8 shots) a. 5832' - 5835' (3', 2 shots) b. 5880' - 5886' (6', 12 shots) c. 16. RD wireline. PU a 5-1/2" Arrowset packer and 3-1/2" tubing and RIH with tubing to ~5760' and 17. set packer. Test tubing going in the hole to 5000 psi. (3-1/2" L-80 is rated to 8,640 psi Burst) 18. MIRU pump truck (with 2000 gals acid) and test lines to 4500 psi. Pump 1000 gals 15% NEFE acid with 20 ball sealers. a. Pump last 1000 gals and flush to 5886'. b. Record ISIP, 5 min, 10 min and 30 min. с.

1

VANGUARD PERMIAN LLC

SOUTH CULEBRA BLUFF 23 #10

API# 30-015-33606 Sec 23 T23S R28E

19. Wait at least 1 hr then RU swabber and swab well in to test acid job. Recover load and report fluid/gas entry, if possible.

20. RDMO completion rig.

21. RU frac Co. and test lines & pump as per frac schedule.

22. Monitor ISIP, 5 min, 10 min, 15 min. Flowback until well dies.

23. MIRU completion rig.


24. PU a 4-3/4" bit, sand bailer and 2-7/8" tubing and RIH. Clean out the well as needed and knockout the CBP to comingle all zones, POOH.

25. RIH w/ 5-1/2" TAC, SN and 2-7/8" tubing.


26. RIH w/ rods and pump.

27. RD & MO.


28. Turn well on to production.



Note: This schematic is not to scale. For display purposes only.



.



. 34