BU	UNITED STATES PARTMENT OF THE IN IREAU OF LAND MANAG	NTERIOR GEMENT		ATION DIVISI STREET M 59210 NM-5880	FORM APPROVED OM B No. 1004-0137 xpires: March 31, 2007 No.	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
<b>SUBMIT IN TRIPLICATE</b> - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NM-111019		
1. Type of Well Oil Well C Gas Well O Other				8. Well Name and No.		
2. Name of Operator Armstrong Energy Corporation				Cobra Federal Com #1 9. API Well No.		
			nclude area code)30-005-63642210. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						
990' FNL & 1650' FEL, Sec 19, T11S, R27E				11. County or Parish, State Chaves County, NM		
12. CHECK AP	PROPRIATE BOX(ES) TO 1	NDICATE NATI	JRE OF NOTICE,	REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION						
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize	Deepen Fracture Treat New Constructio Plug and Abando Plug Back		Abandon	Water Shut-Off Well Integrity Other	
Attach the Bond under which the work will be performed or provide the Bo following completion of the involved operations. If the operation results in testing has been completed. Final Abandonment Notices shall be filed only determined that the site is ready for final inspection.) Notify BLM 24 hrs prior to start of operations. 1. Move in, RU, ND WH, NU BOP, POH with production tbg.			coopled for M LED NMOOD 3	ACC cord Juleon		DIC
<ol> <li>RU Wireline, run gaug</li> <li>TIH w/ tbg @ 5350', ci</li> <li>ND BOP and WH. RU</li> <li>Spot 50 sx, POH, WOG</li> <li>Spot 50 sx @ 2328', PO</li> <li>POH @ 400', spot 25 s release rig, RD and model</li> </ol>	ering to 5350', pull GR, set C rc hole w/ 9.5 ppg mud. Spot D spear, cut csg @ 3600'. POH C 4 hrs, tag @ 3550', POH. 44 DH, WOC, tag @ 2228'. POH X. POH @.604', spot 20 sx to S bye out. 4400 / caliche, rip road and location	IBP @ 5350'. 27 25 sx, pull to 4604 and LD csg. RIH (TTNES) @ 1096', spot 50 s Surface. Cut off we , reseed.	', spot 25 sx. POH, W w/ tbg @ 3650'. x. POH, WOC, tag @	996'. WTN Iors 3' below G	L. Install dry hole marke	nager,
14. I hereby certify that the fore Name (Printed/Typed)	egoing is true and correct	NWO	CD AF	• 	FF	B 2. 6 2
Bruce Stubbs		Titl	e Vice President - O	perations	1	
Signature B	Astilly	Da	2/29/17		SIVIN	
·	THIS SPACE FOR	FEDERAL O	R STATE OFFI	CE USE		
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant	al or equitable title to those rights to conduct operations thereon.	does not warrant or in the subject lease	Office		Date SUUIY	
Title 18 U.S.C. Section 1001 and Ti States any false, fictitious or fraud (Instructions on page 2)	le 43 U.S.C. Section 1212, make it ilent statements or representations	a crime for any pers s as to any matter wit	on knowingly and will hin its jurisdiction.	ully to make to	any department or agency of	the United

Armstrong Energy Corporation P.O. Box 1973 Roswell, NM 88202-1973

## Well: Cobra Federal # 1

## **P&A Procedures**

- 1. MI RU, ND W.H. NU BOP, POOH with production Tbg.
- 2. Rig up W.L. run G.R. to 5350', pull same run & set CIBP @ 5350'.
- 3. TIH w/ Tbg 5350', circulate hole w/ 9.5 MLF. Spot 25sx pull to 4604', spot 25sx PUH WOC 4 hrs. & Tag 4504'.
- ND BOP & W.H. Rig up spear, cut Csg @ 3600' POOH L.D. same, RIH w/ Tbg 3650'.
- 5. Spot 50sx PUH WOC 4 hrs. & Tag 3550' PUH.
- Spot 50sx 2328' PUH WOC & Tag 2228'. PUH 1096', spot 50sx PUH WOC & Tag 996'.
- 7. PUH 400' spot 25sx PUH.60' 20sx to surface. Cut off W.H. & mast anchors 3' /co/ below G.L. Install dry hole maker, R.R. RDMO.

يام الأن ما مسلحة عشلية، الاعتمام من عومك معمار بما يتصميك الذي يعظما الحميد مداريك بمرد محرف

- 8. Clean location, remove caliche, rip road and location, reseed.
- 9. Notify OCD for final inspection.

