Form 3160-5 (August 2007)	DEI	UNITED STATES PARTMENT OF THE INTE IREAU OF LAND MANAGEN	ERIORNM OIL CONS	HERIBO	FORM OMB N Expires:	APPROVED O. 1004-0135 July 31, 2010	
ê					5. Lease Serial No. NMNM0107697		
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter and abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Alłottee or Tribe Name		
L <u>es</u>	SUBMIT IN TRIF	PLICATE - Other instruction	ns on reverse side.CE	IVED	7. If Unit or CA/Agre	ement, Name and/or No.	
1. Type of Well	Gas Well 🔲 Othe				8. Well Name and No. REGULUS 26 FED 5H		
2. Name of Operator			9. API Well No. 30-015-42489				
	RGY PRODUCTI CITY, OK 73102	ION CO.L.P 333 WEST \$HB	Phone No. (include area cod RIDOD 228078DBHOMA	e) CITY, OK 731	10. Field and Pool, or 0235001101AMS SIN	Exploratory K	
		, R., M., or Survey Description)	· · · · · · · · · · · · · · · · · · ·		11. County or Parish, and State		
Sec 26 T19S	R31E 480FNL 66	67 FEL			EDDY COUNT	Y COUNTY, NM	
12.	CHECK APPR	OPRIATE BOX(ES) TO IN	IDICATE NATURE OF	NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SU	BMISSION	1	TYPE C	F ACTION	,		
Notice of Int	ent	 Acidize Alter Casing 	 Deepen Fracture Treat 			☐ Water Shut-Off ☐ Well Integrity	
🖸 Subsequent I	Report	Casing Repair	New Construction	🗖 Recompl	ete	Other	
🗖 Final Abando	onment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Tempora	rily Abandon isposal	Change to Original PD	
Attach the Bond following completesting has been of determined that the Devon Energy on the Stuck States	under which the wor ation of the involved completed. Final Ab he site is ready for fi Production Con 2-5/8" int Csg: Re	npany, L.P. respectfully subr egulus 26 Fed 5H (API: 30-0	Bond No. on file with BLM/BI in a multiple completion or re- nly after all requirements, inclu- nits a sundry for informat 15-42489).	A. Required sub completion in a no iding reclamation	sequent reports shall be ew interval, a Form 316 , have been completed, ort	filed within 30 days 60-4 shall be filed once	
		mmary attached. The CBL w	as submitted to the BLM	• •	non FUD 8/12 Cordiaci kar Ka NMOCO	/15 cord	
14. I hereby certify	that the foregoing is	Electronic Submission #287		t to the Carleby	nd -		
Name(Printed/T)	ped) TRINA C (LATORY ANA			
Signature	(Electronic S	ubmission)	Date 01/07/	2015	, 世長 2 4	2015	
<u></u>		THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	ELA	am	
			Title		BUREAU OF LAND CARLSBAD FI	MANAGEMENT ELD OFFICE Date	
Approved By							

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

OPERATIONS SUMMARY Regulus 26 Federal 5H (API: 30-015-42489)

<u>OBJECTIVE:</u> Run, Cement, and Test 9-5/8" casing to 800 psi and perform a Formation Integrity Test on the shoe to continue drilling the well to proposed total depth.

WELL DATA:

Tubular Data							
	Hole Size	Casing Size	Depth	Weight	Grade	Thread	тос
Hole Section			(MD)	Ib/ft			
Surface	26	20	837	94	J-55	BTC	0
Intermediate 1	17-1/2	13-3/8	2,529	68	J-55	BTC	0
Intermediate 2	12-1/4	9-5/8	4,448	40	J-55	BTC	0

Depth, (ft)	Size (in)	Nôm ID (in)		Burst (psi)	(psi)	Tension (x:1000 lbs)
0 - 837	20	19.124	18.936	2,110	520	1402
0 – 2,529	13-3/8	12.415	12.259	3,450	1950	1140
0 - 4,448	9-5/8	8.835	8.679	3,950	2,570	630

HISTORY:

Drill out of 13-3/8" casing to 2,557' (28' below shoe) and lost full returns. Drilled to section TD without returns. Performed wiper trip to previous shoe without returns but no other hole problems. Granted approval from BLM to run DVT/ECP closer than the regulation 50 feet from previous casing shoe. Ran 9-5/8 Intermediate Casing without issue to 4448' (TD @ 4450'). Pump capacity and a half around 9-5/8" casing with continued no returns while RU floor. Pressure increased while pumping spacer and attempt to pull up with no success. Worked casing for 7.5 hrs with no movement and no ability to pump. Run free-point indicator and determined casing stuck from 4,448' to 4,000'. Granted BLM approval to perforate casing from 4,000' to 4,002': 23 gram charge, 6 spf, 60 deg phasing, 12 total holes. Establish injection rate across perforations at 6.5 bpm with 90 psi. Pump 50 bbls of SealBond followed by Stage 1 Lead: 515 sks, (152 bbls) at 1.66 yield at 12.8 ppg. Pump 550 sks Tail (135 bbls) at 1.38 yield at 13.8 ppg. Displaced with 298 bbls water, leaving 5 bbls cement in casing, shut well in for 12 hours.

Set ECP packer and open DVT with top at 2540' (previous casing at 2529'). Established circulation to surface with a good packer setting and Pump Stage 2 with Lead: 480 sks (144 bbls), 1.66 yield at 12.8 ppg. Pump Tail: 185 sks (46 bbls), 1.38 yield at 13.8 ppg. Circulate 36 bbls of cement returns to the surface.

Created by Neevia Document Converter trial version http://www.neevia.com

OPERATION SUMMARY:

<u>Report Date – 12/15/2014</u>

<u>Operations:</u> ATTEMPT TO WORK CASING FREE. R/U WIRLINE RIH & PERFORATE FROM 4000' TO 4002'. POOH W/ WIRELINE & R/D. R/U CEMENT HEAD & CIRCULATE @ 6 BPM W/ 90 PSI. PREFORM 1st STAGE OF CEMENT WITH NO RETURNS.

Report Date - 12/16/2014

<u>Operations:</u> DROP BOMB & OPEN PACKER ON DV TOOL. CIRCULATE FLUID CALIPER ABOVE PACKER. PREFORM 2ND STAGE CEMENT JOB WITH FULL RETURNS. CIRCULATED 36 BBLS CEMENT TO SURFACE. N/D BOPS, CUT CSG, & INSTALL WELL HEAD. N/U BOP'S & TEST.

<u>Report Date – 12/17/2014</u>

<u>Operations:</u> CONTINUE TEST BOP'S. TEST CASING TO 500PSI. L/D 8" DC'S. M/U & TIH W/ SLICK BHA WITH JUNK BASKET. DRILL DV TOOL. TIH TAG @ 3515' WASH & REAM CEMENT TO 4010'. STARTING LOSSING @ 500 BPH. POOH. WAIT ON CEMENT RETAINER.

Report Date - 12/18/2014

<u>Operations:</u> MONITOR WELL WHILE WAITING ON RETAINER & WIRELINE. RIH WITH GAUGE RUN ON WIRELINE. SET CEMENT RETAINER W/ WIRELINE @ 3907'. TIH W/ CEMENT STINGER ON DP. STING IN RETAINER & TEST ABOVE W/ 500 PSI.

Report Date - 12/19/2014

<u>Operations:</u> WOC TO ARRIVE FROM BULK PLANT. STING INTO RETAINER GET INJECTION RATES. PREFORM SQUEEZE JOB AS PER DEVON PROCEDURE. PULL OUT RETAINER & REVERSE OUT. M/U SLICK BHA. TIH TO 3654'. WOC

<u>Report Date – 12/20/2014</u>

<u>Operations:</u> DRILL RETAINER & CEMENT DOWN TO 3952'. TROUBLESHOOT & REMOVE CEMENT FROM FLOWLINE. DRILL CEMENT F/ 3952' TO 4010'. TEST CASING TO 800PSI. DRILL CEMENT, FLOAT, SHOE TRACK, SHOE & 10' OF NEW HOLE F/ 4010' TO 4458'

<u>Report Date – 12/21/2014</u>

<u>Operations:</u> SAFETY STAND DOWN, DRILL CEMENT, FLOAT EQUIPMENT, SHOE TRACK & 10' FORMATION. ATTEMPT FIT WITH NO SUCCESS. DROP GYRO & POOH. SAFETY STAND DOWN. RIH WITH WIRELINE & SET RETAINER @ 4427'. TIH WITH STINGER.

<u>Report Date – 12/22/2014</u>

<u>Operations:</u> SAFETY STAND DOWN REVIEWING RUNNING CASING. ESTABLISH INJECTION RATE. MIX, PUMP, & SQUEEZE CEMENT AS PER DEVON. STING OUT OF RETAINER & REVERSE OUT. POOH. M/U SLICK BHA & TIH TO 4030'. WOC.

Created by Neevia Document Converter trial version http://www.neevia.com

<u>Report Date – 12/23/2014</u>

<u>Operations:</u> SAFETY STAND DOWN. WOC. TIH TAG RETAINER. DRILL RETAINER & CEMENT DOWN TO 4458'. PREFORM FIT TO 9.2 EMW. POOH. M/U DIRECTIONAL BHA. TIH. SLIP N CUT.

Plan Forward: Resume planned drilling program and off NPT Trouble Time. Reach KOP and run CBL across 9-5/8'' intermediate casing. Drill curve and lateral as planned. Run $7'' \ge 5-1/2''$ production combination casing string as planned.

Created by Neevia Document Converter trial version http://www.neevia.com