Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Artesia

FORM APPROVED

	OMB NO. 1004-0135 Expires: July 31, 2010
5.	Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

abandoned we	6. If Ji	6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRI	7. If U	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well	207			8. Well Name and No. , GISSLER A 7			
Name of Operator PREMIER OIL & GAS INCOR	Contact: DANIEL	JONES .		9. API Well No. 30-015-33589-00-S1			
3a. Address		one No. (include area code	ode) 10. Field and Pool, or Exploratory				
ARTESIA, NM 88210	Ph: 9	72.470.0228	LO	CO HILLS GLO	RIETÁ-YESO		
4. Location of Well · (Footage, Sec., 7	., R., M., or Survey Description)		11. Co	11. County or Parish, and State			
Sec 23 T17S R30E NENW 33	0FNL 2310FWL		ED	EDDY COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO INDIC	CATE NATURE OF	NOTICE, REPORT	, OR OTHER E	DATA		
TYPE OF SUBMISSION TYPE OF ACTION							
□ Nation of Intent	🖺 Acidize . 📙] Deepen	☐ Production (Sta	rt/Resume) [☐ Water Shut-Off		
☐ Notice of Intent	☐ Alter Casing · ☐	Fracture Treat	☐ Reclamation		☐ Well Integrity		
Subsequent Report Subsequent Re	☐ Casing Repair ☐	New Construction	Recomplete		Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily At	orarily Abandon			
	Convert to Injection] Plug Back	☐ Water Disposal				
5/19/2015 - RIH w/ wireline an w/ tubing and spot 500 gal of 28 bbls of fresh water. 5/20/2015 - Install 10K flange, 4969 1SPF (20). 5/21/2015 MIRU Elite frac c 3650#. Pumped 3000 gal 15% 171,863# lbs of sand. Screen and 152 jts 2-7/8? and clean of	nd tubing. Run casing scraper to a set 4" composite plug @ 5070' 10% acetic acid across Yeso 3 per frac valve and goat head. RI Wir rew and Lobo transfer crew. Pumb HCL. Frac Yeso 3 (4684 ? 4969 ed out on final stage. Top of Sandout sand to 4903.50. POOH. RIH 4628? 1 SPF (17). Go back in ho	Test casing to 2000 erfs (4684 - 4969) and reline and perforate Your fresh water and bro?) w/ 8,590 bbls slick to @ 4903?. Go in hole with wireline, set plug	d load hole with NM eso 3 4684 - ke down perfs @ water carrying w/ 4-3/4? bit @ 4655? and	OCT 3 0 2 RECEIVI	rrict (Ui)) ED (Liter record y		
				UPO MI	1000 11/3/15		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #307971 v For PREMIER OIL & GAS In hitted to AFMSS for processing by	NCOR∮POŘATED, sent	to the Carlsbad				
Name (Printed/Typed) DANIEL J	- · · · · · · · · · · · · · · · · · · ·	. [RESIDENT	.054002)			
Signature (Electronic S	Date 07/03/2	Date 07/03/2015					
	THIS SPACE FOR FED	ERAL OR STATE	OFFICE USE				
Approved By ACCEPT	ED	DAVID R (R GLASS LEUM ENGINEER		Date 10/23/2015		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	nitable title to those rights in the subject le		d				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime for statements or representations as to any ma			department or age	ncy of the United		

Additional data for EC transaction #307971 that would not fit on the form

32. Additional remarks, continued

5/22/15 ? Stage 2. Pumped 3000 gal 15% HCL Frac Yeso 4 (4431 ? 4628?) w/ 7,185 bbls slickwater carrying 2,202 lbs of 120756# sand. SDON.
5/26/15 ? Clean out to 4834?. POOH to check valve. SDON.
5/27/15 ? Foam up at 3500?. Go in hole to 150 jts. Go to 6151? Try to circulate pressured up. Tubing got stuck. Turn out of hole and stand tubing in derrick.
5/28/15 ? Go in hole with 4? swedge, 2 drill collars, 2-7/8? tubing to 4884. Did not touch anything. POOH. Go back in hole with 4-3/4? to 4884?. Did not touch anything. POOH. Go back in with 2-3/8? seating nipple, 40 jts 2-3/8? tubing w/ turn down collars and change over, tallied 1271.65?, 21 jts 2-7/8? tubing, TAC, 678.09? + 3? anchor = 681?, 126 jts 2-7/8?, tallied 4069.01. ? of 16th would not go in liner. POOH and cut mule tail off jt. Go back in hole and land tubing anchors. Ran 20? Quinn Frac Pump 4 1-1/4? K Bars, 55 ?? rods, 180 7/8? rods, 26? polished rod. Lean down to put unit back together. 16 bbls to load. Hang well on and begin pumping.