

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

*Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"*

30-Mar-16

MEMORIAL PRODUCTION OPERATING, LLC
500 DALLAS SUITE 1800
HOUSTON TX 77002-

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

BURNHAM GRAYBURG SAN ANDRES UNIT No.001C			30-015-04049-00-00
Active Injection - (All Types)			P-2-17S-30E
Test Date:	3/22/2016	Permitted Injection PSI:	Actual PSI:
Test Reason:	5-year Test	Test Result: F	Repair Due: 6/25/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	Informed by operator, well will not pass MIT.		
BURNHAM GRAYBURG SAN ANDRES UNIT No.001D			30-015-04056-00-00
Active Injection - (All Types)			F-2-17S-30E
Test Date:	3/23/2016	Permitted Injection PSI:	Actual PSI:
Test Reason:	Post Workover Test	Test Result: F	Repair Due: 6/26/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Repaired? Failure on 2/11/15, No paperwork on repairs. Reporting injection from April - Nov 2015 despite Shut-in Directive.		

NORTH SQUARE LAKE UNIT No.012**30-015-04856-00-00****Active Injection - (All Types)****P-19-16S-31E**

Test Date:	3/23/2016	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Post Workover Test	Test Result:	F	Repair Due:	6/26/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Repaired? Failure on 2/10/15 5/19/15 - intend to P&A. Well not plugged. No c103 subsequent.				

NORTH SQUARE LAKE UNIT No.005**30-015-10322-00-00****Active Injection - (All Types)****L-20-16S-31E**

Test Date:	3/23/2016	Permitted Injection PSI:		Actual PSI:	
Test Reason:	Post Workover Test	Test Result:	F	Repair Due:	6/26/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Permit Violation	FAIL CAUSE:	
Comments on MIT:	Repaired? Failure on 2/10/15 5/19/15 - intend to P&A Well not plugged. Shut-in. looks like it might have been repaired. No c103 subsequent.				

LOCO HILLS A FEDERAL No.002**30-015-20536-00-00****Active Injection - (All Types)****N-10-17S-30E**

Test Date:	3/22/2016	Permitted Injection PSI:		Actual PSI:	1750
Test Reason:	5-year Test	Test Result:	F	Repair Due:	6/25/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure.				

FEDERAL R No.007**30-015-20695-00-00****Active Injection - (All Types)****B-10-17S-30E**

Test Date:	3/22/2016	Permitted Injection PSI:		Actual PSI:	1900
Test Reason:	5-year Test	Test Result:	F	Repair Due:	6/25/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure. Fluid came from ground around casing.				

FEDERAL R No.008**30-015-20696-00-00****Active Injection - (All Types)****H-10-17S-30E**

Test Date:	3/22/2016	Permitted Injection PSI:		Actual PSI:	750
Test Reason:	5-year Test	Test Result:	F	Repair Due:	6/25/2016
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Other Internal Failure	FAIL CAUSE:	
Comments on MIT:	Well will not hold pressure. 15 bbls then went on vacuum.				

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Richard Ingle

Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.