in 3160-5 une 2015)

NET OIL COMSERVATION ARTESTA DISTRICT

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FEB 1,5 2018

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Nam
SUBMIT IN TRIPLICATE - Other instructions on page 2	7. If Unit or CA/Agreement, Name

SUBMIT IN TRIPLICATE - Other inst	7. If Unit or CA/Agreement, Name and/or No.		
 Type of Well Gas Well Other 	8. Well Name and No. UCBHWW FEDERAL 7		
Name of Operator Contact: RKI EXPLORATION & PROD LLC E-Mail: caitlin.ohair	9. API Well No. 30-015-25313-00-S1		
3a. Address 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172	3b. Phone No. (include area code) Ph: 539-573-3527	Field and Pool or Exploratory Area BRUSHY DRAW-WOLFCAMP DELAWARE	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description, Sec 25 T26S R29E NENW 817FNL 2019FWL 32.017780 N Lat, 103.939260 W Lon		11. County or Parish, State EDDY COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA	

TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other			

RKI EXPLORATION & PRODUCTION, LLC RESPECTFULLY REQUESTS TO P&A THE ABOVE MENTIONED WELL.

THE WBD AND PROCESS ARE ATTACHED.

Pert W/ Deep Penetrating Shots.

RECLAMATION PROCEDURE ATTACHED

SEE ATTACHED FOR **CONDITIONS OF APPROVAL**


14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #401971 verifie For RKI EXPLORATION & PR Committed to AFMSS for processing by J	DD LLC	, sent to the Carlsbad	
Name (Printed/Typed)	CAITLIN O'HAIR	Title	SUBMITTER	
Signature	(Electronic Submission)	Date	01/23/2018	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By	mus Q. Comos	Title	Supr. PET	2-6-18 Date
certify that the applicant hol	ny, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease licant to conduct operations thereon.	Office	Carlshaf	
Title 18 U.S.C. Section 100	1 and Title 43 U.S.C. Section 1212, make it a crime for any pe	erson kno	wingly and willfully to make to any departmen	t or agency of the United

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

^{13.} Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.



Proposed Plugged WBD

UCBH WW Fed #7 **Proposed WBD**

Les Peeler 1-19-18

30-015-25313

KB: 2978' GL: 2965'

07/30/1985 Spud: Completed: 09/01/1985

Perf @ 150' sqz 100 sxs to Surface

Sct 25 - 26S - 29 E Eddy Co., New Mexico Brushy Draw, Delaware Field Ser. # NM 35607 GPS: 32.018119 -103.938901

N. of Red Bluff Lake

13 3/8" 54.5# J-55 Csg. (17 1/2" hole) to 476' Cmt'd w- 675 sxs. to surface

Perf @ 526' sqz 100 sxs-WOC-Max Tag 376

Perf @ 1,340' sqz 100 sxs WOC -Tag@ 1,190'

Rustler Water: 350' - 1,290'

Perf @-2,970" sqz 60 sxs WOC -Tag@2,820"

8 5/8" 24# J-55 Csg. (11" hole) to 2920' Cmt'd w- 150 sxs. ≈TOC @ 2,387'

5 1/2" 15.5# J-55 Csg. (7 7/8" Hole) to 6,350' Cmt'd w- 900 sxs. TOC @ 2,350' (per CBL)

Set 5 1/2" CIBP @ 5,061' & Spot 60 Sxs. OVER DVT DV Tool: 4,801'

PBTD: 6,162'

Delaware: 5,161' - 5,241'

Brushy Draw: 5,554' - 6,110'

les a peeleroilfield com

TD @ 6,350'



UCBH WW Fed #7 Plug and Abandon Procedure

Brushy Draw - Delaware Field

Section 25 T-26S, R-29E Eddy Co., New Mexico

API # 30-015-25313 Lease # NM 35607 GPS: 32.018119 -103.938901

Spud Date: 07/30/1985 TD Date: 09/01/1985

Producing Formations: Delaware: 5,161' - 6,110'

 KB Elev:
 2978'

 GL Elev:
 2965'

 TD:
 6,350'

 PBTD:
 6,162'

 Marker Joint:
 N/A

CASING SUMMARY:

Safety Factor = 80% of new applied to burst, collapse and tension parameters in table.

Size	Depth (ft)	Weight (#/ft)	Grade psi	Connection Type	Capacity (bbls/ft)	ID (in)	Drift (in)	Burst (psi)	Collapse (psi)	Tension (lbs)
13 3/8"	476'	54.5 #	<u> </u>	n/a	.1546	n/a	n/a	n/a	n/a	n√a
8 5/8"	2,920'	24#		n/a	.0637	n/a	n/a	n/a	n/a	n/a
5 1/2"	6,350'	15.5#		n/a	.0238	n/a	n/a	n/a	n/a	n/a

Surface:

13 3/8": 0'- 476'- TOC @ surface w-675 sxs.

Production:

8 5/8": 0'-2,920' - TOC @ 2,387' w-150 sxs.

Production

5 1/2": 0'-6,350' - TOC @2,350' w-850 sxs.

COMPLETION HISTORY TO DATE:

OBJECTIVE: Plug and abandon.

WPX REQUIRES THAT HARD HATS, STEEL TOE BOOTS, FIRE RETARDANT CLOTHING, AND SAFETY GLASSES BE WORN ON LOCATION.

HOLD SAFETY MEETING PRIOR TO COMMENCING PERFORATING, WIRE LINE AND PUMPING OPERATIONS

NO IGNITION SOURCES WITHIN 100 FT OF THE WELLHEAD, FLOWBACK TANKS OR MANIFOLD.

PROCEDURE:

- 1) Test safety anchors and replace as necessary.
- 2) MIRU Service Unit. Deliver, unload and tally 5,200' 2-3/8" 4.7# J-55 EUE work string.
- 3) Press. test tbg.
- 4) NDWH NUBOP -
- 5) POOH w- rods & tbg. & Lay Dn.
- 6) RUWL RIH w- GR to 5,061'.
- 7) RIH w- 5 1/2" tbg. conveyed CIBP & set @ 5,061' PU 1 jt. Pump 135 bbls. heavy mud. Spot 60 sx Class C Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) 5,061' 4,500' Covering DVT @ 4,801', flush with heavy mud. TOOH w- tbg.

8) Stand back 2,900' tbg. & LD rest.

9) RUWL - RIH & Perf @ 2,970' (50' below 8 5/8" csg.)

10) Set pkr & Sqz. 60 sxs. Class "C" Cmt. @ 2,970! - 2820.

- 11) WOC Tag Max Tag @ 2,820' 2870
- 12) POOH & LD Tbg. & stand back 1,345'
- 13) RU WL & Perforate @ 1,345' (50' below Rustler Water) RD wireline.
- 14) RIH w- Pkr & tbg. set Pkr. Establish pump rate. Squeeze 100 sx Class "C" Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 1,345' to 1,190'. Flush with mud.
- 15) WOC & Tag Max. Tag @ 1,190'
- 16) POOH & LD tbg. & stand back 400'.
- 17) RU WL & Perforate @ 526'. RD MO wireline
- 18) RIH w- Pkr & tbg. set Pkr. Establish pump rate. Squeeze 100 sx Class C Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 526' to 376'.
- 19) WOC & Tag Max. Tag @ 376'.
- 20) RU WL & Perforate @ 150'. RD MO wireline
- 21) RIH w- Pkr & tbg. set Pkr. Establish pump rate. Squeeze 100 sx Class C Cement (14.8 ppg, 6.3 gps, 1.32 cfs yield) from 150' to surface.
- 22) RDMO Service Unit. RDMO Cementers.
- 23) MIRU Welder. Cut-off casing head. WO cap with well name and number, operator name, and date.
- 24) Pull safety anchors, dress, and reclaim surface location if necessary.

WPX Contact List:

WPX	Title	Ofc.	Cell	
Justin Warren	Production Superintendent	575-885-7525	701-421-7324	
Steve Bernhardt	Permian Production Engineer	539-573-3548	918-671-0683	
Brad Ballinger	Permian Production Engineer	539-573-0135	303-928-0799	
Bailey Nett	Permian Production Engineer	539-573-2547	505-386-8974	
David Hernandez	Permian Production Engineer	539-573-0205	918-282-8382	
Josh Walker	Regulatory Specialist	539-573-0108	580-716-0330	
Les Peeler	Plugging Consultant	405-659-5185	405-318-4726	

Emergency Contacts - New Mexico:

Hospital: Carlsbad Medical Center (575) 887-4100

2430 W. Pierce St., Carlsbad, NM 88220

Sheriff's Office: Lea County Sheriff Dept (575) 396-3611

Eddy County Sheriff Dept (575) 887-7551

Emergency Contacts - Texas:

Hospital: Reeves County Hospital (432) 447-3551

2323 Texas St, Pecos TX 79772

Sheriff's Office: Reeves County Sheriff Dept (432) 445-4901

Loving County Sheriff Dept (432) 377-2411

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612