

RECEIVED

OIL CONSERVATION DIVISION

MAR 09 2020

1220 S. St. Francis Dr. Santa Fe, NM 87505

EMNRD-OCD ARTESIA

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

WELL API NO. 30-015-23728
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name DORSTATE SWD
8. Well Number 1
9. OGRID Number 373626
10. Pool name or Wildcat SWD; BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>SWD</u>	
2. Name of Operator <u>PERMIAN WATER SOLUTIONS, LLC</u>	
3. Address of Operator <u>600 TRAVIS ST., SUITE 4700, HOUSTON TX 77002</u>	
4. Well Location Unit Letter: H Section 27 1980 feet from the <u>NORTH</u> line and 660 feet from the <u>EAST</u> line Township 25 S Range 28 E NMPM EDDY County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 2968' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plan to P&A as follows. MIRU pulling unit. Check wellhead psi. If pressured up, then try to kill with brine or mud depending on psi. Once well is stable, un-flange well head and try to open bypass on AS 1X pkr or on/off tool. After pkr is released and well is dead, POOH w/ tbq & pkr and LD all equipment. PU 2.375" work string, 4.75" bit, x/over & csg scraper, and RIH to tag CIBP @ 3680'. Circulate hole volume twice to clean up & try to test CIBP back to GL. If test fails, RIH w/ pkr and find leak. After leak is found, get approval from OCD to set plugs to isolate and PB to GL. If test on 2nd plug is good, notify OCD and get plug recommendation to P&A back to GL. After plug recommendation has been approved by OCD, schedule job and P&A well. After P&A is completed, clean site, remove anchors, and install P&A marker. See attached current and proposed well bore diagrams.

Use This format

① R₂ y Pull Tb,
② RIH + Tag TD
③
④
⑤
⑥

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Brian Wood

TITLE CONSULTANT

DATE 1-27-20

Type or print name BRIAN WOOD

E-mail address: brian@permitswest.com

PHONE: 505 466-8120

For State Use Only

DENIED

DENIED

APPROVED BY:

TITLE

GC
DATE 3/13/20

Conditions of Approval (if any):