


OPERATOR: Xeric Oil & Gas	API# 30-015-22220
WELL: Eddy "GF" State # 1	LOCATION: C-16-23-27
SURFACE CSG- HOLE SIZE "	CSG. SIZE 16" SET @ 399' SX. CMT. TOC. Circ
INT.CSG- HOLE SIZE	CSG. SIZE 10 3/4" SET @ 2000' SX. CMT. TOC. 840'
LONG STRING- HOLE SIZE "	CSG. SIZE 7 5/8" SET @ 8990' SX. CMT. TOC. 4310'
OTHER-	



Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-015-22220
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. L-00187-003
7. Lease Name or Unit Agreement Name: Eddy "GF" State
8. Well No. 1
9. Pool name or Wildcat Forehand Ranch Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	2. Name of Operator Xeric Oil & Gas Corporation
3. Address of Operator P. O. Box 352 Midland, TX 79702	4. Well Location Unit Letter C : 810 feet from the North line and 1980 feet from the East line Section 16 Township 23S Range 27E NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU Pulling Unit and workstring. Circulate hole w/9 1/2# mud.
2. TIH w/tbg open ended @ 7060' & spot 25 sx Class H (Top of plug @ 6938') & tag..
3. Cut 7 5/8" casing @ freepoint (+/- 4000') and lay down.. 25 sx plug @ 5470'
4. Spot 50 sx Class C 50' in and out of stub & tag.. 100' plug 1950'-2050'
5. Cut 10 3/4" casing @ freepoint (+/- 800') and lay down.. 100' plug 980'-1080'
6. Spot 75 sx class C 50' in & out of stub & tag.
7. Spot 25 sx class C @ 400'. 100' plug 350'-450'-TAG
8. Spot 25 sx class C @ 50'. 60' plug 0'-60'- WDC-24 HRS-TAG
9. Install dry hole marker & clean location.

Salt gel mud consisting of 10#
Brine W/25# of gel per bbl

Notify OCD 24 hrs. prior to any work done



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 8/15/03
Type or print name Angie Crawford Telephone No. 432-683-3171

APPROVED BY [Signature] TITLE Field Rep ID APPROVED AUG 19 2003
Conditions of approval, if any:

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: Eddy "GF" State #1
COUNTY: Eddy
STATE: NM


HOLE SIZE: 20"
CASING: 16" @ 39'
CEMENTED WITH: 430 SX
CEMENT TOP: Surface

TUBING: _____
RODS: _____
PUMP: _____
PACKER: _____

HOLE SIZE: 14 3/4"
CASING: 10 3/4" @ 2000
CEMENTED WITH: 1300 SX
CEMENT TOP: 840'
Per. Temp. Survey

LINER: HOLE SIZE 6 1/2"
CASING SIZE 5"
CEMENTED WITH 650 SX
TOP 8688' BOTTOM 12267'

HOLE SIZE: 9 1/2"
CASING: 7 5/8" @ 8990'
CEMENTED WITH: 800 SX
CEMENT TOP: 4310'
Per. Temp. Survey



Perfs:

③ 7061' - 7215'
② 10,932' - 10,942'
① 11,842' - 12,162'

PBTD: _____
TD: 12,269