

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

SUNDRIY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-22865
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator BP America Production Company		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1089, Eunice NM 88231		7. Lease Name or Unit Agreement Name: EMPIRE ABO UNIT 'G'
4. Well Location Unit Letter J : 1420 feet from the S line and 2050 feet from the E line Section 34 Township 17S Range 28E NMPM County EDDY		8. Well Number 353
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3663.8' GR		9. OGRID Number 00778
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram or proposed completion or recompletion.

Notify OCD 24 hrs. prior to any work done.

Proposed P&A procedure:

1. MIRU PU. Check casing and surface pipe for pressure - bleed off into containment. Monitor well and assure it's stable. ND WH, remove joint in head and install BOP. Test BOP and casing to 500 psi.
2. TIH with bull-plugged perforated nipple on work string. Tag CIBP at 6187'. Spot 250' cement plug on top of CIBP using 25 sx Class C neat. PU to 5900'. Load hole with mud-laden fluid.

Continued on page 2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Barry C. Price TITLE Area Operations Team Lead DATE 08/06/08
Type or print name Barry C. Price E-mail address: barry.price@bp.com Telephone No. 575-394-1648

For State Use Only

APPROVED BY Phyllis Harkin TITLE Comptroller DATE 8/4/08
Conditions of Approval, if any:

Form C-103
Empire Abo Unit G-353
30-015-22865
Continued from Page 1

3. POH to 3900' (Glorieta top = 3800'). Spot 25 sack balanced cement plug from 3900' – 3650'. PU and WOC 2 hours. Tag plug, re-spot if necessary.
4. POH to 3150' (stage tool = 3014'). Spot 25 sack balanced cement plug from 3150-2900'.
5. POH to 900' (8 5/8" surface casing shoe = 800', Yates top = 550'). Spot 45 sack balanced cement plug from 900' – 450'. POH. WOC 2 hours. Tag plug, re-spot if necessary. POH
6. Spot 10 sack cement plug from 30' to surface.
7. RD PU.
8. Dig out WH and cut-off casingheads to 3' below GL.
9. Install regulation dry-hole marker. Clean location and prepare location for NMOCD inspections.


Empire Abo Unit G-353
Empire Abo Field

API No. 30-015-22865

1420' FSL & 2050' FEL
Sec 34 - T17S - R28E
Eddy County, New Mexico

Status 6-27-2008

Event
Date



Empire Abo Unit G-353
Empire Abo Field

API No. 30-015-22865

1420' FSL & 2050' FEL
Sec 34 - T17S - R28E
Eddy County, New Mexico

Proposed P & A

Event
Date

