

V.L. Foster, page two

- 4-7- RIH w/ 2-3/8 tbg w/ $\frac{1}{2}$ MULE shoe JT TAG 2085, Unable to Go inside $4\frac{1}{2}$ csg. PU to 2054, CIRC hole w/ 10# brine, mix & spot 100sx Class "C" cmt, plug 2054-Displ to 2000'.
- 4-8- RIH w/ 2-3/8 tbg. TAG cmt plug 1440' CIRC hole w/ 10# brine. POH w/ 2-3/8 tbg.
- 4-9- PERF 4 sqz holes 1400', RIH w/ 2-3/8 tbg open ended. Spot 50sx Class "C" cmt Plug 1395-1135, POH w/ tbg. WOC 4 hrs. RIH w/ 2-3/8 tbg open ended, to 1440', No cmt above perfs at 1400', PU TS 1395, Mix & pump 50 sx Class "C" cmt, Plug 1395-1135, POH w/ tbg.
- 4-10- RIH w/ 2-3/8 tbg open-ended. TAG cmt plug at 590'. POH w/ 2-3/8 tbg. PERF 4 sqz. holes @ 480'. RIH w/ 2-3/8 tbg open-ended, Mix & spot 50 sx cmt Plug 466-220'. POH w/ 2-3/8 tbg WOC 5 hrs. RIH w/ 2-3/8 tbg. Open-ended. TAG cmt plug @ 290', POH w/ 2-3/8 tbg.
- 4-11 Spot 10 sxs cmt. Plug at surface/cut off csg (4' below GL) Weld on steel plate, install dry hole marker.