

OIL CONSERVATION DIVISION

P. O. BOX 2

SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
U.S.G.S.		
LAND OFFICE		
OPERATOR	<input checked="" type="checkbox"/>	

RECEIVED BY
OCT 7 1985
O. C. D.
ARTESIA OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State

Fed

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Anadarko Petroleum Corporation	8. Farm or Lease Name State L-16
3. Address of Operator P. O. Drawer 130, Artesia, New Mexico 88210	9. Well No. 1
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 18S RANGE 29E N.M.P.M.	10. Field and Pool, or Wildcat Loco Hills-Queen-Grayburg-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3501' GL	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK
TEMPORARILY ABANDON
PULL OR ALTER CASING
OTHER

PLUG AND ABANDON
CHANGE PLANS
OTHER

REMEDIAL WORK
COMMENCE DRILLING OPNS.
CASING TEST AND CEMENT JOB
OTHER

ALTERING CASING
PLUG AND ABANDONMENT
OTHER

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig up pulling unit; go in hole with tubing open-ended; circulate hole with 10# brine & Salt gel mud.
- Spot 50 sx cement from 2455' up to 2087' (this plug covers Grayburg Fm. top, 7" casing shoe and top of 5 1/2" liner). Pull up hole; wait 3 hours; tag top of plug.
- Perforate 4 squeeze holes @ 920' (100' below Salt section).
- Go in hole with packer and cement squeeze with 50 sx cement out squeeze holes, leaving 155' cement in 7" and 155' cement outside 7" (this plug isolates bottom of Salt section). Wait 3 hours and tag top of plug.
- Perforate 4 squeeze holes @ 370' (50' above Salt section).
- Go in hole with packer and cement squeeze with 50 sx cement out squeeze holes, leaving 155' cement in 7" and 155' cement outside 7" (this plug isolates top of Salt). Wait 3 hours and tag top of plug.
- Spot 50' cement plug at surface.
- Cut off all casing and anchors below surface; set P & A marker; clean and level location.

Note: Will leave 10# brine and Salt gel mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Williams TITLE Field Foreman DATE October 4, 1985

APPROVED BY Mike Williams TITLE Oil & Gas Inspector DATE OCT 8 1985

CONDITIONS OF APPROVAL, IF ANY: N.M.O.C.C. in sufficient time to witness

Plugging