

Leonard Oil Co.
State B 7717 #1
Ut I-2-19-27

8 5/8" at 375' 50 Sxs cement
7" at 2550' 100 Sxs cement

1. Move in and rig up plugging contractor
2. Remove dry hole marker and prepare well head and rig up BOP
2. Begin drilling operations. Drill out the following plugs:
 - (A) Surface
 - (B) 1055'-1060'
 - (C) 1591'-1605'
 - (D) 2250'-2280'
 - (E) 2950'-2975'
4. Run in hole with tubing and packer and test casing. Depending on condition of casing we may need to continue drilling and testing.
5. Spot a 100' plug at 2975'
6. Spot a 100' plug at 2250'
7. Spot a 100' plug at 1650'
8. Spot a 100' plug at 1000'
9. Perforate 7" casing at 425' and squeeze 100 Sx of cement
10. If possible circulate cement on the 8 5/8" casing either by perforating or using holes in casing.
11. Spot a 10 Sx surface plug and dry hole marker.
12. Set new marker.
13. Mud between plugs.

[illegible]