		I COLOR 1C
NOV 5 11 00 MM 193BUREAU NOV 5 11 00 MM 193BUREAU SUNDRY NOTI Do not use this form for Boposals	UNITED STATES MENT OF THE INTERIOR OF LAND MANAGEMENT CES AND REPORTS ON WELLS to drill or to deepen or reentry to a different reservoir. N FOR PERMIT—" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 029387 A 6. If Indian, Allottee or Tribe Name
SUI	BMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type of Well Oil Gas Well Well Name of Operator		8. Well Name and No. SHUGART A # 5
SOUTHLAND ROYALTY COMPANY		9. API Well No.
3. Address and Telephone No.		30-015-0563800
	79710 915–688–6943	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or St L, 1650' FSL & 990' FWL 29, T18S, R31E	irvey Description)	SHUGART (Y,SR,Q) 11. County or Parish, State EDDY COUNTY, NM
CHECK APPROPRIATE	BOX(s) TO INDICATE NATURE OF NOTICE, REPO	DRT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		١
X Notice of Intent		Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	
Final Abandonment Notice	Altering Casing	Conversion to Injection Dispose Water
. Describe Proposed or Completed Operations (Clear		Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
 3. Describe Proposed or Completed Operations (Clearling ive subsurface locations and measured and to POOH 1. MIRU : POOH 2. PU bit a tubing. 3. MIRU (perform Lower wireline) 4. PU "So tubing. 5. MIRU. movem 6. Start pr function 	V state all pertinent details, and give pertinent dates, including estimated date of start rue vertical depths for all markers and zones pertinent to this work.)* service unit. POOH with: 148, 3/4" rods and pump. ND wellhead. NU BOF with ±118 joints of 2 3/8", 4.7#, J-55 tubing and mud anchor. and scraper for 4 1/2", 10.5# casing on ±3,800' of 2 3/8", 4.7#, J-55 production POOH with tubing, LD bit and scraper. electric wireline unit. RU pack off head on BOP. RIH with 3 1/8" HSC ting gun and CCL. Correlate CCL to GR/ CCL dated 4-18-77 and perforate to Yates from 2,546' - 2,570' with 4 SPF, 90° phasing. POOH. RDMO electric	Conversion to Injection Dispose Water (Note: Report results of multiple completion as Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled, on the J-55 ing her is

7. Close annulus. Increase rate to 3 BPM. Treat the perforated intervals with 8,000 gallons of Resi-Sol acid as per the listed schedule while continuously moving the Sonic Hammer through the perforated interval(s).

Anticipated Pressure (tubing):	2,900 psi
Maximum Pressure (tubing):	6,100 psi
Maximum Pressure (casing):	3,500 psi
or Stripping Head rating	

NOTE: Pump ±100 gallons of 2% KCl between connections.

- 8. PU and LD tubing check valve. Drop ball. Lower tubing to ±3,790'. Open shear sleeve and annulus. Circulate hole clean with 2% KCl. Monitor returns.
- 9. POOH with tubing and Sonic Hammer. PU RBP and treating packer for 4 1/2", 10.5# casing, on ±2,630' of 2 3/8", 4.7#, J-55 tubing. Set RBP at ±2,630'. PU to ±2,620'. Set packer.
- 10. MIRU fracture stimulation company. NU on 2 3/8" tubing. Pressure test surface lines and RBP to 6,100 psi.
- Release packer and PU to ±2,400'. Set packer. NU frac value on 2 3/8" tubing. Pressure test frac value and surface lines to 6,100 psi. Place 500 psi on annulus and monitor throughout treatment.
- 12. Fracture Lower Yates with 6,500 gallons of 35# cross-linked gel and 20,000 lbs of 12/20 Brady sand down 2 3/8" tubing. See attached pump and breaker schedule.

Anticipated Rate:	18 BPM
Anticipated Pressure:	3,800 psi
Maximum Pressure:	6,100 psi

- 13. Record ISIP, 5, 10, 15 minute shut in pressures. SI for ±4 hours.
- 14. RDMO frac company.
- 15. Flow back well as needed. RU foamed air unit. Clean out to top of RBP at ±2,630'. llow well to stabilize and foam clean again. Latch on to RBP and release. POOH laying down retrieving tool and RBP.
- PU 2 3/8" mud anchor, 1.781" SN and 2 3/8" x 4 1/2" TAC on ±2,510' of 2 3/8", 4.7#,
 J-55 production tubing. Set TAC with tubing above top perf at 2,546'. ND BOP. NU wellhead.

RIH with $2" \ge 1 \frac{1}{2}" \ge 12'$ pump, $\pm 100 - \frac{3}{4}"$ rods. Space out pump and hang on. 17. RDMO service unit.

Turn over to production operations. Report well tests daily for 15 days via PDT. 18.

Date:_____

Approved:______ T. J. Harrington



MERIDIAN OL

rss/SHUGA5_C.DRW 10/26/93