16.

Ut...(ED STATES Artesia, SMM 188210 CIPL CATE* DEPARTMENT OF THE INTERIOR (Other instructions on re-

GEOLOGICAL SURVEY

	Form a	pprove	eđ.	
	Budget	Burea	u No.	42-R142
TRIAB	n na .a.			

					· · -	
5.	LEASE	DESIGN	KOITA	AND	SERIA	L NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

LC-029387-D

SUNDRY	<u> </u>	NOTICE	S	ANI)	REPC	R	TS	ON	be\	ENES	
use this form	for	proposals	to	drill or	to	deepen	οr	plug	back	to a	different	res

ervoir. (Do not use this form for proposals to arill by to despend of proposals.)

Use "APPLICATION FOR PERMIT—" for such proposals.)

	. 1	
JUL 07 1983	7. UNIT AGREEMENT NAM	(E
O. C. D.		
ARTESIA, OFFICE	9. WELL NO.	
79701	2	
ccordance with any State requirements.*	· · · · · · · · · · · · · · · · · · ·	
T-18-S, R-31-E	11. SEC., T., R., M., OR BI SURVEY OR AREA	K. AND
	Sec. 19, T-18	-S, R-31-E
NS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
3631' GR	Eddy	N.M.
	O. C. D. ARTESIA, OFFICE 79701 ccordance with any State requirements.* T-18-S, R-31-E NS (Show whether DF, RT, GR, etc.)	O. C. D. ARTESIA, OFFICE 79701 ccordance with any State requirements.* T-18-S, R-31-E Sec. 19, T-18 Sec. 19, T-18

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:						
	Li					<u> </u>		
TEST WATER SHUT-OFF	ll	PULL OR ALTER CASING		WATER SH	IUT-OFF	<u> </u>	REPAIRING WELL	-
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE	TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE	1	ABANDON*		SHOOTING	OR ACIDIZING		ABANDONMENT*	_
REPAIR WELL		CHANGE PLANS				<u>eat Queen</u>		XX
(Other)				(Nor	TE: Report rest upletion or Reco	ults of multiple ompletion Report	completion on Welt and Log form.)	I1

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *
 - MIRUPU. POH w/rods & tbq. RU & set CIBP @ 3350'. Loaded hole w/2% KCl wtr. Ran cmt bond log. TOC @ 2710'. Ran csg inspection log from 2800' to surf. Press csg to 500#.
 - 2. RU & perf @ 3160-3216' (18 holes). GIH w/tbg & pkr to 3215'. Spot 168 gals 7 1/2% NE acid from 3215-3047'. Pull pkr to 3058'. Rvse acid out of csg into tbg. Set pkr. Pmp into perfs @ 1200#. Pmp 3 1/2 BBLs @ .6 BPM @ 1100#. Acdz perfs w/total of 3000 gals 15% NE acid & 27 BS. Flw & swb 45 BLW in 4 hrs.
 - RU & frac perfs 3160-3216' w/18,000 gals gelled KCl wtr, 25,500# 20/40 sd & 12,500# 10/20 sd. Open well on 1/4" ck. Flwd 25 BLW in 24 hrs.
 - RDPU. Rlsd pkr. Clean out sd from 3335-3350'. LD workstring. Ran 2 3/8" tbg & set @ 3275'. SN @ 3260'. GIH w/rods & BHP. Start well pmpg.



MAR 1 0 1983

DIL & GAS

·		ROSWELL, NEW MEXICO
S. I hereby certify that the foregoing is true and co	TITLDistrict Operations	
(This space for Federal or State office use)		
APPROVED BY	TITLE	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:	ILLUU	OP IT
		JUL 5 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO