	Drawer DD	CLSF	
	UNITED STATES SUBMIT IN TRIPLACATE.	Form approved.	
Form 9-33 (May 196		Budget Bureau No. 42-B1424. 5. LEASE DESIGNATION AND SERIAL NO.	
	GEOLOGICAL SURVEY	LC-029387 (b)	
	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT_" for such proposals.)		
	Use "APPLICATION FOR PERMIT-" for such proposals.)	7. UNIT AGREEMENT NAME	
1. 01L			
WELL 2. NAME	OF OPERATOR	8. FARM OR LEASE NAME	
50	uthland Royalty Company V RECEIVED BY	Shugart "D"	
3. ADDRE	SS OF OPERATOR	9. WELL NO.	
21	Desta Drive, Midland, Texas 79705	9 10. FIELD AND POOL, OR WILDCAT	
4. LOCAT See a At su	iso space 17 heiow.)	Shugart (Y,SR,Q,G)	
	or FSL & 330' FWL, Sec. 20, T-18-S, R-31-E O. C. D. ARTESIA, OFFICE	11. SEC., T., B., M., OB BLK. AND SURVEY OR AREA	
•••	ARTESIA, OTTO		
	I. NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 20, T-18-S, R-31-E	
14. PERM	Unknown	Eddy N.M.	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or (
	NOTICE OF INTENTION TO: SUBSEQ	UENT REPORT OF:	
TEST	WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
	TURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING ABANDONMENT [®] XX	
	UR WELL CHANGE FLANS (Other)		
(Otl	(Nors: Report_result	s of multiple completion on Well pletion Report and Log form.)	
pre	THE FROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates posed work. If well is directionally drilled, give subsurface locations and measured and true vertice at to this work.) *	, including estimated date of starting any mi depths for all markers and zones perti-	
1.	RU WL to back off tbg. Unable to pull tbg. & pkr. Perf 2 pkr. Circ FW dwn tbg & up annulus. Moved pkr up hole 10' Unable to move up or dwn.	holes in tbg 1" above & hung again. Worked tbg.	
2.	 Ran free pt. Tbg stuck @ 1840'. Back off collar @ 1811'. POH w/tbg. TIH w/BS, jars, 4 3 1/2" DC's & tbg. Screw onto fish. Worked stuck tbg. Jars parted. TOH w/tbg. 		
3.	3. TIH w/OS, jars DC's & tbg. Fished jars. Backed off tbg. TOH w/tbg & fish. TIH w/BS, jars & DC's. Screw into fish. Work pkr loose. Circ csg w/100 bbls FW. TOH w/tbg. TIH w/tbg & ret tool. Retrieve RBP. POH w/tbg. TIH w/cmt ret & tbg. Set ret @ 3087'.		
4.	Well plugged & abandoned 4-7-85 per NMOCD. GIH w/tbg. St pmpd 150 sxs Cl "C" neat cmt. 50' plug top of ret. TOH w/ tbg. Set ret @ 1797'. Dowell pmpd 100 sxs Cl "C" neat cmt Spotted 10# mud from 1747-720'. Pull tbg to 720'. Pmpd 75 Cmt circ to surf. TOH w/tbg. RDCU. Weld dry hole marker.	tbg. TIH w/cmt ret & , 50' plug top of ret. sxs Cl "C" neat cmt.	
	reby certify that the foregoing is true and correct TED bhan Mark TITLE Operations Engineer	DATE 4/17/85	
	150		
(Thi	s space for Federal or State office use)	7256	
APP CON	TITLE DITIONS OF APPROVAL, IF ANY :	DATE 2386	

*See Instructions on Reverse Side