

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 1980' FWL - Unit Letter N

14. PERMIT NO.

30-D15-20426

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR. If necessary kill well. Release Baker Model R double grip pkr at 6665' & pull Hbg Gum Shole.
2. G1H w/ lit, csq scraper & Hbg to 7600'. Tag RBP & POOH. G1H w/ OE Hbg to 7600'. Pump 13 bbls 10 ppq mud then 25 sxs class "H" 15.6 ppq cement to place plug over BP. Displace w/ 42 bbls 10 ppq mud & POOH. G1H w/ workstring & cement retained & set at 6626'. Pump 25 sxs class "H" 15.6 ppq cement. Pull out of retained & pump 25 sxs 15.6 ppq cement to cap. retains. POOH to 6400'. Pump 149 bbls 10 ppq mud to circ hole full. POOH.
3. G1H w/ 4' perf gun. Perf at 5510' w/ 4 spf & POOH. G1H w/ Hbg & establish inj rate thru perfs and circ up annulus. If inj rate cannot be accomplished, G1H w/ OE workstring to 5573' & pump 25 sxs class H, 15.6 ppq cement & displace w/ 30 bbls 10 ppq mud. If inj rate is established, G1H w/ OE Hbg to 5510' & pump 40 sxs class "H" 15.6 ppq cement. Displace w/ 31 bbls 10 ppq mud. Shut-in for 4 hrs. G1H w/ wireline & tag cement plug. Plug should be no deeper than 5410'. Fill hole w/ 10 ppq mud. POOH to 2138'. Pump 25 sxs class "H" 15.6 ppq emt. Displace w/ 12 bbls 10 ppq mud. This isolates Gum from San Andres. POOH. G1H w/ perf gun. Perf at 1730' w/ 4 spf & POOH. G1H w/ OE Hbg. Establish inj rate thru perfs and circ up annulus w/ 10 ppq mud. If inj rate cannot be established

18. I hereby certify that the foregoing is true and correct

SIGNED William W. Baker
(This space for Federal or State office use)

TITLE Administrative Supervisor

DATE April 18, 1989

APPROVED BY Shammy Shaw
CONDITIONS OF APPROVAL, IF ANY:

FOR: CHIEF OF BUREAU
TITLE JONES

DATE 4-27-89

*See Instructions on Reverse Side