



Foamed Acid

Job Recommendation

Acidize this well with 4,000 gallons of 10% Fe acid comingled with 6,000 gallons of CO₂. Treat this well down tubing at 4 BPM with an estimated WHTP of 4,332 psi. Drop 100 ball sealers to divert the acid. Flush with 60 Quality CO₂ and 2% KCl.

10% FE ACID DETAILS: (4,000 gal)

Base Fluid	10% Fe Acid
Base Fluid	547 gal/M Water
Base Fluid	253 gal/M Acid
Base Fluid	200 gal/M Methanol
Clay Stabilizer	2 gal/M Cla-Sta® XP
Iron Control	10 gal/M Fe-1A
Iron Control	9 gal/M Fe-2A
Corrosion Inhibitor	2 gal/M HAI-85M
Surfactant	1 gal/M LOSURF-300
Surfactant	4 gal/M SSO-21M

Replace 200 gallons of the mix water with Methanol.