

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TO LOCATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 43-21424

3. LEASE DESIGNATION AND SERIAL NO.

NM7039

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

7. UNIT AGREEMENT NAME

Northwest Indian Basin U

8. FARM OR LEASE NAME

9. WELL NO.

1-Y

10. FIELD AND POOL, OR WILDCAT

Northwest Indian Basin

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA

Sec. 28 T20S R23E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☒ (OTHER)

2. NAME OF OPERATOR

Charles A. Dean

OCT 20 1978

3. ADDRESS OF OPERATOR

503 Gulf Bldg. Midland, Texas 79701

O. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements, OFFICE
See also space 17 below.)
At surface

2030' FSL & 1980' FWL Section 28, T20S, R23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, OR, etc.)

4229 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and casing points nearest to this work.)*

Perfs: 8747-61 Production Csg 4 1/2" 13.5# set @ 8932'
8 5/8" set @ 1993'
13 3/8" set @ 816' circ. cmt.

1. Set CIBP @ 8515' cap with 5 sx cement on top.
2. Circulate hole with brine containing 25 sacks gel per 100 barrels
3. Shot 4 1/2" casing 5886' pulled same set 25 sx cement plug 5935'-5785'
4. Set 50 sx cement plug (150') from 5500'-5350'
5. Set 35 sx cement plug (100') at 3500'-3400'
6. Set 35 sx cement plug (100') at base of 8 5/8' @ 1993' (2050-1950)
7. Set 20 sx cement plug at surface
9. Weld dry hole marker
9. Clear Location.

RECEIVED

OCT 08 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE 10/7/76

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE OCT 19 1978

CONDITIONS OF APPROVAL, IF ANY: