

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAR 25 1991

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

O. C. D.  
ARTESIA, OFFICE

WELL API NO.

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
L326

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Lone Tree

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

8. Well No. 1

2. Name of Operator  
Bledsoe Petro Corp. ✓

9. Pool name or Wildcat  
Undesignated

3. Address of Operator  
3908 N. Peniel, Suite 500, Bethany, OK 73008

4. Well Location  
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 13 Township 21S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
GR 3163

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
PULL OR ALTER CASING   
OTHER: Test zone behind 9 5/8" csg.

PLUG AND ABANDON   
CHANGE PLANS   
REMEDIAL WORK   
COMMENCE DRILLING OPNS.   
CASING TEST AND CEMENT JOB   
ALTERING CASING   
PLUG AND ABANDONMENT   
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Set CIBP at 9000' w/ 35' cement on top

1. Set CIBP at 9000', cap with 35' cement plug (strawn perms open 9312-46, 9674-82 & 10,481-487).
2. Circulate hole to 9.5# mud. Plug @ 2930' 2nd Done Spring sand
3. Shoot 5 1/2" casing at free point (calc. TOC 7650') est free point 5000-6000'
4. Spot 100 ft cement plug at 5 1/2" cut off point. Tag
5. Pull 5 1/2" csg., spot 100 ft cement plug 2000' above 5 1/2" cut off point.
6. Spot 100' cement plug at base of 9 5/8" csg (50' out-50' in) @ 3060'. Tag
7. Run tubing with bit, dress off last plug, if necessary, to 3000', circulate mud from hole with fresh water, circulate fresh water with salt water.
8. Perforate 9 5/8" csg for production 2930-2980' (Delaware sd.), test, stimulate as required.
9. Put well on production or continue plugging operations with cement plug from 30' to surface. Est starting date April 15, 1991.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President DATE 3/21/91

TYPE OR PRINT NAME Gary J, Garbacz (405) 789-5053 TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 5/2/91

CONDITIONS OF APPROVAL, IF ANY: