Submit 3 Copies to Appropriate District Office

APPROVED BY DISTRICT II SUPERVISOR

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

4 1996

215F

DISTRICT I OIL CONSERVATION DIVISION	,
DISTRICT I P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 OIL CONSERVATION DIVISION P.O. Box 2088	WELL API NO.
DISTRICT II 811 S. 1st Street, Artesia, NM 88210-2834 Santa Fe, New Mexico 87504-2088	30 - 015 - 28589 5. Indicate Type of Lease
DISTRICT III	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lagge Name of U.S. & S. S. S.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Stinking Draw
I. Type of Well: OIL GAS WELL WELL OTHER	Journal of aw
2. Name of Operator Marathon Oil Company	8. Well No.
3. Address of Operator	4
P.O. Box 552, Midland, TX 79702	9. Pool name or Wildcat Dagger Draw U. Penn Assoc S.
4. Well Location Unit Letter 0: 970 Feet From The South Line and 207	-
Unit Letter U: 970 Feet From The South Line and 207	D Feet From The East Line
Section 36 Township 20 1/2 South _{Range} 23-E	MPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL:3653 KB:3668.5	County
Check Appropriate Box to Indicate Nature of Notice, 1	Panart as Other B
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON LA CHANGE PLANS COMMENCE DRILLING C	PNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEM	
OTHER: New Well	Completion
12. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates	Completion X
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 	including estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411 Cleaned out to 9535 Cinc	including estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circle 11/7/95:Ran GR-CCL-CBL.	including estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean.	including estimated date of starting any proposed Clean DEC 2 9 1005
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean.	including estimated date of starting any proposed Clean DEC 2 9 1005
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300. 9335-51. 9402-9412 with 6. ISPE	including estimated date of starting any proposed Clean DEC 2 9 1005
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pact 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well.	including estimated date of starting any proposed Clean DEC 29 105 keropped bar and perfed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pact 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well.	including estimated date of starting any proposed Clean DEC 29 105 keropped bar and perfed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 1/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pact 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/12/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95:Swabbed perfs 9402-9412	including estimated date of starting any proposed Clean DEC 2 9 1005 keren Bropped bar and perfed bing. Set PLS PKR @ 9363'.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 1/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pact 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/12/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95:Swabbed perfs 9402-9412	including estimated date of starting any proposed Clean DEC 2 9 1005 keren Bropped bar and perfed bing. Set PLS PKR @ 9363'.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95: MIRU PU. NU and test BOP. 11/6/95: Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 1/7/95: Ran GR-CCL-CBL. 11/8/95: Drilled out to 9581'. Circ clean. 11/9/95: Ran in hole with tubing conveyed perf guns. 11/10/95: Set Packer @ 9100. ND BOP NU Tree. Test Tree and pactor of packer and packer of packer of packer and packer of packer	including estimated date of starting any proposed Clean DEC 2 9 1005 keropped bar and perfed bing. Set PLS PKR @ 9363'.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95: MIRU PU. NU and test BOP. 11/6/95: Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95: Ran GR-CCL-CBL. 11/8/95: Drilled out to 9581'. Circ clean. 11/9/95: Ran in hole with tubing conveyed perf guns. 11/10/95: Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95: Swabbed Well. 11/12/95: Shut in For BHP BU. 11/13/95: Retrieved BHP bombs. Shut in for Weekend. 11/16/95: Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95: Swabbed perfs 9402-9412. 11/18/95: Acidized 9402-9412 with 2500 gallons 7 1/2% HCL. Swall/19/95: Swabbed 9402-9412. POOH with PKR & Tbg. RIH with RB 11/20/95: Set PLS Pkr @ 9363'. Test RBP. Set Pkr @ 9320. Test 11/21/95: Swabbed well	including estimated date of starting any proposed Clean DEC 2 9 1005 keropped bar and perfed bing. Set PLS PKR @ 9363'.
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pactors of packer and pack	including estimated date of starting any proposed Clean DEC 2 9 1005 keran Propped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE !103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pactors of packer and pactors of packer and pactors. 11/11/95:Swabbed Well. 11/11/95:Swabbed Well. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tubility to be a substantial packer of packer and pa	including estimated date of starting any proposed Clean DEC 2 9 1005 kero Dropped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335 bed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/11/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95:Swabbed perfs 9402-9412. 11/18/95:Swabbed perfs 9402-9412. 11/18/95:Swabbed 9402-9412 with 2500 gallons 7 1/2% HCL. Swall/19/95:Swabbed 9402-9412. POOH with PKR & Tbg. RIH with RB. 11/20/95:Set PLS Pkr @ 9363'. Test RBP. Set Pkr @ 9320. Test. 11/21/95:Swabbed well 11/22/95:Acidized 9335-51 W/2000 gallons 7 1/2% HCL/MEO. Swabled 1/23/95:POOH W/Pkr. Reset RBP @ 9326'. 11/28/95:Set RBP @ 9326'. Pkr @ 9248'. Swabbed Well.	including estimated date of starting any proposed Clean DEC 2 9 1005 keran Propped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/12/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95:Swabbed perfs 9402-9412. 11/18/95:Acidized 9402-9412 with 2500 gallons 7 1/2% HCL. Swall/19/95:Swabbed 9402-9412. POOH with Pkr & Tbg. RIH with RB. 11/20/95:Set PLS Pkr @ 9363'. Test RBP. Set Pkr @ 9320. Test. 11/21/95:Swabbed well 11/22/95:Acidized 9335-51 W/2000 gallons 7 1/2% HCL/MEO. Swabled 1/23/95:POOH W/Pkr. Reset RBP @ 9326'. 11/28/95:Set RBP @ 9326'. Pkr @ 9248'. Swabbed Well.	including estimated date of starting any proposed Clean DEC 2 9 1005 kero Dropped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335 bed {OVER}
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/12/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/11/95:Swabbed perfs 9402-9412. 11/18/95:Swabbed perfs 9402-9412. 11/18/95:Swabbed 9402-9412 with 2500 gallons 7 1/2% HCL. Swa 11/19/95:Swabbed 9402-9412. POOH with PKR & Tbg. RIH with RB. 11/20/95:Set PLS Pkr @ 9363'. Test RBP. Set Pkr @ 9320. Test 11/21/95:Swabbed well 11/22/95:Acidized 9335-51 W/2000 gallons 7 1/2% HCL/MEO. Swabled 11/22/95:Acidized 9335-51 W/2000 gallons 7 1/2% HCL/MEO. Swabled 11/22/95:Acidized 9326'. Pkr @ 9326'. Swabbed Well. 1 hereby certify that the information store is true and complete to the best of my knowledge and belief. SIGNATURE Advanced Engine	including estimated date of starting any proposed Clean DEC 2 9 1005 kero Dropped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335 bed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. 11/5/95:MIRU PU. NU and test BOP. 11/6/95:Drilled out DV tool @ 6411. Cleaned out to 9535. Circled 11/7/95:Ran GR-CCL-CBL. 11/8/95:Drilled out to 9581'. Circ clean. 11/9/95:Ran in hole with tubing conveyed perf guns. 11/10/95:Set Packer @ 9100. ND BOP NU Tree. Test Tree and pace 9260-9300, 9335-51, 9402-9412 with 6 JSPF. 11/11/95:Swabbed Well. 11/12/95:Shut in For BHP BU. 11/13/95:Retrieved BHP bombs. Shut in for Weekend. 11/16/95:Blew well down. ND BOP. NU tree. POOH with Pkr & tull/17/95:Swabbed perfs 9402-9412. 11/18/95:Acidized 9402-9412 with 2500 gallons 7 1/2% HCL. Swall/19/95:Swabbed 9402-9412. POOH with Pkr & Tbg. RIH with RB. 11/20/95:Set PLS Pkr @ 9363'. Test RBP. Set Pkr @ 9320. Test. 11/21/95:Swabbed well 11/22/95:Acidized 9335-51 W/2000 gallons 7 1/2% HCL/MEO. Swabled 1/23/95:POOH W/Pkr. Reset RBP @ 9326'. 11/28/95:Set RBP @ 9326'. Pkr @ 9248'. Swabbed Well.	including estimated date of starting any proposed Clean DEC 2 9 1005 kero Dropped bar and perfed bing. Set PLS PKR @ 9363'. bbed well. P. Set RBP @ 9385' ed annulus. Swabbed 9351-9335 bed {OVER}

_ TITLE ___

- 11/29/95:POOH W/Pkr RBP & TBG. Set CIBP @ 9255'. Tested CIBP to 1000 PSI.
- 11/30/95:Using Tubing conveyed perf guns perfed 9132-9144, 9194-9206 W/6JSPF. Pkr @ 9401'. NU tree.
- 12/1/95: Swabbed perfs 9132-9206. No fluid entry. POOH with tubing and packer.
- 12/2/95:Set CIBP @ 9125'. Dump bailed 35' cement on plug. TOC @ 9090'.
- 12/3/95:Perfed 7650-66, 7680-94, 7702-06, 7726-54 with 23 gram Tungsten charges. 2 JSPF.
- 12/4/95:Using Pinpoint Injection Packer acidized 7650-7754 with 7750 gallons 15% HCL. Swabbed back load.
- 12/5/95:Swabbed well to 12/7/95
- 12/7/95:RIH W/Electric Submersible Pump. Landed bottom of skirted pump @ 7800'. ND BOP NU Tree. RDMO PU. Turned well into test.
- 12/19/95:MIRU PU NU BOP. POOH W/pump and tubing.
- 12/20/95:Installed rod pump, rods and pump jack 2 7/8" tubing. Perf tubing sub @ 7785'. NU Tree. RDMO PU. Turned well into test.

and the same