Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well Oil Well Gas Well Other 2. Name of Operator Contact: MARY CORLEY					5. Lease Serial No. NMSF078596A									
					6. If Indian, Allottee or Tribe Name									
					7. If Unit or CA/Agreement, Name and/or No. NMNM73209 8. Well Name and No. VANDEWART A LS 4 9. API Well No.									
								BP AMERICA PRODUCTION CO E-Mail: corleyi			1@bp.com 30-045-08404-00-S1			\checkmark
								3a. Address P. O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700			10. Field and Pool, or Exploratory BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., T	n)	11. County or Parish, and State												
Sec 13 T29N R8W NWNE 07 36.73048 N Lat, 107.62364 W			SAN JUAN COUNTY, NM											
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE N	ATURE OF 1	NOTICE, RE	EPORT, OR OTHE	R DATA								
TYPE OF SUBMISSION	TYPE OF ACTION													
D Notice of Intent	☐ Acidize	Acidize Deepen		☐ Production (Start/Resume)		■ Water Shut-	Off							
Notice of Intent ☐ Alter Casing		☐ Fractui	Fracture Treat		tion		ity							
☐ Subsequent Report	☐ Casing Repair	asing Repair		☐ Recomplete		Other								
☐ Final Abandonment Notice	☐ Change Plans ☐ Plug and Abandon ☐ Tempo		□ Tempora	rarily Abandon Workover Operations		rations								
	☐ Convert to Injection ☐ Plug Back ☐ Water		☐ Water D	isposal										
If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f BP America Production Compperforating the Menefee and I Please note: The Lower Lewis Upper Lewis Shale is conside Shale portion of the formation	rk will be performed or provided operations. If the operation roandonment Notices shall be final inspection.) canny respectfully request cower Lewis Shale formation is considered the Charca in this aronly.	e the Bond No. on fi esults in a multiple c iled only after all req permission to ac ations as per the sidered a portion	le with BLM/BIA completion or reconstruction ld pay in the sattached procons of the Mesave	A. Required sub- ompletion in a rading reclamation subject well be edure.	sequent reports shall be ew interval, a Form 316, thave been completed,	filed within 30 days 0-4 shall be filed or	s nce							
14. I hereby certify that the foregoing is	Electronic Submission	A PRODUCTION	CO, sent to th	e Farmington	•									
Name (Printed/Typed) MARY CORLEY				•	RESENTATIVE									
Signature (Electronic	Submission)		ate 10/21/2	2002			<u> </u>							
	THIS SPACE F	OR FEDERAL	OR STATE	OFFICE U	SE	1 1 1 1								
/s/ Jim Lovato						UAN ~	/ 20							
Approved By			<u> Fitle</u>			Date								
onditions of approval, if any, are attache														

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

Office

Vandewart A LS #4 Payadd Procedure

Procedure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. Tag for fill and tally OH with 2-3/8" production tubing currently set at 5219'.
- 6. RU WL unit. Run GR log across Menefee and Lewis Shale from 4000' 5250' to select perforations.
- 7. TIH with bit and scraper for 4-1/2" casing to 5225'.
- 8. RU WL unit. RIH with 4-1/2" CIBP. Set CIBP at 5200'.
- 8. RIH with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge. Perforate Menefee formation (correlate to GR log).

Menefee perforations, 2 spf:

To be determined from GR log

- 9. RIH with 2-7/8" frac string and 4-1/2" packer. Set packer at 4850'.
- 10. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule.
- 11. Flowback frac immediately.
- 12. Release packer and TOH with frac string and packer. LD frac string.
- 13. RU WL unit. RIH with 4-1/2" CIBP. Set CIBP at 4750'. Load hole with 2% KCL.
- 14. Run CBL log from 3800' 4750' to locate cement top for Lewis Shale frac job.
- 15. Pressure test casing to 1500 psi
- 16. RIH with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge. Perforate Lewis Shale formation (correlate to GR log).

Lewis Shale perforations, 2 spf:

To be determined from GR log

- 17. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 18. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule.
- 19. Flowback frac immediately.
- 20. TIH with tubing and bit. Cleanout fill and drill bridge plugs set at 4750' and 5200'. Cleanout fill to PBTD at 5527'. Blow well dry at PBTD.
- 21. Rabbit tubing and RIH with 2-3/8" production tubing.
- 22. Land 2-3/8" production tubing at 5350'.
- 23. ND BOP's. NU WH. Test well for air. Return well to production.

Vandewart A LS #4

Sec. 13 T29N R8W API#: 30-045-08404

