Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013  WELL API NO. 30-045-27340  5. Indicate Type of Lease STATE FEE  6. State Oil & Gas Lease No.					
District II	OIL CONSERVATION DIVISION						
	1220 South St. Francis Dr. Santa Fe, NM 87505						
1220 S. St. Francis Dr., Santa Fe, NM 87505							
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL S.)  PROPOSAL S.)	7. Lease Name or Unit Agreement Name  NEBU Pump Mesa SWD						
PROPOSALS.)  1. Type of Well: Oil Well G	8. Well Number 001						
2. Name of Operator SIMCOE LLC	9. OGRID Number 329736						
3. Address of Operator 1199 Main Ave., Suite 101	10. Pool name or Wildcat						
Durango, CO 81301	Morrison Bluff Entrada						
4. Well Location							
Unit LetterN:990	_feet from the _South line and1600feet	from theWestline					
Section 36	1 5	MPM San Juan County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6430'							
10 01 1							

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ⊠	PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	]		
TEMPORARILY ABANDON ☐	CHANGE PLANS	COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB			
DOWNHOLE COMMINGLE	NMOCD REC'D				
CLOSED-LOOP SYSTEM	7/10/20	_	_		
OTHER:	1710/20	OTHER:			

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The basis of this NOI is an increase in casing pressure observed on the NEBU Pump Mesa WDW 1.

On 2/25/20 BP noted 922 psi on the casing of this disposal well and shut down operations. Attempts to set a plug in the packer at 8032 (in order to test the tubing) were unsuccessful due to debris in the tubing. While casing pressure was blown down, tubing pressure was monitored. A correlation was apparent that the casing pressure source was from the tubing or a failed packer seal. A coiled tubing unit was used to (successfully) mill out debris inside the tubing on 5/20 so a plug could be set in the lower packer. With the plug set in the lower packer, integrity tests revealed communication between the tubing and casing but not across the packer. Debris in the tubing was identified as plastic lining, likely from the internally coated plastic tubing itself. Still with the plug set, both the casing and tubing pressures blew down to zero indicating a good lower packer seal. BP was unsuccessful in pulling the plug and in the process lost a retrieval tool (fish) on top of the plug and lost the pressure seal of the plug, bringing back pressure to both the tubing and casing. The well was identified as having a good lower packer seal, good casing integrity, a failed seal between tubing and upper packer, and a tubing string with deteriorated plastic lining.

In order to restore casing integrity, SIMCOE LLC (BP as contractor operator) proposes to remove both the upper and lower packers and replace with a single permanent packer designed for bottom hole conditions, primarily a temperature of 250 degrees F. Second, to replace the 3 ½" internally plastic coated tubing with 3 ½", J-55 plastic lined tubing. A general procedure is as follows

- 1 Rig up service unit
- 2 Perforate the tubing just above the upper packer at 8020' and circulate kill weight fluid, 12.3 ppg, to surface on both tubing and annulus
- 3 Remove the upper packer (Baker Hornet) at 8032
- 4 Remove the fish sitting on top of the lower packer at 8114
- 5 Remove the lower packer (Baker Lok Set) at 8114
- 6 Set a new permanent packer between the previous packer setting depths of 8032 and 8114, preferably to the deeper portion of the range
- 7 Circulate out kill weight fluid

- 8 Install new 3 ½", J-55 plastic lined tubing string and seal assembly, tie/seal into new permanent packer
- 9 Place packer fluid within the casing tubing annulus from 8110' to surface
- 10 Perform and chart a witnessed MIT to 500 psi on the casing tubing annulus
- 11 Rig down service unit
- 12 Return well to disposal

Contingency to perform remedial cement work if casing fails pressure test

At the time of this writing, BP as a contractor for SIMCOE LLC has performed the first 3 steps of this procedure.

Included is a proposed wellbore diagram, post workover.

Spud Date:	06/07/1990	Rig Rele	ase Date:				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE	Patricia Campbell Discn=Patricia Campbell Discn=Patricia Campbell email=Patricia Campbell Date: 2020.06.29 16:30:51 -06:00'		Regulatory Analyst	_DATE	6/29/2020_		
Type or print i	name Patti Campbell	E-mail add	lress: _patti.campbell@bpx.	com	PHONE:	970-712-5997	
For State Use  APPROVED I  Conditions of	Moura Violelina	TITLE_	Deputy oil & gas insp		DATE_	7/1/20	



