Form 3160-5 (August 2007)

determined that the site is ready for final inspection )

(Instruction on page 2)

## RECEIVED UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No 1004-0137

JUL 12 2012 BUREAU OF LAND MANAGEMENT Expires July 31, 2010 . Lease Serial No Farmington Field Office SF-077282 SUNDRY NOTICES AND REPORTS ON WELLER unof Land Nanagam Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7 If Unit of CA/Agreement, Name and/or No 1 Type of Well Oil Well X Gas Well Other 8 Well Name and No Grenier A 2R 2. Name of Operator 9 API Well No **Burlington Resources Oil & Gas Company LP** 30-045-30251 3a Address 3b Phone No. (include area code) 10 Field and Pool or Exploratory Area **Aztec Pictured Cliffs** (505) 326-9700 PO Box 4289, Farmington, NM 87499 4 Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11 Country or Parish, State **New Mexico** Surface Unit E (SWNW), 1440' FNL & 960' FWL, Sec. 34, T30N, R10W San Juan 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report New Construction Casing Repair Recomplete Other Change Plans X Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

Burlington Resources requests permission to P&A the subject well per the attached procedure, current and proposed schematics.

> Notify NMOCD 24 hrs prior to beginning operations

RCVD JUL 23'12 OIL CONS. DIV. DIST. 3

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)			
Dollie L. Busse	Title	Staff Regulatory Technician	
Signature Mittail Bussa	Date	7/12/12	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by			JUL 2 0 2017
Original Signed: Stephen Mason		Title	Date
Conditions of approval, if any, are attached Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which ventitle the applicant to conduct operations thereon		Office	
Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any false, fictitious or fraudulent statements or representations as to any matter within its juri	sdiction	MAAA	ment or agency of the United States any
77	0 2 5	# <b>ULD</b>	<del></del>

## ConocoPhillips GRENIER A 2R Expense - P&A

Lat 36° 46' 19.164" N

Long 107° 52' 36.732" W

## **PROCEDURE**

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. NU relief line.
- 2. Check casing and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and blow down casing pressure. Kill well with water, as necessary.
- 5. ND wellhead.
- 6. Open bradenhead valve. Establish rate down 2-7/8" casing with 20 bbls water, record pump rate and pressure. Monitor bradenhead for flow. If no flow or blow, then pump 7/8" RCN balls and additional water and monitor pressure, rate and volumes pumped to confirm perforations are taking water and there is not a casing leak. If the bradenhead flows water or there are other indications of a casing leak, then MO and RU pulling unit to use 1-1/4" integral joint (IJ) tubing workstring to plug this well.
- 7. Connect the pump line to the bradenhead valve. Load the BH annulus with water, note the volume. Pressure test the bradenhead annulus to 300#. If it tests, then continue to step 8. If the bradenhead annulus does not test, then set plug 1 in step 8 but displace to the appropriate depth with water down the 2-7/8" casing. After waiting on cement, perforate at the appropriate depth. Establish circulation to surface out the bradenhead valve. Then circulate cement to fill the BH annulus to the surface, circulate cement out the bradenhead valve, shut in the casing and wait on cement.

The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

- 8. Plug 1 (Pictured Cliffs perforations and Fruitland, Kirtland, Ojo Alamo tops, 0-2650', 97 Sacks Class B Cement)
  Establish rate into PC perforations with water. Mix and pump total of 97 sxs cement (long plug, 30% excess) and bullhead down the 2-7/8" casing. First pump 10 sxs cement, then drop RCN balls (the number needs to be calculated in field). Pump 87 sxs cement and do not displace. Double valve and shut in well. Wait on cement and tag.
- 9. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



