

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 28 2012

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

Farmington Field Office

SF-078863

SUNDRY NOTICES AND REPORTS ON WELLS of Land Management

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2 Name of Operator

ConocoPhillips Company

3a Address

PO Box 4289, Farmington, NM 87499

3b Phone No (include area code)

(505) 326-9700

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface

Unit P (SESE), 1025' FSL & 975' FEL, Sec. 33, T28N, R11W

5 Lease Serial No

63 If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8 Well Name and No

Krause WN Federal 4E

9. API Well No

30-045-24486

10 Field and Pool or Exploratory Area

Basin Dakota

11 Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones

Attach the bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once

Testing has been completed Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection)

ConocoPhillips requests permission to P&A the subject well per the attached procedure, current and proposed wellbore schematics.

RCVD SEP 4 '12
OIL CONS. DIV.
DIST. 3

Notify NMOCD 24 hrs
prior to beginning
operations

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Dollie L. Busse

Title Staff Regulatory Technician

Signature

Dollie L. Busse

Date

8/27/12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

AUG 29 2012

Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

Title 18 U.S.C Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

ConocoPhillips
KRAUSE WN FEDERAL 4E
Expense - P&A

Lat 36° 36' 51.012" N

Long 108° 0' 9.72" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1 Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2 MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3 When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4 RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5 ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.

Note: The Dakota perforation and formation top were isolated per the temporary abandon procedure dated 3/5/2012. The rig moved on the well on 8/1/2012 and set a CIBP @ 6099' on 8/2/2012. OCD requested a pressure test, and the test failed. The Dakota cement plug was pumped from 6099' to 5941'. On 8/3/2012, TOC was tagged @ 6047'. Attempted to pressure test casing, test failed. Plug #1A was mixed and pumped from 6047' to 5889'. A casing inspection log was run. **On 8/6/2012 TOC was tagged @ 5956' and attempted to pressure test again; the test failed.** The log was reviewed, and it was recommended to move from a TA of the Dakota formation to a P&A of the full wellbore. **Holes in the casing are suspected to be between 3700' and 4300' - not expected to pass pressure test before this point.**

- 6 TOH with tubing string (per pertinent data sheet - 5889' 2-3/8" tubing with plugging sub)

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

7. Plug 1 (Gallup, 5193-5293', 12 Sacks Class B Cement)

Pressure test tubing to 1000 psi. Load casing with water and attempt to establish circulation. Mix 12 sx Class B cement and spot a balanced cement plug inside the casing to isolate the Gallup formation top. PUH.

8. Plug 2 (Mancos, 4313-4413', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced cement plug inside the casing to isolate the Mancos formation top. POOH.

9. Plug 3 (Mesaverde, 3110-3210', 52 Sacks Class B Cement)

Perforate 3 HSC holes @ 3210'. Set a 4-1/2" cement retainer @ 3160'. Establish injection rate into squeeze holes. Mix 52 sx Class B cement. Squeeze 40 sx Class B cement into HSC holes and leave 12 sx inside the casing to isolate the Mesaverde formation top. POOH.

- 10 Pressure test the casing after Plug 3. If the casing passes the pressure test, run a CBL. If it does not pass the pressure test, pump the next plug and pressure test again. Continue to pump and pressure test until a successful test, then run a CBL.

11. Plug 4 (Chacra, 2512-2612', 12 Sacks Class B Cement)

Perforate 3 HSC holes @ 2612'. Set a 4-1/2" cement retainer @ 2562'. Establish injection rate into squeeze holes. Mix 52 sx Class B cement. Squeeze 40 sx Class B cement into HSC holes and leave 12 sx inside the casing to isolate the Chacra formation top. PUH.

12. Plug 5 (Pictured Cliffs, 1588-1688', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside the casing to isolate the Pictured Cliffs formation tops. PUH.

~~1403 1303~~

13. Plug 6 (Fruitland Coal, ~~1080-1480~~, 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside the casing to isolate the Fruitland Coal formation top. PUH.

~~694~~


14. Plug 7 (Ojo Alamo, Kirtland, ~~720-985~~, 24 Sacks Class B Cement)


Mix ~~24~~ sx Class B cement and spot a balanced plug inside the casing. PUH.

15. Plug 8 (Surface, 0-50', 45 Sacks Class B Cement)

Mix 45 sx Class B cement and spot a balanced plug inside the casing to surface. TOOH. Shut in well and WOC.

- 16 Nipple down BOP and cut off casing below the casing flange. Fill production/surface casing annulus with cement as necessary using poly pipe. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





**UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402**

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: 4E Krause WN Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
3. The following modifications to your plugging program are to be made:
 - a) Place the Fruitland plug from 1403' – 1303'.
 - b) Bring the top of the 8 5/8" Casing Shoe/Kirtland/Ojo Alamo plug to 694'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.