# Form 3160-5 (March 2012)

# RECEIVED

**UNITED STATES** DEPARTMENT OF THE INTERIOR

AUG 14 2012

FORM APPROVED OMB No. 1004-0137

	OIVID.	110 1007	-01.	,,
	Expires	October	31,	20
Serial No.				

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WETATRINGTON Field Office

SUNDRY NOTICES AND REPORTS ON WETATRINGTON FIEld OFFI

SUNDRY NOTICES AND REPORTS ON WETATRINGTON FIELD FIE

Do not use this for abandoned well.	orm for proposals to Use Form 3160-3 (A	o drill or $t\stackrel{>}{0}$ PD) for suc	re-enter and h proposals	d Manag	ement		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7 If Unit of CA/Agreement, Name and/or No			
1 Type of Well					w.=.	<u></u>	
✓ Oil Well ☐ Gas Well ☐ Other					8 Well Name and No CW Roberts #5		
2 Name of Operator Four Star Gas & Oil Company				9 API Well No 30-039-21295			
3a Address ATTN. Regulatory Specialist  3b Phone No			(include area code) 10 Field and Pool or Explorator				
332 Road 3100 Aztec New Mexico 87410		505-333-1941			39189 Lindrith Gallup		
4 Location of Well (Footage, Sec., T.) 1850' FNL 1650' FWL Sec 17, Twp 25N, Rr		)			11 County or Parish, Si Rio Arriba, New Mexi		
12 CHEC	K THE APPROPRIATE BO	X(ES) TO IND	CATE NATURE	OF NOTIC	E. REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION		E OF ACT	ION				
Notice of Intent	Acidize Alter Casing	Deepo	en ire Treat		iction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	_	Construction		mplete	Other Perforate and	
Final Abandonment Notice	Change Plans Convert to Injection	Plug a	and Abandon		orarily Abandon r Disposal	fracture	
Attach the Bond under which the w following completion of the involv testing has been completed. Final adtermined that the site is ready for 7/23/2012  Tbg press = 760 psi, Csg press = 80 test two 2-3/8" TIWs & two 2-7/8" TI 7/24/2012  SICP = 540 psi, SITP = 80 psi. Blow down well. RU floor. NU Clas workstring.  LD 255 jts 2-3/8" 4.7# J55 EUE. Ch 7/25/2012  SICP = 380 psi. Tally 2-7/8" workst Continue TIH w/ casing scrapper. L	ed operations If the operation Abandonment Notices must be final inspection.)  The property of	on results in a mode filed only after a 18 psi, bleed DB-1 adapter.  pipe, blind, & a for 2-7/8" ram,	ultiple completions all requirements  Bradenhead to annular 250 psi lossilps, & elevator arapper & start T	zero. RU flow, 1500 p	letion in a new interval, reclamation, have been downward line. Bleed good line in the sign of the sig	a Form 3160-4 must be filed once completed and the operator has as to flowback tank. Pressure	
Nee  14 I hereby certify that the foregoing is to	d Completion	Laport d/Typed)	3160-4 F	o, Mo	savida	****	
April E. Pohl		,	Title Regulator				
Signature April &	Poh/		Date 8/16	4/12	A	PRO FOR DECORA	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by						was 13 SMS	
******			Title		FARM	AGTON FIELD OFFICE	
Conditions of approval, if any, are attached that the applicant holds legal or equitable the entitle the applicant to conduct operations to conduct operations.	itle to those rights in the subject				N AMERICAN AND AND AND AND AND AND AND AND AND A	5	
Title 18 U S C Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any ne	rson knowingly an	d willfully to	make to any department	or agency of the United States any false	

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

#### 7/26/2012

SICP = 320 psi. Continue TIH & set RBP @ 6990'. Load 40 bbls of 2% KCL biocide water on plug, set packer. Would not pressure-up. Move plug up to 6973'. Load water on plug, set packer. Pressure test failed. Move plug to 6500'. Load water onto plug. Test failed, would not pressure-up.

TOH & break-out tools. No visible marks or damage of any kind on packer elements. Tools had gritty paraffin stuck in crevices.

# 7/27/2012

Multigas readings 20.9 oxygen, 0 H2S, 0 CO2, 0 LEL. Spot Poor Boys & take-on 60 bbls 2% biocide water. Spot & RU Poor Boys at well.

Hot Oil 7" casing 60 bbls @ 250 deg.

RIH w/ 7" CBP & set same @ 6980'. Fluid level detected @ 3200'. POOH.

Load hole from fluid level. Pressured to 500 psi. Allow air/water flip-flop.

RIH & pull Schlumberger CBL. RU WSI & test casing to 500 psi surface pressure. Rock solid chart. Perf MesaVerde w/ 4" HEGS guns 3 spf 5812-18, 5835-44, 5857-5890, 5933-36, & 5966-70'. Fifty-four feet of perfs over 158' interval. One hundred sixty-five 0.42" holes. RD Schlumberger.

Pressure test 3-1/2" pipe rams 250 psi low, 1500 psi high.

#### 7/28/2012

TIH w/ packer on 3-1/2", 9.3 # tubing. Continue TIH & set packer @ 5702'. Move-out racks & hydrawalk. RU frac valve / guide for stinger into tubing. RU stinger.

# 7/29/2012

RU HES. Pump & ball-off w/ acid.

Delta Frac well w/ 83,569 lbm ottowa 20/40 sand, Max treating pressure - 8055 psi. Average treating pressure - 7481 psi. Max wellhead rate ~ 37 bpm, Fluid to recover - 657 bbls. Final ISIP - 3818 psi. 5 min - 2136 psi. 10 min - 2003 psi. 15 min = 1912 psi.Annulus pressure started @ 100 psi. Max pressure ~ 450 psi. Annular pressure bled down with treating pressure.

RD HES. RD Stinger.

Finish RU WSI flowback.

Open well up @ 1700, 1400 psi, 10/64 choke flowing back nitrogen.

#### 7/30/2012

Flowback well.

#### 7/31/2012

RD flowback. RD frac valve & tubing hang-off (BO2 connector). Unseat packer. TOH LD 3-1/2" frac string. RD WSI flowback equipment and frac stack. Set-up HydraWalk & racks. RU both 3" lines to flowback.

Unseat Baker packer & TOH LD 3-1/2" tubing.

#### 8/1/2012

SICP = 120 psi. Change to 2-7/8" rams & pressure test 250 psi low / 1500 psi high. Tests good. Load-out 3-1/2" tbg to Oil Tool company. Replace seals on swivel.

MU junk mill &TIH. Continue in hole to 5040'. Hook-up air-foam unit and unload well. TIH to (5670') just above MesaVerde perfs (top perf 5812').

#### 8/2/2012

SICP = 440 psi. TIH to just above CBP, 6980'. Unload well w/ air-foam unit & blow down well. Establish circulation & drill CBP. Unload feed-in from Gallup & Dakota. Circulate sweep. Hang swivel. TOH to above MesaVerde.

#### 8/3/2012

SICP = 860 psi. Transfer 2% KCl water to rig's frac tank. Pull two loads of flowback.

Blow well down. Unload well from above MesaVerde. TIH & tag @ 8054'. Unload well from tag.

PU swivel. Establish circulation & drill 10' of hard fill. TOH to above MesaVerde perfs.

#### 8/6/2012

Check well, SICP - 960 psi, SITP - 0 psi, Open well to flowback tank RIH w/ mill, tag for fill at 8072 on 256 jts Start air, establish circulation, Built to 1000 psi then started unloading

Start mist at 12 bwph & 400 psi, Drlg, Made 4' in first 2 hrs recovering frac sand, small pieces of rubber, Broke thru @ 1200 hrs @ 8076', Cont cleaning out, Clean out well to 8146' (10' out on jt 259, very hard drlg at this pt,circ clean, recovering mostly frac sand, a few very small pieces of scale. SD air. LD one jt, rack swivel, POOH w/ 37 stnds 2 7/8 workstring to 5795'. Secure well, SDFN.

# 8/7/2012

Check well, SICP - 820 psi, SITP - 0 psi (string float), Open well to flowback tank
Caliper Elevators, RIH w/ 75 jts workstring, (Held BOP drill) Tag for fill @ 8138' 8' fill overnight
Start air, establish circulation, Built to 1150 psi before unloading, Unloaded 70 bbls w/ trace of oil

Start mist at 12 bwph, PSI falling to 350 psi, One 3 bbl sweep/hr, Washout fill to 8146, Drill/cleanout from 8146' to 8149 hard drilling, continue cleaning out to 8188' pipe measurement (PBTD@8168) recovering trace of oil, frac sand, scale and plug pieces. Did not tag a solid bottom. Circulate well off bttm, Pumping 2 - 3 bbl sweeps/hr, Recovering 1/2 to 1 cup frac sand per 5 gal sample, Last sample taken down to 1/4 cup/5 gallon sample SD air, Rack back swivel, POOH w/ 76 jts to above Mesaverde perfs, Secure well, SDFN.

# 8/8/2012

Check well, SICP - 760 psi, SITP - 0 psi (string float)Open well to flowback tank and bleed down. RIH w/ 2.7/8" workstring, Tag for fill @ 8175' (13' fill overnight)

Start air, establish circulation. Built to 1000 psi.

Start mist @ 13 bwph, wash out fill @ 375 psi to 8188' pipe meas, recover frac sand, pump sweeps Samples show just a trace of sand, SD air, POOH, LD 2 7/8" workstring Offload 1/2 of prod pipe, load and sent 1/2 of workstring out. Secure well, SDFN.

### 8/9/2012

Check well, SICP - 720 psi. Open well to flowback tank.

PU 2 3/8" elevators and caliper same. Change out pipe rams to 2 3/8", PU and install hangar, Test rams to 250/1500 psi. Test good.

Take delivery of remaining 2 3/8" prod tbg, Load out remaining 2 7/8" workstring and returned. Tally Pipe

PU & RIH w/ Muleshoe, SN, 2 3/8 L80 tbg

Continue in hole w/ 2 3/8 prod tbg

Load remaining 2 3/8 tbg to racks, tally same

Cont in hole w/ 2 3/8 prod tbg, PU Hangar and land same. Total of Muleshoe(32), SN(1.10), 75 jts 2 3/8 4.7# L80 8rd EUE(2378.02), TAC(2.80), 2 jts(63.55), 4' pup(4.15), 176 jts((5584.23), 4' pup(4.12), 8' pup(8.16), 10' pup(10.10), 1 jt (31.76), Hangar(0.68), 254 jts total + muleshoe, EOT - 8134.67, SN - 8102.67

RD Tongs, floor, ND annulars, ND BOP's

PU on hangar, set slips, Remove Hangar, Attempt to set TAC in tension, tried numerous times. Would not set. Install and land hangar, Left anchor unset, NU WH, Test void to 1500 psi. Secure well, SDFN.

# 8/10/2012

Check well, SICP - 700 psi. SITP - 0 psi. Open well to flowback tank.

PU and RIH w/  $2" \times 1 \, 1/4 \times 18$  RHAC pump w/ strainer nipple , and shear tool,  $4' \times 7/8"$  stabilizer bar, RIH in singles w/ 3/4" rods

Continue in hole w/ new 7/8, 3/4 rod string. Total of 18' RHAC pump, 2' x 3/4 pony w/ shear tool, 7/8" x 4' stabilizer bar, 213 - 3/4" x 25' rods, 109 - 7/8" x 25 rods, Space out w/ 2', 4', 6' & 8' x 7/8" pony rods, 1 1/4" x 26' PR

Load -test tbg to 500 psi, Test good, Check pump action w/ rig to 500 psi, Test good. Clamp off well. RDMO.



# **Wellbore Schematic**

Well Name Lease Field Name Business Unit CW Roberts 05 Roberts, C W Basin(New Mexico) Mid-Continent/Alaska

