Form 3160-5 (August 2007)

RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires July 31, 2010

		5	Lease	Serial	N
_		-			

		Farmin	gton Field (5 Lease Serial No.	IM-02294		
SUN	IDRY NOTICES AND REPO						
Do not us	e this form for proposals (well. Use Form 3160-3 (A	to drill or to re-en	ter an				
SU	JBMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, Name and/or No					
1 Type of Well							
Oil Well	X Gas Well Other			8 Well Name and No Whitley 10			
2. Name of Operator			· -	9 API Well No	Tritley 10		
	ton Resources Oil & Gas				045-20720		
PO Box 4289, Farmingt		3b Phone No. (include a (505) 326-	•	10 Field and Pool or Exploratory Area Basin Fruitland Coal			
4. Location of Well (Footage, Sec., T.,R Surface Unit E (S	R.,M., or Survey Description) WNW), 1850' FNL & 850' F	WL, Sec. 17, T271	N, R9W	Country or Parish, State San Juan , New Mexico			
12. CHECK 1	THE APPROPRIATE BOX(ES)	TO INDICATE NATI	URE OF NOT	TCE, REPORT OR OTH	ER DATA		
TYPE OF SUBMISSION		TY	PE OF AC	ΓΙΟΝ			
Notice of Intent	Acıdize	Deepen	Pı	oduction (Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat		eclamation	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	R	ecomplete	Other		
\mathcal{B}^{C}	Change Plans	X Plug and Abandon	T To	emporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	🔲 w	ater Disposal	<u> </u>		
determined that the site is ready for	Abandonment Notices must be filed or final inspection) &A'd on 9/11/12 per the att				RCVD OCT 4'12 OIL CONS. DIV. DIST. 3		
14 I hereby certify that the foregoing is Dollie L. Busse	J. Busse	Title St	10/1	ry Technician	RECOR RECOR		
	THIS SPACE FO	R FEDERAL OR S	TALE OFF	CE USE			
Approved by				OCT 0 2 2012			
			Title	F.A F-2	EN 1- PAIR I		
Conditions of approval, if any, are attach	ed Approval of this notice does not v	varrant or certify		। इ.स.च्या	MUTUATIELD OFFICE		

Title 18 U S C. Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon

that the applicant holds legal or equitable title to those rights in the subject lease which would

Office

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources Whitley #10

September 11, 2012 Page 1 of 1

1850' FNL and 850' FWL, Section 17, T-27-N, R-9-W San Juan County, NM Lease Number: NM-02294 API #30-045-20720

Plug and Abandonment Report Notified NMOCD and BLM on 9/5/12

Plug and Abandonment Summary:

- Plug #1 with 24 sxs (28.32 cf) Class B cement inside casing from 2192' to 2016' to cover the Fruitland perforations.
- Plug #2 with 120 sxs (141.6 cf) Class B cement inside casing from 1616' to 1267' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with 121 sxs (142.78 cf) Class B cement from 359' to surface to cover the surface casing shoe.
- Plug #4 with 32 sxs to fill the 4.5" casing and install P&A marker.

Plugging Work Details:

- 9/6/12 MOL and RU. Monitor wellhead while waiting on Downhole Expert. ND part of wellhead. SI well. SDFD.
- 9/7/12 Check well pressures: tubing 90 PSI, casing 90 PSI and bradenhead 0 PSI. Pump 20 bbls down tubing to kill well. ND wellhead and NU BOP. LD tubing hanger 1 joint, 1-6' 1-8' 2- 3/8 sub. POH and tally 36 stands, 74 joints to 2311'. TIH with 4.5" A-Plus watermelon mill and 36 stands, EOT 2254'. LD 35 stands and mill. TIH with 4.5, CR tubing jumped and CR set at 442'. PU 1-4.5" watermelon mill with 3-7/8" twister bit. TIH with 7 stands and tag CR. Unable to beat CR down. POH and LD mill. SI well. SDFD.
- 9/10/12 Check well pressures: casing 10 PSI and bradenhead 0 PSI. TIH with 3 stands and tag CR at 442'. RU swivel and tag at 442. Establish circulation. Drill out CR. TIH with tubing to 2250'. POH and LD BHA. TIH with CR and set at 2192'. Circulate well clean. Pressure test casing to 800 PSI, OK. Spot plug #1. LD 20 joints, SB 25 stands. SI well. SDFD.
- 9/11/12 Open up well; no pressures. Tag cement at 1956'. Perforate 3 HSC holes at 1616'. TIH with CR and set at 1570'. Spot plug #2. LD all tubing and setting tool. TIH with drill collars and LD 6 3-1/8" drill collars. Perforate 3 HSC holes at 359'. Establish circulation out bradenhead. Spot plug #3. ND BOP. Dig out wellhead. Monitor well. Issue Hot Work Permit. Cut wellhead. Cement and fill 4' in 4.5" annulus and install P& A marker. RD & MOL.

Val Jamerson, BLM representative, was on location. Jim Yates, COPC representative, was on location.