

PN

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505


WELL API NO. 30-045-07620
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name New Mexico Com A
8. Well Number 1
9. OGRID Number 131994
10. Pool name or Wildcat Basin Fruitland Coal/ Blanco P.C. South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well Gas Well Other

2. Name of Operator
Four Star Oil & Gas Company

3. Address of Operator
11111 S. Wilcrest Houston, Texas 77099



4. Well Location
Aztec PC

Unit Letter P : 900 feet from the South line and 890 feet from the East line

Section 32 Township 29N Range 10W NMPM San Juan County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
5579' DR

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type: Depth to Groundwater Distance from nearest fresh water well

Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Four Star Oil & Gas Company has completed the plugging and abandoning the subject well effective July 8, 2004. The well was plugged as follows:

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Kenneth W. Jackson TITLE Regulatory Specialist DATE 07/14/04

Type or print name Kenneth W. Jackson E-mail address: Telephone No. (281) 561-4991

(This space for State use)

APPROVED BY A. Villanueva TITLE STAFF OIL & GAS INSPECTOR, DIST. 03 DATE MAY 3 2005

Conditions of approval, if any: 5-3-05.

July 6, 2004 MIRU ND wellhead NU BOP., 4 1/2" casing rotted at surface. POOH with tubing and laid down. PU 4 1/2" CIBP, 2 3/8" tubing to 1885' and set. Load hole with water.

July 7, 2004 Cut off 8 5/8" stub/bonnet, cut and dress 4 1/2" top. Welded on new 4 1/2", and 101/2" ppf stub w/ 2" circ valves. NU and test casing to 500 psi. Tested good.

July 8, 2004 RU Schumberger cmt. Load hole and pressure test lines to 500 psi. Mix 18 sks Class "G" cmt and spotted from 1885' to 1650'. Pooh and lay down tubing. RU Schlumberger W/L and shot two (2) holes @ 970'. Break circ down 4 1/2" csg and circ out bradenhead. Run Halco cement retainer to 920 feet and set. Mix and pump 150 sx (30bbls) Class "G" neat. Circ cmt to surface out Bradenhead. Pull BOP. POOH with setting tool. RIH to 150'. Mix and pump 10 sx to surface. POOH. RD & MOL. Erect P&A marker and clean up location.