RECEIVED

INITED STATES

rom 3100- 3		ONIT	CDSTATES		· ·	PORM AFFROVED			
(August 2007)		DEPARTMENT	OF THE INTERIOR	00T a= 10	4h	OMB No. 1004-0137			
			AND MANAGEMENT	OCT 25 20	IK.	Expires: July 31,2010			
		Deliance of Li			5. Lease Serial N	No.			
	SI	JNDRY NOTICES A	IND REPORTS ON V	VELLSaton Field					
			roposals to drill or to re-						
			3160-3 (APD) for such pi		1 -	Apache Tribe			
	SUBMIT II	N TRIPLICATE - Othe	r Instructions on page 2).		Agreement Name and/or No.			
1. Type of Well Oil Well	√ Gas Well	Other			8. Well Name an	d No.			
2. Name of Operator					Jicarilla .	460-16 #5			
Black Hills G	as Resourc	es. Inc.			9. API Well No.				
3a. Address			3b. Phone No. (include	area code)	30-039-2	30-039-25864			
3200 N 1st St,	Bloomfield	i, NM 87413	(505) 634-51	•	10. Field and Po	ol, or Exploratory Area			
		R., M., or Survey Description)			Cabresto	Canyon Tert.			
		Sec. 16 T30N R3W				11. County or Parish, State			
					Rio Arril	ba County, New Mexic	0		
12. CH	ECK APPRO	OPRIATE BOX(S) TO I	NDICATE NATURE OF	NOTICE, REPORT,					
TYPE OF SUBM	ISSION			TYPE OF ACTION			-		
[7]									
Notice of Intent		Acidize	Deepen	Production (Start/ Resume)	Water Shut-off			
7		Altering Casing	Fracture Treat	Reclamation		Well Integrity			
Subsequent Rep	ort	Casing Repair	New Construction	Recomplete		Other			
	20	Change Plans	Plug and abandon	Temporarily	Abandon				
	DE I		=						
Final Abandonn		Convert to Injection	Plug back	Water Dispo					
If the proposal is to d Attach the Bond und following completion	eepen directions er which the wor of the involved pleted. Final Abs	Ily or recomplete horizontally, k will performed or provide the operations. If the operation res- andonment Notice shall be filed	t details including estimated start give subsurface locations and me Bond No. on file with the BLM ults in a multiple completion or re only after all requirements, inclu	asured and true vertical dep BIA. Required subsequent ecompletion in a new interv	oths of all pertinent no reports shall be filed al, a Form 3160-4 sl	narkers and zones. d within 30 days hall be filed once			
Black Hills	Gas Resou	arces intends to plug	and abandon Jicarilla	ı 460-16 #5 per att	ached proced	ure.			
						RCVD NOV 1'1	2		
			•			OIL CONS. DIV			
					,	DIST. 3	•		
						ט . וכנט			
		•	•						

14. I hereby certif	y that the foregoing is true and correct. Name (Printed/ Typed)		
Daniel M		Regulatory Techician	
Signature	Taniel Many	Date Oct 25,20	1/2
7	(THIS SPACE FOR	FEDERAL OR STATE OFFICE U	JSE
Approved by	Original Signed: Stephen Mason	Title	Date OCT 1 0 2012
that the applicant he	oval, if any are attached. Approval of this notice does not warrant or colds legal or equitable title to those rights in the subject lease which vertice to conduct operations thereon.		
	tion 1001 AND Title 43 U.S.C. Section 1212, make it a crime for an		department or agency of the United States any false,

(Instructions on page 2)



PLUG AND ABANDONMENT PROCEDURE

October 18, 2012

Jicarilla 460-16 #5

Cabresto Canyon; Ojo Al	lamo Ext./ San Jose Ext.	
1039' FSL, 1840' FEL, Section 16, T	Γ30N, R3W, Rio Arriba Count	ty, NM
API 30-039-25864 / Long:	/ Lat:	_

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- 1. This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
 regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
 location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
 Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND
 wellhead and NU BOP. Function test BOP.

3.	Rods:	Yes_	<u>X</u> .	, No_	, Unknown	•		•		
					, Unknown	, Size	2-3/8"	, Length _	3107'	<u> </u>
	Packer:	Yes	_X	_,	, Unknown	Туре	AS-1Xrema	aining pieces	to be m	illed out

If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

NOTE: Fish in hole. Bottom part of AS-1X pkr. TOF at 3129'. PU drill collars, workstring and washover mill with air package and drill out packer at 3129'. Circulate well clean. Round trip 5.5" gauge ring to 3264'.

NOTE: Black Hills will handle getting air package and necessary equipment to drill out packer. Supervisor will need to coordinate with Leslie Lam at Black Hills prior to MOL.

- 4. Plug #1 (Pictured Cliffs, Fruitland and Kirtland tops, 3902' 3496'): Mix 52 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs, Fruitland and Kirtland tops. Note: this plug may be modified on location based on success of drilling out packer.
- 5. Plug #2 (Ojo Alamo perforations and top, 3359' 3214'): TIH and set 5.5" CR at 3264'. Mix 44 sxs Class B cement. Squeeze 32 sxs below CR, pumping 20 sxs into Ojo Alamo perforations and leaving 12 sxs inside casing below CR then sting out of CR and leave 12 sxs above. PUH with tubing.

2164 2064

- 6. Plug #3 (Nacimiento top, 2127' 2027'): Mix 17 sxs Class B cement and spot a balanced plug inside the casing to cover the Nacimiento top. TOH.
- 7. Plug #4 (San Jose perforations, 1642' 1542'): TIH and set 5.5" CR or CIBP at 1642'. Mix 17 sxs Class B cement and spot a balanced plug inside the casing above the CR to isolate the San Jose perforations. PUH.

Jicarilla 460-16 #5

Current

Cabresto Canyon; Ojo Alamo Ext./San Jose Ext.
_____/ Lat: _____/ API 30-039-25864

1039' FSL & 1840' FEL, Section 16, T-30-N, R-3-W, Rio Arriba County, NM

TOC @ Surface per Sundry Today's Date: 10/18/12 and Completion report Spud: 6/10/98 12-1/4" Hole OA Comp: 7/22/98 SJ Comp: 10/13/98 8-5/8" 24#, K-55 Casing set @ 537' Cement with 300 sxs, circulated 42 sx to Elevation: 7324' GI 7336' KB surface San Jose @ 0' San Jose Perforations: 1692' - 2056' 2-3/8" tubing at 3107" Nacimiento @ 2077' (101 jts, SN, Perf Sub and rods with pump) Fish in hole: bottom part of AS-1X pkr. TOF at 3129'. Numerous attempts to fish packer from 1/20/01 to 1/26/01 Ojo Alamo @ 3308' Ojo Alamo Perforations: 3314' - 3359' Kirtland @ 3546' Fruitland @ 3746' Pictured Cliffs @ 3852' 7-7/8" Hole 5.5" 15.5#, K-55 Casing @ 4093' Cement with 600 sxs, circulated 105 sxs to surface

4115' TD 3950' PBTD

Jicarilla 460-16 #5 Proposed P&A

Cabresto Canyon; Ojo Alamo Ext./San Jose Ext. __/ Lat: __ _/ API 30-039-25864

1039' FSL & 1840' FEL, Section 16, T-30-N, R-3-W, Rio Arriba County, NM

Today's Date: 10/18/12

Spud: 6/10/98

OA Comp: 7/22/98

SJ Comp: 10/13/98 Elevation: 7324' GI

7336' KB

12-1/4" Hole

San Jose @ 0'

Nacimiento @ 2077'


Ojo Alamo @ 3308'

Kirtland @ 3546'

Fruitland @ 3746'

Pictured Cliffs @ 3852'

7-7/8" Hole



TOC @ Surface per Sundry and Completion report

8-5/8" 24#, K-55 Casing set @ 537' Cement with 300 sxs, circulated 42 sx to surface

Plug #5: 587' - 0' Class B cement, 70 sxs

Plug #4: 1642' - 1542'

Set CR @ 1642'

Class B cement, 17 sxs

San Jose Perforations: 1692' - 2056'

> Plug #3: 2127' - 2027' Class B cement, 17 sxs

Set CR @ 3264'

Ojo Alamo Perforations: 3314' - 3359'

Plug #2: 3359' - 3214' Class B cement, 44 sxs: 12 sxs below CR and 20 sxs into OA perforations. leave 12 sxs above CR

Plug #1: 3902' - 3496' Class B cement, 52 sxs

5.5" 15.5#, K-55 Casing @ 4093' Cement with 600 sxs, circulated 105 sxs to surface

4115' TD 3950' PBTD

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 5 Jicarilla 460-16

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Nacimiento plug from 2164' 2064'.
- b) You are required to have H2S monitoring equipment and personnel on location during plugging operations.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.