For/n 3160-5 (August 1999)

UNITED STATES

John C. Thompson

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Signature

A walker between

Approved by

RECEIVED

FORM APPROVED OMB No. 1004-0135 Expires Jnovember 30, 2000

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NOV 28 2012

Jicarilla Apache Lease #424

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill-pinter the distribution of the abandoned well. Use Form 3160-3 (APD) for such reposals Manageme

6. If Indian, Allottee or Tribe Name

Jicarilla Apache Nation

Lease Serial No.

	LICATE = Other instru	ctions on reverse	e side	7. If Out of C7.	Agreement, N	ine and/or iv
Type of Well	25-35-20-23-20-23-20-20-20-20-20-20-20-20-20-20-20-20-20-	A the "a receiptor of a	and the second s			
Oil Well Gas Well Other				8. Well Name and No.		
2. Name of Operator				Logos #2		
Logos Capital Management, LLC				9. API Well No.		
3a. Address		3b. Phone No. (include area code)		30-04 3 -21120		
7415 East Main, Farmington, NM		l			10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Basin Dakota	3	
1930' FSL & 730' FEL Section 6, T22N, R5W			11. County or Parish, State			
		Sandoval C				
12. CHECK APPRO	OPRIATE BOX(ES) TO IN	NDICATE NATURE	OF NOTICE, RI	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamat	on (Start/Resume)	Water Shut	
Subsequent Report	Casing Repair Change Plans	New Constructi	on 🔲 Recomple		Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Di	•		
13. Describe Proposed or Completed Oper If the proposal is to deepen direction. Attach the Bond under which the wo Following completion of the involved Testing has been completed. Final A determined that the site is ready for final	operations. If the operation resu Abandonment Notices shall be fil	details, including estima ive subsurface locations the Bond No. on file wi alts in a multiple comple led only after all require	led starting date of a and measured and tru th BLM/BIA. Requi tion or recompletion i ments, including reck	ny proposed work and le vertical depths of al ired subsequent reports in a new interval, a Fo amation, have been co	approximate dur l pertinent marke shall be filed w rm 3160-4 shall impleted, and the	ation thereof. rs and zones. ithin 30 days be filed once operator has
Ran 159 jts of 5-1/2", 17#, P11 tool at 2557' KB. Bump plug o						
plug on 2nd stage to 1120 psi -						
pressure up to 2150 psi to close						
Rig released at 00:00 hrs 10/6/2	2012.				•	
See attachment for 3 stage cem	ent details.		•		•	RCVD NOV 29'12 OIL CONS. DIV.
* O	sq pressure	test on	the com	pletion	report	DIST. 3
14. I hereby certify that the foregoing						
Name (Printed/Typed)		Title				

Quend form to include Hole Size, TD & date TD 1

Date

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States Sections or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE USE

Title

Agent / Engineer

October 15, 2012

Date

FARMING YOU FILE

Logos #2 – production casing/cement sundry (attachment)

1 stage: Precede cement w/ 10 bbl water, 20 bbls of mud clean & 5 bbl water pace. Mix & pump 100 sx (198 cf) of Premium Lite w/ 0.25#/sk Cello-Flake, 0.2% CD-32, 0.2% FL-52A. Tail in w/ 250 sx (345 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello-Flake, 0.2% FL-52A. Good circulation throughout job. Pump slurry at 5 bpm. Drop plug & displace cement w/ 112 bbls of water & 41.3.5 bbls of mud (total displacement: 153.4 bbls). PD at 20:30 hrs 10/5/2012. Bump plug to 2000 psi (held pressure ok) – release pressure to check floats, holding OK. Increase pressure & open 1st DV tool at 2300 psi. Circulate off top of 1st DV tool. Continue pumping and *circulate out 30 bbls of good cement to surface*. Switch over to rig pump and circulate for 4 hrs – good returns entire time.

2nd stage: Precede cement w/ 10 bbls water & 10 bbls of mud clean. Mix & pump 100 sx (209 cf) of Premium Lite, 1% CaCl2, 5#/sk LCM-1, 8% Bentonite. Tail in w/ 226 sx (312 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello Flake, 0.2% FL-52. Drop plug & displace cement w/ 54 bbls of water & 50 bbls of mud (total displacement: 104 bbls). PD at 03:00 hrs 10/6/2012. Bump plug to 1200 psi (close 1st DV tool) – holding pressure OK. Release pressure to check float, held OK. Open cement head & drop dart. Hesitate for 15 mins. Pressure up on 2nd DV tool, opened at 1030 psi. Circulate off top of 2nd DV tool. Continue pumping and *circulate out 30 bbls of good cement to surface*. Switch over to rig pump & circulate for 4 hrs – good returns entire time.

3rd stage. Precede cement w/ 10 bbls water & 10 bbls of mud clean. Mix & pump 250 sx (532 cf) of Premium Lite w/ 3% CaCl2, 0.25 #/sk Cello-Flake, 5#/sk LCM-1, 8% Bentonite, 0.4% Sodium Metasilicate, 0.4% FL-52A. Tail in w/ 150 sx (204 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello Flake, 0.2% FL-52. Pump slurry at 5 bpm. Drop plug & displace cement w/ 59.3 bbls of water. PD at 09:00 hrs 10/6/2012. Bump plug to 2150 psi (close 2nd DV tool) — holding pressure OK. Release pressure to check float, held OK. *Circulated 50 bbls of good cement to surface*.