Form 3160-5 UNITED STATES (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NOV 19 2017 SUNDRY NOTICES AND REPORTS ON WELLS		OMB I Expires 5. Lease Serial No. NM	NMSF-080180-A	
Do not this form for proposals Farmingtorabandoned well. Use Form 3160-3 (to drill or to re-enter an	6. If Indian, Allottee or Tribe	3 Name	
Bureau of Lailu Wallags SUBMIT IN TRIPLICATE - Other instructions on page 2.		7. If Unit of CA/Agreement,	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well		Sar	San Juan 30-6 Unit	
Oil Well X Gas Well Other			San Juan 30-6 Unit 441S	
2. Name of Operator Burlington Resources Oil & Gas Company LP			9. API Well No. 30-039-27643	
3a. Address 3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499	(505) 326-9700	Basin Fruitland Coal		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit I (NESE), 1840' FSL & 1255' FEL, Sec. 31, T30N, R6W		11. Country or Parish, State Rio Arriba	, New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF	NOTICE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION TYPE OF ACTION				
X Notice of Intent Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
\	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report Casing Repair	New Construction	Recomplete	Other	
Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice Convert to Injection	Plug Back	Water Disposal		
Attach the bond under which the work will be performed or provide the following completion of the involved operations. If the operation resul Testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection.) Burlington Resources requests permission to Powellbore schematics. **Add incide PC Plus from	ts in a multiple completion or recomp d only after all requirements, including &A the subject well per th	letion in a new interval, a Form 310 g reclamation, have been completed attached procedure, c	60-4 must be filed once d and the operator has	
wood was ac bus			RCVD NOV 26 '12	
	Notify NMOCD 24 prior to beginni	hrs ng	OIL CONS. DIV.	
+	operations		DIST. 3	
14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Ty</i>	ped)			
Dollie L. Busse	Title Staff Regu	Title Staff Regulatory Technician		
Signature Milli Cussu	Date ///	119/10		
THIS SPACE FO	OR FEDERAL OR STATE (OFFICE USE		
Approved by			unit a a oo	
Original Signed: Stephen Mason	POT A		MOV 2 0 20	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Title

Office

ConocoPhillips SAN JUAN 30-6 UNIT 441S Expense - P&A

Lat 36° 46' 1.441" N

Long 107° 29' 55.979" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Unseat pump, kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. TOOH with 3/4" rods; LD rods.
- 6. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.
- 7. TOOH with 2-3/8", 4.7#, J-55, EUE tubing (per pertinent data sheet).

 Rods:
 Yes
 Size:
 3/4"
 Length:
 3738"

 Tubing:
 Yes
 Size:
 2-3/8"
 Length:
 3759"

Round trip 7" casing scraper top of liner (3485') or as deep as possible.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk vield. Per CBL, cement volumes may change.

8. Plug 1 (Fruitland formation top, Open Hole, Intermediate Shoe, Liner Top, 3245-3440', 48 Sacks Class B Cement)
RIH and set CR for 7", 20#, J-55 casing at 3440'. Load casing and circulate clean. Pressure test tubing to 1000 psi. Pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. Run CBL from 3245' to surface. Mix 48 sx of Class B cement and spot plug inside casing to isolate the Fruitland formation top, open hole, intermediate shoe and liner top. PUH.

3014 2684

9. Plug 2 (Ojo Alamo and Kirtland formation tops, 2785-3667', 55' Sacks Class B Cement)

Mix 56 sx Class B cement and spot balance plug inside casing to isolate the Ojo Alamo and Kirtland formation tops. PUH


10. Plug 3 (Nacimiento formation top, 1610-1710', 29 Sacks Class B Cement)


Mix 29 sx Class B cement and spot balance plug inside casing to isolate the Nacimiento formation to. PUH

11. Plug 4 (Surface Shoe, 0-183', 45 Sacks Class B Cement)

Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 45 sx cement and spot a balanced plug inside casing from 183' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 183' and the annulus from the squeeze holes to surface. Shut in well and WOC.

12. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 441S San Juan 30-6 Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Kirtland/Ojo Alamo plug from 3014' 2684'.
- b) Place the Nacimiento plug from 1551'- 1451'.
- c) You are required to have H2S monitoring equipment and personnel on location during plugging operations.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.