Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE - Other instructions on page 2.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

RECEIVED

JAN 24 20

FURWI APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WEILES MINGS OF LAND MAN Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an Wan in the Name of Land Wan in th abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMSF079600

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well							
Oil Well Gas Well Other					8. Well Name and No. CW Roberts #3A		
2. Name of Operator Four Star Gas & Oil Company					9. API Well No. 30-039-22732		
3a. Address 3b. Phone No. (include area cod				?)	10. Field and Pool or Exploratory Area		
ATTN: Regulatory Specialist 332 Road 3100 Aztec New Mexico 87410	505-333-1941	Lindrith Gallup			ota West/Blanco Mesaverde		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
1650 FSL 810 FWL L-18-25N-03W Lot: 3					Rio Arriba County, New Mexico		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDIC	ATE NATURE	OF NOTIC	CE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize	Deepen Deepen	Deepen Prod			uction (Start/Resume) Water Shut-Off	
	Alter Casing	Fracture	Treat	Recla	amation	Well Integrity	
Subsequent Report	Casing Repair	New Co	nstruction	Reco	omplete .	Other Artificial lift revision	
Subsequent Report	Change Plans	Plug an	d Abandon	Temp	porarily Abandon	tubing repair	
Final Abandonment Notice	Convert to Injection	Plug Ba	ck	Wate	er Disposal		
Attach the Bond under which the w following completion of the involv testing has been completed. Final determined that the site is ready for 1/3/2013	ed operations. If the operati Abandonment Notices must	on results in a mu	tiple completion	or recomp	letion in a new interva	l, a Form 3160-4 must be filed once	
MIRU.							
1/4/2013 Check well pres. SITP 0 psi SICP 24 NDWH. NUBOP. Attempt to test ar Work tbg. up to 68,000# and hanger 7970' (38' fill). POOH L/D 8 jts. 2 3	nnular. Full test BOP 220 r came free. Pull up & tak	0 psi high 250 ps e hanger off. P/	ii low. J 8 jts. 2 3/8" V	VS. RIH 8	& tag @ 7932' if prod	l. tbg. Btm. perf. @ 7930' PBTD @	
1/7/2013 POOH with production tubing had 1: POOH with 60 joints of 2 3/8" tubing				o. SWIFN.	OIL CO	NS. DIV DIST. 3	
See attached pages for remainder of procedure and well bore diagram.							
					JA	N 3 0 2013	
					•		
14. I hereby certify that the foregoing is to	rue and correct. Name (Printe	ed/Typed)	·····				
April E. Pohl	E. Pohl Title Regulatory Specia				ist		
Signature April E Pohl Date Ganuary 23, 2013							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by					JAN ZU ZUD		
			Title			Date ARMINGTON FIELD OFFICE	
Conditions of approval, if any, are attached that the applicant holds legal or equitable tentitle the applicant to conduct operations	itle to those rights in the subje		tify			BY	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it	a crime for any per	on knowingly and	d willfully t	to make to any departme	ent or agency of the United States any false,	

NMOCDA

1/8/2013

Started RIH with 4 3/4" bit and bit sub, and tubing float. RIH with 150 joints EOT at 4743 FT. SWIFN.

1/9/2013

RIH with tagged at 7944 FT, unloaded well @ 1650 PSI, Circulating at 600 PSI, cleaned out to 7965 FT, circulated clean.

POOH LD one joints and power swivel, POOH and racked back 44 STDs. SWIFN.

1/10/2013

POOH with tubing and PU tubing scrapper. PU and RIH with tubing scrapper to 7928 FT. POOH with work string and scrapper and LD work string. EOT at 4733 FT. SWIFN.

1/14/2013

Finish RIH with production tubing to 7940 FT, RIH with cap string to ~400 FT, Land hanger, ND BOPs, NU well head.

RD rig floor and ND BOPs and set tubing anchor pulled 15-K into tubing, NU well head, SWIFN.

1/16/2013

RU equipment and PU pump (7.91 FT gas anchor,18 FT pump, 5.8 Rod pup) and 202 joints 3/4" rods, 114 joints 7/8" rods, spaced out the pups (8-4 Ft), Tested pump to 500 psi for 10 minutes, good test. SWIFN.

1/17/2013

RDMO.



Wellbore Schematic

