		RE	CEIVE		• •	
	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN	s INTERIOR	EC 18 2012	FORM A OM B No. Expires: M	PPROVED 1004-0137 Jarch 31, 2007	
				5. Lease Serial No. NOO-C-14-20-41	58	
	NOTICES AND REI is form for proposals I ell. Use Form 3160-3 (ice 6. If Indian, Allottee o Navajo	or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					ement, Name and/or No.	
I. Type of Well Oil Well□ □ □ Gas Well□□				8. Well Name and No	8. Well Name and No.	
2. Name of Operator Nacodgoches Oil & Gas Inc.				Navajo #32-2 9. API Well No.		
3a Address 816 North Street, Nacogdoches TX. 75961		3b. Phone No. (include area code) 936-560-4747		30-045-24945	Evaloration Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Exploratory Area	
1050' FNL & 1610' FEL, Section 32 27N 19W				11. County or Parish,		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,				San Juan County, NM		
	PROPRIATE BOX(ES) TO				. DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen Fracture Treat	Production	(er Shut-Off I Integrity	
	Casing Repair	New Constructi	r1			
Final Abandonment Notice	Change Plans	Plug and Aband Plug Back	on Temporarily		· .	
determined that the site is ready	ic. completed the plugging on				RCVD FEB 26 '13 OIL CONS. DIV. DIST. 3	
					. ·	
				·		
14. I hereby certify that the forepoint of the forepoi	going is true and correct	Title	e Engineer			
Signature Stee Tran,	۲ ۵	Dat	;	12/15/2012		
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FOR	FEDERAL OF	R STATE OFFIC	CE USE		
Approved by	•		Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudul	43 U.S.C. Section 1212 make it a	crime for any perso as to any matter with	n knowingly and willfu in its jurisdiction.	illy to make to any department	it or agency of the United	
(Instructions on page 2)					DECTION	
				PARMENO	RONPHELDOFFICE	
1				Fif	All and a second s	

.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Nacogdoches Oil & Gas Inc. Navajo #32-2 October 31, 2012 Page 1 of 2

1050' FNL and 1610' FEL, Section 32, T-27-N, R-19-W San Juan County, NM Lease Number: NOO-C-14-20-4158 API #30-045-24945

Plug and Abandonment Report

Notified NMOCD and BLM on 10/22/12

Plug and Abandonment Summary:

Plue 41 hus not set por Sundry Notice dured 10/1/12

Plug #2 pump 18 sxs (21.24 cf) Class B cement inside casing from 5501' to 5343'.

Plug #3 pump 24 sxs (28.32 cf) Class B cement with 2% CaCl inside casing from 5274'.

Plug #4 pump 24 sxs (28.32 cf) Class B cement inside casing from 4522' to 4311'.

Plug #5 with 24 sxs (28.32 cf) Class B cement with 2% CaCl inside casing from 3670' to 3459'.

- Plug #6 with 52 sxs (61.36 cf) Class B cement inside casing from 3005' to 2812', leaving 30 sxs outside the casing, 6 sxs below and 16 sxs above the CR.
- Plug #7 with 52 sxs (61:36 cf) Class B cement inside casing from 2082' to 1891' leaving 30 sxs outside, 6 sxs below and 16 sxs above.
- **Plug #8** with 50 sxs (59 cf) Class B cement inside casing from 605' to 450' leaving 32 sxs outside, 6 sxs below and 12 sxs above the CR.
- **Plug #9** with 41 sxs (48.38 cf) Class B cement inside casing from 100' to surface with good cement to the pit.
- Plug #10 with 33 sxs (38.94 cf) Class B cement found cement in 5.5" casing down 66' and in the 8-5/8 x 5.5" down 53' to install P&A marker.

Plugging Work Details:

- 10/23/12 Rode rig and equipment to location. SDFD.
- 10/24/12 Check well pressures: tubing 1300 PSI, casing 340 PSI and bradenhead 0 PSI. RU relief lines and attempt to blow the well down. Well wouldn't blow down. SI well. Change all equipment from 2-7/8" to 2-3/8". Pump 60 bbls down the tubing and casing to kill well. ND the wellhead. Strip on the 8-5/8" companion flange and the BOP. TOH and tally 170 joints of 2-3/8" tubing. At 65 stands the well started to, come around pumped 30 bbls to kill well. Continue TOH with 20 stands EOT at 5466'. SI well. SDFD.
- 10/25/12 Check well pressures: casing 600 PSI and bradenhead 0 PSI. Pump 50 bbls to kill well. PU 5.5" DHS CR, didn't pass through wellhead. Remove BOP and companion flange and the tubing hanger bowl and found a stripping rubber in the bowl below the tubing hanger. NU BOP and companion flange and tubing bowl. TIH and well started to come around. Continue to TIH. Set DHS CR at 5501'. Pressure test to 1250 PSI, OK. Attempt to pressure test the casing. Pressure up to 800 PSI and bleed off to 600 PSI in a minute. Spot plug #2 with TOC at 5343'. TOH. RU Bluejet logging tool to 5340' and log to surface. Cement from 5340' to 4440', 2930' to 2330' and 1433' to 1070'. PU plugging sub and TIH with 81 stands. PU 6 joints EOT at 5402'. No tag. TOH to 4636' and reverse out. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Nacogdoches Oil & Gas Inc. Navajo #32-2 October 31, 2012 Page 2 of 2

- 10/26/12 Open up well; no pressures. TIH and tag cement at 5399'. TOH to 5274'. Spot plug #3 with TOC at 5063'. WOC. TIH and tag cement at 4986'. PU 12' sub EOT at 4522'. Attempt to pressure test casing to 800 PSI, bled down to 700' in 2 minutes. Spot plug #4 with TOC at 4311'. SI well. SDFD.
- 10/29/12 Open up well; no pressures. TIH and tag cement at 4330'. TOH to 3670'. Attempt to pressure test casing to 800 PSI, bled down to 700 PSI in 2 minutes. Spot plug #5 with TOC at 3459'. WOC. TIH and tag cement at 3474'. Attempt to pressure test casing to 850 PSI and bled down to 750 PSI in 4 minutes. Perforated 3 HSC holes at 3005'. POH. Establish rate into perfs of 2 bpm at 850 PSI. TIH with DHS CR and set at 2953'. Attempt to pressure test casing to 800 PSI and bled down to 700 in 4 minutes. Establish rate of 1 bpm at 850 PSI. Spot plug #6 with TOC at 2812'. SI well. SDFD.
- 10/30/12 Open up well; no pressure. TIH and tag cement at 2806'. Attempt to pressure test up to 800 PSI and bled to 700 PSI in 2 minutes. Perforated 3 HSC holes at 2082'. POH. Establish rate into perfs 1 bpm at 850 PSI. Set DHS CR at 2032'. Attempt pressure test casing up to 850 PSI, OK. Establish rate into the perfs of 1 bpm at 850 PSI. Spot plug #7 with TOC at 1891'. Perforated 3 HSC holes at 605'. 30 minutes after perforating found a light flow of water up the casing. S. Mason, BLM approved procedure change. Establish rate of 3 bpm at 850 PSI. Bradenhead circulated at 0.5 bbl found leak in the surface casing below the bradenhead valve. Circulate well clean. TIH with 5.5" DHS CR and set at 555'. Sting into CR and pump 5 bbls into the perfs at 2 bpm at 850 PSI. S. Mason, BLM and G. Leslie- Bob, Navajo Nation, B. Powell, NMOCD approved procedure change. Spot plug #8 with TOC at 450'. LD all tubing. Perforated 3 HSC holes at 100'. Establish rate into perfs of 2 bpm at 900 PSI. Spot plug #9 with TOC at 4838'. SI well. SDFD.
- 10/31/12 Open up well; no pressures. ND BOP. Dig out wellhead. Write and perform Hot Work Permit and cut off wellhead. Found cement in 5.5" down 66' and in the 8-5/8" x 5-1/2" down 53'. Spot plug #10 and install P&A marker. RD & MOL.

Gail Leslie-Bob, Navajo Nation representative, was on location.