• · `a		e -	an	eende	d			
Form 3160-5 (March 2012)	DEPARTMENT O	UNITED STATES PARTMENT OF THE INTERIOR REAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014 5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS					Jicarilla Tribal #424 6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					Jicarilla Apache			
SUBMIT IN TRIPLICATE – Other instructions on page 2.					/. If Unit of CA/Ag	reement, Name and/or No.		
Type of Well Oil Well Gas Well Other					8. Well Name and No. Logos #2			
2. Name of Operator Logos Capital Management, LLC					9. API Well No. 30-043-21120			
3a. Address3b. Phone N4001 North Butler, Building 7101505-436-26Farmington, New Mexico 87401505-436-26				include area code) 10. Field and Pool or Exploratory Area Please see below.				
4. Location of Well <i>(Footage,</i> 1930' FSL & 730' FEL Section 6, Township 22N, Range 5W			11. County or Parish, State Sandoval, New Mexico					
12	CHECK THE APPROPR	IATE BOX(ES) TO IND	ICATE NATUR	E OF NOTICE	, REPORT OR OT	HER DATA		
TYPE OF SUBMISSIO	Ň	ТҮРЕ ОҒ АС				TION . (
Notice of Intent	Acidize	g Deep	=		tion (Start/Resume) nation	Water Shut-Off Well Integrity		
Subsequent Report	P Casing Repa		Construction	Recom	•	Other Amended Report Production Casing		
Final Abandonment Notic	Change Plan c Convert to In	_	and Abandon Back	· · ·	rarily Abandon Disposal	and Cement		
testing has been completed determined that the site is r Drilled 7-7/8" production hole KB & 2nd DV tool at 2557' KI	Final Abandonment Notic eady for final inspection.) to 6639' TD @ 6:00 hrs B. Bump plug on 1st stag OK. Open 2nd DV tool &	es must he filed only after 10/5/12. Ran 159 jts c ge cement to 2000 psi circulate 30 bbls of ce	r all requirement f 5-1/2", 17#, P held OK. Ope ment to surface	ets, including re 2110, LT&C ca en DV tool & c e. Bump plug	elamation, have be asing. Land casir irculate 30 bbls o on 3rd stage to 7	al, a Form 3160-4 must be filed once en completed and the operator has ng at 6639' KB, 1st DV tool at 4473' f cement to surface. Bump plug on '40 psi, pressure up to 2150 psi to d at 00:00 hrs 10/6/2012.		
See attachment for 3 stage cement details.						RCVD DEC 27'12		
Pools: Venado MesaVerde (O) 624 WC 22N5W6; Gallup(O) 979 WC 22N5W6; Dakota(O) 97	OIL CONS. DIV. DIST. 3							
					GC			
14. I hereby certify that the foreg	oing is true and correct. Nam	c (Printed/Typed)						
Kristy Graham	Title Director of Administration and Engineering Support							
Signature Dust.	Date 12/05/2012							
	THIS SI	PACE FOR FEDE	RAL OR ST	ATE OFFI	CE USE	ACCEPTED FORMEUUMU		
Approved by						DEC 17 2012		
Conditions of approval, if any, are that the applicant holds legal or eq entitle the applicant to conduct ope	Fitle crtify uld Office			FAHMINGTON FLD SEFICE				
Title 18 U.S.C. Section 1001 and fictitious or fraudulent statements	Title 43 U.S.C. Section 1212, or representations as to any r	make it a crime for any pe matter within its jurisdiction	rson knowingly a	nd willfully to r	nake to any departm	ent or agency of the United States any false,		

NMOCDAY

Logos #2 - production casing/cement sundry (attachment)

1 stage: Precede cement w/ 10 bbl water, 20 bbls of mud clean & 5 bbl water pace. Mix & pump 100 sx (198 cf) of Premium Lite w/ 0.25#/sk Cello-Flake, 0.2% CD-32, 0.2% FL-52A. Tail in w/ 250 sx (345 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello-Flake, 0.2% FL-52A. Good circulation throughout job. Pump slurry at 5 bpm. Drop plug & displace cement w/ 112 bbls of water & 41.3.5 bbls of mud (total displacement: 153.4 bbls). PD at 20:30 hrs 10/5/2012. Bump plug to 2000 psi (held pressure ok) – release pressure to check floats, holding OK. Increase pressure & open 1st DV tool at 2300 psi. Circulate off top of 1st DV tool. Continue pumping and *circulate out 30 bbls of good cement to surface*. Switch over to rig pump and circulate for 4 hrs – good returns entire time.

2nd stage: Precede cement w/ 10 bbls water & 10 bbls of mud clean. Mix & pump 100 sx (209 cf) of Premium Lite, 1% CaCl2, 5#/sk LCM-1, 8% Bentonite. Tail in w/ 226 sx (312 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello Flake, 0.2% FL-52. Drop plug & displace cement w/ 54 bbls of water & 50 bbls of mud (total displacement: 104 bbls). PD at 03:00 hrs 10/6/2012. Bump plug to 1200 psi (close 1st DV tool) – holding pressure OK. Release pressure to check float, held OK. Open cement head & drop dart. Hesitate for 15 mins. Pressure up on 2nd DV tool, opened at 1030 psi. Circulate off top of 2nd DV tool. Continue pumping and *circulate out 30 bbls of good cement to surface*. Switch over to rig pump & circulate for 4 hrs – good returns entire time.

3rd stage. Precede cement w/ 10 bbls water & 10 bbls of mud clean. Mix & pump 250 sx (532 cf) of Premium Lite w/ 3% CaCl2, 0.25 #/sk Cello-Flake, 5#/sk LCM-1, 8% Bentonite, 0.4% Sodium Metasilicate, 0.4% FL-52A. Tail in w/ 150 sx (204 cf) of Type III w/ 1% CaCl2, 0.25#/sk Cello Flake, 0.2% FL-52. Pump slurry at 5 bpm. Drop plug & displace cement w/ 59.3 bbls of water. PD at 09:00 hrs 10/6/2012. Bump plug to 2150 psi (close 2nd DV tool) – holding pressure OK. Release pressure to check float, held OK. *Circulated 50 bbls of good cement to surface*.

