Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED

	OMB No. 1004-01
17	Expires: July 31, 2

BUREAU OF LAND MANAGEMENT APR () 2 20

	Expires: .	July 3	31, 2010	
ease Serial No.				

		AI IV	7 2 3 5. Lea			
C118	DRY NOTICES AND REPO	Field C	Contract 104			
Do not use	e this form for proposals t	to drill or to re-enter an	ក្ក Mar age	Jicarilla Apache		
abandoned	well. Use Form 3160-3 (A	PD) for such proposa	ls.		·	
	BMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If U	Jnit of CA/Agreement, Na	ame and/or No.	
1. Type of Well	· 🖂					
Oil Well	Gas Well Other		8. W€	ell Name and No.	arilla E 15	
2. Name of Operator		-1	9. AP	I Well No.		
3a. Address	ConocoPhillips Compa	3b. Phone No. (include area co	da) IO E		39-21773	
PO Box 4289, Farmingto	on, NM 87499	(505) 326-9700	· ·	10. Field and Pool or Exploratory Area Basin Dakota/Wildhorse Gallup		
4. Location of Well (Footage, Sec., T., R				ountry or Parish, State		
Surface UNIT "L" (NW	/SW), 1645' FSL & 830' FV	VL, Sec. 16, T26N, R4V	٧	Rio Arriba ,	New Mexico	
12. CHECK 1	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE,	, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYPE	OF ACTION	N		
X Notice of Intent	Acidize	Deepen	Product	tion (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclam	ation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomp	plete	X Other Remove	
7	Change Plans	Plug and Abandon		rarily Abandon	Packer & Commingle	
Final Abandonment Notice 13. Describe Proposed or Completed Op	Convert to Injection	Plug Back		Disposal		
Testing has been completed. Final determined that the site is ready for Plans are to remove the	red operations. If the operation result Abandonment Notices must be filed in final inspection.) e packer set @ 7,557' and procedure and wellbore	only after all requirements, included the property of the prop	ading reclamation	on, have been completed a	n Dakota with the	
					DOUR ADD A 11 9	
					RCVD APR 4'13 OIL CONS. DIV.	
					DIST. 3	
14. I hereby certify that the foregoing is	s true and correct. Name (Printed/Ty)	ped)				
	D 1 1			Regulatory Tech	nician	
	Denise Journey	Title				
À				4/1/2013		
Signature) enust) ourself Date						
	THIS SPACE FO	OR FEDERAL OR STA	TE OFFICE	USE		
Approved by Original Signal	gned: Stephen Mason				ADD 0.5 2012	
		T	itle		Date APR 0 2 2013	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCDA

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

ConocoPhillips JICARILLA E 15 WO - Commingles

Lat 36° 29' 26.588" N

Long 107° 15' 32.4" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU coiled tubing rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. **Note: This is a dual well, separated by a packer.** Kill well with 2% KCI, if necessary.
- 4. ND wellhead and NU BOPE. RU lubricator. Test BOP.
- 5. Spool out of the hole with 1" coiled tubing. ND BOP and NU wellhead. RDMO coiled tubing rig.
- 6. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview,
- 7. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 8. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 9. ND WH and NU BOPE. Pressure test and function test BOP. TOOH and LD GP side 2-1/16" tubing.
- 10. PU and remove dual tubing hanger.
- 11. Release retrievable packer (set at 7557'). TOOH and LD DK side 2-1/16" tubing and packer.
- 12. PU and TIH with packer plucker and new 2-3/8" tubing to mill out permanent packer at 7582'. TOOH with packer remnants.
- 13. PU mill and bit sub for 5-1/2" 15.5# casing and TIH to clean out to PBTD. Record fill depth in WellView.

Save a sample of the fill and contact engineer for further analysis. TOOH. If fill could not be CO to PBTD, please call Production Engineer to inform how much fill was left and confirm/adjust landing depth.

14. TIH with tubing using Tubing Drift Procedure (detail below).

	Tubing and BHA Description			
Run Same BHA:	No	1 2-3/8" 4.7# J-55 Mule Shoe/Expendable Check		
Tubing Drift ID:	1.901"	1 2-3/8" 4.7# J-55 Seating Nipple (1.780" ID)		
		1 2-3/8" 4.7# J-55 Tubing Joint		
Land Tubing At:	+/- 7725'	1 2-3/8" 4.7# J-55 Pup Joint (4')		
KB:	14'	~242 2-3/8" 4.7# J-55 Tubing Joints		
		As Needed 2-3/8" 4.7# J-55 Pup Joints		
		1 2-3/8" 4.7# J-55 Tubing Joint		

15. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

