Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

KEAU OF LAND MANAGEMEN			J
	APR	09	2013 5. Lease Serial No.

NW-9037

				1.4	INI-AUS!			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or feeling than a land abandoned well. Use Form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name ந்திர்க்க						
		7. If Unit of CA/Agreement, Na	ame and/or No.					
Oil Well X Gas Well Other		8. Well Name and No. REESE MESA 8 POW						
•		9. API Well No. 30-045-25992						
Burlington Resources Oil & Gas Company LP 3a. Address 3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area						
PO Box 4289, Farmingto	on, NM 87499	(505) 326-9		Basin Fruitland Coal				
4. Location of Well (Footage, Sec., T.,R Surface UNIT L (NWS)	R.,M., or Survey Description) W), 1660' FSL, & 835' FWL	., Sec. 12, T32N, R8	W	11. Country or Parish, State San Juan ,	New Mexico			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA								
TYPE OF SUBMISSION		TYF	TYPE OF ACTION					
X Notice of Intent	Acidize	Deepen	P	roduction (Start/Resume)	Water Shut-Off			
2	Alter Casing	Fracture Treat	R	eclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	R	ecomplete	X Other MIT			
60	Change Plans	Plug and Abandon	ТТ	emporarily Abandon	Pressure Observation			
Final Abandonment Notice	Convert to Injection	Plug Back		/ater Disposal	Well			
-	r final inspection.) ntends to perform an MIT to as performed 7/1/2008. Pr	-			RCVD APR 12'13 OIL CONS. DIV. DIST. 3			
14. I hereby certify that the foregoing is	strue and correct. Name (Printed/Typ	red) Title		Regulatory Techn	iician			
Signature Inix	Journey	Date	3/27/2013 Date					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by Original Sign	ned: Stephen Mason		Title		Date			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

ConocoPhillips REESE MESA 8 POW Expense - MIT

Lat 36° 59' 40.956" N

Long 107° 37' 53.292" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 5. ND wellhead and NU BOPE. Pressure and function test BOP.
- 6. TIH with a 2-7/8" gauge ring or scraper to 3650'. TOOH.
- 7. TIH w/ 1-1/4" workstring and 2-7/8" packer. Set at 3620'.
- 8. RU hose from pump truck and connect to casing. Pump 2% KCL (treated with biocide) down casing. Annular capacity is 12 BBLS. Perform MIT. MIT must be performed at 560 psi for 30 minutes and recorded on a 2 hour chart with a 1000# spring maximum. Report results of test to engineer and regulatory.
- 9. Release packer and TOOH with 1-1/4" work string and 2-7/8" packer. TIH with 1-1/4" workstring and use air package to unload well. TOOH with workstring.
- 10. ND BOP, NU wellhead. RDMO.

part 19

Current Schematic

ConocoPhillips

Well Name: REESE MESA #8

