Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMSF078875	
					 If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No. 	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					891001059C	
1. Type of Well Gas Well Other					8. Well Name and No. CANYON LARGO UNIT 359	
2. Name of Operator Contact: CATHERINE SMITH HUNTINGTON ENERGY LLC E-Mail: csmith@huntingtonenergy.com					9. API Well No. 30-039-23878-00-S1	
3a. Address 908 NW 71ST ST OKLAHOMA CITY, OK 7		(include area code 0-9876 Ext: 129 -2011		10. Field and Pool, or Exploratory DEVIL'S FORK		
4. Location of Well (Footage, S	11. County or Parish, and State			and State		
Sec 31 T25N R6W NESV 36.353897 N Lat, 107.51	, ,	RIO ARRIBA COUNTY, NM				
12. CHECK	APPROPRIATE BOX(ES) T	O INDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE OF ACTION				
Notice of Intent ``	□ Acidize	🗖 Deej			ion (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing	—	ture Treat	Reclam		Well Integrity Other
Final Abandonment Noti	Casing Repair ce Change Plans	_	and Abandon	□ Recomp	arily Abandon	
	Convert to Injection				ter Disposal	
Attach the Bond under which the following completion of the inv testing has been completed. Find determined that the site is ready	ectionally or recomplete horizontally, ne work will be performed or provide volved operations. If the operation re nal Abandonment Notices shall be fil / for final inspection.)	e the Bond No. on esults in a multiple led only after all r	file with BLM/BI/ e completion or reco equirements, includ	A. Required sub ompletion in a point of the second	osequent reports shall be rew interval, a Form 316 n, have been completed, it the	filed within 30 days 0-4 shall be filed once
3/20/13: Spot equipment. Hold safety mtg. RU pulling unit & cmt equipment. Check psi on the v ND the WH, NU BOP & function test the BOP. Secure location. Kelly Nix w/BLM on location. C Brandon Powell w/NMOCD on 3/19/13.					Vell. OTI COMO DILI	
CIBP @ 5690'. RU Basin & PU 20' of subs. EOT @	Service & start equipment. C Well Logging. Log well from 9 5690' KB, Plug #1: 44 sx 15. location. Kelly Nix w/BLM on	5682'-surface. 6#, 1.18 yld, 5	PU plugaing su	b & TIH w/8	∖ tagged 8 stands	
14. I hereby certify that the forego	Electronic Submission #	TON ENERGY	LC, sent to the	Farmington	-	<u> </u>
Name (Printed/Typed) CATHERINE SMITH			Title REGUL	ATORY		
Signature (Electri	onic Submission)		Date 04/09/2	013		
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE	
APProved By ACCER	STEPHEN _{Title} PETROLE	I MASON UM ENGIN	EER	Date 04/10/2013		
Conditions of approval, if any, are a	ttached. Approval of this notice doe or equitable title to those rights in th conduct operations thereon.		Office Farming	aton		
Title 18 U.S.C. Section 1001 and Ti	tle 43 U.S.C. Section 1212, make it a ulent statements or representations a	a crime for any pe s to any matter w	rson knowingly and	l willfully to m	ake to any department or	agency of the United
** BLM	REVISED ** BLM REVISE	D ** BLM RE	EVISED ** BLI	M REVISE	D ** BLM REVISE	D **

NMOCD \wedge

•

. ----

Additional data for EC transaction #203935 that would not fit on the form

32. Additional remarks, continued

3/22/13: Hold safety mtg. Start equipment. Check psi on well: tbg, csg & BH: 0. RU relief line & open well. TIH w/12 stands & PU 1 jt & tag TOC @ 5116', EOT @ 5104'. Test csg-ok. Plug #2: 12 sx 15.6#, 1.18 yld, 14.16 cu ft, Class B cmt from 4104'-3946' TOC. Secure location.

3/25/13: Hold safty mtg & start equipment. Check psi on the well. RU relief line and open well. Tag CR @ 2690'. Drill out. Circ the well clean for 15 mins. RD swivel and TIH. EOT now at 3446'. Continue TOOH with stands. RD the power swivel. RIH w/4 1/2" WL. Set CR to 3349'. POOH. Secure location.

3/26/13: Hold safety mtg & start equipment. Check psi on the well: 0 csg, 0 BH. RU relief line & open well. PU the CR stinger. TIH w/52 stands. PSI test csg to 950#. Good test. Plug #3: Mix and pump 64 sx 15.6#, 1.18 yld, 75.52 cu ft Cls B cmt from 3401'-3271' TOC. Leaving 4 sx below the CR, 50 sx outside and 10 sx above the CR. Plug #4: Mix and pump 30 sx 15.6#, 1.18 yld, 35.4 cu ft Class B cmt from 2606' - 2211' TOC. TOOH. LD to 2091'. Plug #5: Mix and pump 28 sx 15.6#, 1.18 yld, 33.04 cu ft Class B cmt from 2091'-1722' TOC. TOOH. LD all tbg. Load hole w/4 bbls. TIH w/ 3 1/8" HSC & perf 3 holes @ 548', because of a collar. Wait on water truck. Plug #6: Mix and pump 215 sx 15.6#, 1.18 yld, 253.7 cu ft Class B cmt from 548' - surface w/good cmt to pit. Secure location.

3/27/13: Hold safety mtg & start equipment. Check psi on the well: csg & BH 0. Dig out the WH & ND the BOP. Cut off the WH, cmt in the 8 5/8" x 4 1/2" @ surf and the 4 1/2" DN 18'. Set the Surface Hole Marker & top off w/25 sx, 15.6#, 1.18 yld, 29.5 cuft Class B cmt. RD the pump. RD pulling unit. Kelly NIx w/BLM on location.

