· 1			RECEIVI		
Form 3160- 5 (August 2007)	UNITED S DEPARTMENT OF BUREAU OF LAND SUNDRY NOTICES AND Do not use this form for propos abandoned well. Use Form 3160	THE INTERIOR MANAGEMENT BU REPORTS ON WE sals to drill or to re-ent	LLS I er an 6. If	FORM APPROVED OMB No. 1004- 0137	
	T IN TRIPLICATE - Other Ins	tructions on pagė 2.	7. If	f Unit or CA. Agreement Name and/or No.	
Type of Well     Oil Well     Gas We     Gas We	l Other			Vell Name and No. Jicarilla 30-03-34 #4	
Black Hills Gas Reso	urces, Inc.			PI Well No.	
3a. Address	······································	3b. Phone No. (include are		30-039-26733	<u> </u>
3200 N 1st St, Bloom		(505) 634-5104		Field and Pool, or Exploratory Area	
<ol> <li>Location of Well (Foolage, Sec., T., R., M., or Survey Description)</li> <li>2066' FSL &amp; 2018' FEL NW/SE Section 34 T30N R3W (UL: J)</li> </ol>				East Blanco Pictured Cliffs County or Parish, State	·
	PROPRIATE POV(S) TO DIDIO	ATE NATURE OF NO		Rio Arriba County, New Mex	10
12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT,					
TYPE OF SUBMISSION		ן 	YPE OF ACTION		
Notice of Intent	Acidize	Deepen	Production ( Start/ R	esume) Water Shut-off	
_	Altering Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
31	Change Plans	Plug and abandon	Temporarily Abando	on	
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal		
Attach the Bond under which the following completion of the invo testing has been completed. Fina determined that the site is ready	tionally or recomplete horizontally, give so work will performed or provide the Bond lved operations. If the operation results in Abandonment Notice shall be filed only a for final inspection.)	No. on file with the BLM/ BI a multiple completion or recor fifter all requirements, includin	A. Required subsequent reports npletion in a new interval, a Fo g reclamantion, have been com	shall be filed within 30 days rm 3160-4 shall be filed once	
14. I hereby certify that the foregoin Daniel Manus	g is true and correct. Name (Printed/ Type	Regulatory	7 Technician		
Signature Hand	Mannes	Date Man	14,2013	S AGREPTEDFO	Resm
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE USE	AA14	
Approved by			<u> </u>	Piar 2 1	:013 
Conditions of approval, if any are atta	hed. Approval of this notice does not war	rant or certify		Dates a stranger play	nn=
	ble title to those rights in the subject lease			W_sm	UTRICE
	le 43 U.S.C. Section 1212, make it a crime presentations as to any matter within its ju		d willfully to make any departm	nent or agency of the United States any false	, ,

(Instructions on page 2)

17 3

ς



.



## Black Hills Gas Resources has plugged & abandoned this well as follows:

5/1/13: 4:00 PM, Notified BLM, JAT-BLM, & NMOCD of upcoming operations.

- 5/2/13: MIRU A Plus Well Service Rig #14. SITP 7 psi. SICP 30 psi. SIBHP 0 psi. Set up H2S monitors. Bled well down. No H2S monitored. TOH with rods & pump. SDFN.
- 5/3/13: SITP 3 PSI. SICP 2 psi. SIBHP 0 psi. Bled well down. No H2S. Dig out BH. Install 2" plumbing to surface. ND WH. NU & function test BOP. Attempt to pull 2 3/8" tbg. Tbg stuck. Pump 30 bbls down tbg while working tbg. Stretch indicates tbg stuck at 2900'. Turned pipe to the right, came free. TOH with 2 3/8" tbg. Recovered 78 joints & 1 partial joint 2 3/8", 4.7#, J-55 tbg. Top of fish at 2550'. SDFWE.
- 5/6/13: SICP 0 psi. SIBHP 0 psi. No H2S. TIH with overshot & fishing tool assembly on 2 7/8", 6.5#, N-80 workstring. Latched onto fish. Jarred on fish for 45 min. Jars failed. Release OS. TOH. Replace jars. TIH. Latch onto fish. Jarred on fish for 1 ½ hrs. Max pull 80K#. Pumped 30 bbls down csg while jarring, no movement on fish. Release OS. PUH 1 joint. SDFN. Rod Velarde, JAT-BLM on location.
- 5/7/13: SITP 0 PSI. SICP 0 psi. SIBHP 0 psi. Latch onto fish. Jarred on fish for 2 hrs. Stacking out 3" higher than beginning of jarring. Received approval from Bryce Hammond JAT-BLM & Steve Mason BLM at 10:15 AM & Brandon Powell NMOCD at 10:45 AM to pump plug #1 thru fish at 2550' to cover OA top & Lower Nac perfs then balance plug above fish to cover Nac top.. TOH with fishing tools. TIH with overshot with seal control. Seal onto fish. Pump 95 bbl down tbg. Establish injection rate at 2 bpm, 700 psi with 15 bbl. Mix & pump Cmt Plug #1 (124 sx, 146.3 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) : 1) Pump 46 sx thru fish to fill inside tbg fish from 3304' to 2550' & fill csg from 3304' to 3168' (Top of Lower Nac perfs) + 100% excess. PU off fish. 2) Spot balanced plug, 78 sx from 2550' to 1862'. Flush with 1 ¼ bbl water. TOH. Load BH with 1 ¼ bbls. Pressure test BH to 300 psi. Held ok. SDFN. Bryce Hammond, JAT-BLM contacted by phone.
- 5/8/13: SICP 0 psi. SIBHP 0 psi. No H2S. TIH. Tag plug #1 at 2459'. Circ hole clean. Pressure test csg to 850 psi. Held OK 5 min. Mix & pump Cmt Plug #1A (56 sx, 66.08 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 2459' to 1965' to isolate Nac perfs & top. TOH. TIH to 321'. Mix & pump Cmt Plug #2 (42 sx, 49.56 cu ft, 15.6 ppg, 1.18 yield, class 'B' cmt) from 321' to surface. Circ good cmt out csg valve. TOH. ND BOP. Dig out & cut off wellhead. TOC at 28' in 5 ½" csg & 48' in 8 5/8" csg. RD rig. Mix & pump 26 sx 15.6# class B cmt to top off csgs & set DH marker. Release A-Plus Rig #14. Bryce Hammond, JAT-BLM contacted by phone.