

Form 3160-5 (August 2007) UNITED STATES
DEPARTMENT OF THE INTERIOR

MAY 29 2013

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT Field Iffice Stresses

Expires: July 31, 2010

Bureau of Land Man			S Lease Serial No. NMSF-078741			
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an			6. If Indian, Allottee or Tribe N	ame		
	well. Use Form 3160-3 (A					
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well			San S	Juan 30-6 Unit		
Oil Well X	Gas Well Other		8. Well Name and No.  San Juar	n 30-6 Unit 490S		
2. Name of Operator			9. API Well No.			
Burlingt	ton Resources Oil & Gas	Company LP	30-0	39-27719		
		3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area			
PO Box 4289, Farmington, NM 87499		(505) 326-9700	Basin Fruitland Coal			
4. Location of Well (Footage, Sec., T.,R.  Surface Unit O (S	,M., or Survey Description) WSE), 920' FSL & 1495' F	EL, Sec. 25, T30N, R6W	11. Country or Parish, State Rio Arriba	New Mexico		
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	TICE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION		TYPE OF AC	TION			
Notice of Intent	Acidize	Deepen 1	Production (Start/Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
X Subsequent Report 00	Casing Repair	New Construction	Recomplete	Other		
120	Change Plans	X Plug and Abandon	remporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
13. Describe Proposed or Completed Ope	13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.					

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

4/30/13 Notified Brandon Powell/OCD (R.Espinosa onsite). Ran CBL, TOC @ 197'. Requested permission to perf @ 185'. Verbal approval to perf between 160'-185'.

The subject well was P&A'd on 5/1/13 per the notification above and the attached report.

RCVD JUN 4'13 OIL CONS. DIV. DIST. 3

Staff Regulatory Technician	
. 5/29/13	ACESTSVEPS SELYS
OR STATE OFFICE USE	0.000000
	PIRI 3 I LUIS
Title	PATHER BLOW FIELD OFFICE
Office	24 7.
0	or State Office USE

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Burlington Resources
San Juan 30-6 Unit 490S

May 1, 2013 Page 1 of 2

920' FSL and 1495' FEL, Section 25, T-30-N, R-6-W Rio Arriba County, NM Lease Number: NMNM-078741 API #30-039-27719

Plug and Abandonment Report Notified NMOCD and BLM on 4/24/13

## Plug and Abandonment Summary:

- Plug #1 with 18 sxs (21.24 cf) Class B cement inside casing from 3704' to 3545' to cover the Pictured Cliffs interval and top. WOC. Tag Plug #1 at 3545'.
- Plug #2 with CR at 3350' spot 59 sxs (69.62 cf) Class B cement inside casing from 3350' to 3044' to cover the Fruitland Coal and Intermediate shoe casing and liner top.
- Plug #3 with 64 sxs (75.52 cf) Class B cement inside casing from 2956' to 2624' to cover the Kirtland and Ojo Alamo tops.
- **Plug #4** with 33 sxs (34.22 cf) Class B cement inside casing from 1553' to 1382' to cover the Nacimiento top.
- **Plug #5** with 88 sxs (103.84 cf) Class B cement inside casing from 177' to surface to cover the surface casing shoe; circulate good cement out bradenhead valve.
- Plug #6 with 40 sxs Class B cement install P&A marker.

#### **Plugging Work Details:**

- 4/26/13 MOL and RU. Check well pressures: 70 PSI on casing and tubing; no bradenhead pressure. Layout reliev lines to pit and blow well down. PU on rod string and unseat pump. Re-seat pump. Attempt to pressure test tubing; no test. LD polish rod. TOH and LD rods with pump. Total tally 137 ¾" plain rods, 3-K bars and pump. Attempt to pressure test tubing with standing valve; pump 30 bbls of water 3.5 bpm at 150 PSI; no test. ND wellhead. NU BOP and test. PU on tubing and LD tubing hanger. TOH and tally 113 joints 2-3/8" tubing with pup joints, profile nipple, mud anchor, x-over and muleshoe guide. Total tally approximately 3452'.
- 4/29/13 Open up well; no pressures. PU tubing workstring and TIH; tag at 3704'. Spot Plug #1 with estimated TOC at 3545'. PUH and WOC. TIH and tag Plug #1 at 3545'. TOH with tubing. Round trip casing scraper to 3361' (5.5" liner at 3361'). RIH with Select Oil CR to 3350'. SI well. SDFD.
- 4/30/13 Check well pressures: tubing and casing 10 PSI and bradenhead 0 PSI. Set CR at 3350'. Pressure test tubing to 1200 PSI for 10 minutes. Circulate casing clean with total 140 bbls of water. Pressure test casing to 800 PSI for 30 minutes. Attempt to pressure test bradenhead to 300 PSI; bled down to 200 PSI in 5 minutes. TOH with tubing and LD setting tool. ND stripping head. RU A-Plus wireline and run CBL from 3350' to surface. Call TOC at approximately 190'. Spot Plug #2, Plug #3 and Plug #4. LD tubing. Note: R. Espinoza, BLM and B. Powell, NMOCD, approved procedure change. Perforate 3 squeeze holes at 177'. Pump 20 bbls of water down casing and establish circulation out bradenhead. Circulation clean with additional 10 bbls of water 2.5 bpm at 400 PSI. Spot Plug #5. SI well. SDFD.

# A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Burlington Resources San Juan 30-6 Unit 490S

May 1, 2013 Page 2 of 2

### Plugging Work Details Continued:

5/1/13 Open up well; no pressures: ND wellhead. RU High Desert. Dig out wellhead. Cut off wellhead. Found cement at surface. Weld on P&A marker. Spot Plug #6 with 40 sxs Class B (47.2 cf) cement. RD and MOL.

Andy Jackson, BLM representative, was on location. Josh Jacobs, Conoco representative, was on location.