Lie William Lings UNITED STATES Form 3160-5

(August 2007)

JUN 03 201B

FORM APPROVED

DEPARTMENT O	F THE INTERIOR	
BUREAU OF LAND	D MANAGEMENTS	p

OMB No. 1004-0137

BUTTAITSTON FIOLG (1970) Bureau of Land (Vana 5) desse Serial No.

Expires: July 31, 2010

SF-078913

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.		7. If Unit of CA/Agreemen	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Oil Well X Gas Well Other			Lindrith B Unit  8. Well Name and No.	
		Lir	Lindrith B Unit 30	
2. Name of Operator			9. API Well No.	
ConocoPhillips Company		3	30-039-23859	
3a. Address		3b. Phone No. (include area of	ode) 10. Field and Pool or Expl	oratory Area
PO Box 4289, Farmington	on, NM 87499	(505) 326-970	0 West Lin	ndrith Gallup/Dakota
4. Location of Well (Footage, Sec., T., I	R.,M., or Survey Description)	<u> </u>	11. Country or Parish, Stat	e
Surface Unit I (NESE), 1680' FSL & 660' FEL, Sec. 16, T24N, R3W		Rio Arriba	, New Mexico	
			1	
12. CHECK	THE APPROPRIATE BOX	(ES) TO INDICATE NATURE	OF NOTICE, REPORT OR OT	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
•	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
(5)	Change Plans	Plug and Abandon	X Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
13 Describe Proposed or Completed Or	peration: Clearly state all pertinen	t details, including estimated startin	a date of any proposed work and appr	oximate duration thereof

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

ConocoPhillips Company requests permission to temporarily abandon the subject well with the intent to return the well to production once gas prices rise. Please see the attached procedure and well bore schematic.

Notify NMOCD 24 hrs

prior to beginning operations

RCVD JUN 11'13 OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	Staff I	Staff Regulatory Technician		
Kenny Davis Ti	le			
Signature	te	5/30/2013		
THIS SPACE FOR FEDERAL	OR STATE OFFICE US	E		
Approved by  Original Signed: Stephen Mason		JUN 0 3 2013		
Conditions of construct if any analysis of Assembly Assembly and Assem	Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certife that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office			

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

## ConocoPhillips LINDRITH B UNIT 30 Expense - TA

Lat 36° 18' 27.68" N

Long 107°9' 17.136" W

## **PROCEDURE**

- \*\*\*There is a plunger in this well, BE SURE TO SET A LOCKING THREE SLIP STOP.\*\*\*
- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCI, if necessary.
- 5. ND wellhead and NU BOPE. Pressure test and function test BOP. PU and remove tubing hanger and tag for fill, adding additional joints as needed. Record fill depth in Wellview.
- 6. TOOH with 2-3/8" tubing (per pertinent data sheet).
- 7. PU CIBP and packer for 5-1/2", 15.5# casing. RIH and set CIBP 50' above DK perforations at 7386' Set packer above CIBP and test to make sure CIBP is set. **NOTE: The well was cleaned out with a mill and bit during the February 2013 workover.**
- 8. Load casing with packer fluid (approximately 176 bbls). Perform an MIT by pressure testing the casing to 560 psi for 30 minutes. Be sure to record the test on a chart with 1000 psi spring. Pressure drop can not be greater than 10 percent over a 30 minute period. If casing tests, move on to step 9. If casing does not test, notify COPC engineer.
- 9. Top off the casing with packer fluid. ND BOPE and NU wellhead. RD MOL.

