Office Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103		
District I	Energy, Minerals and Natural Resources		Jun 19, 2008		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II	OIL CONSERVATION DIVISION		30-045-33120		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of L		
1000 Rio Brazos Rd., Aztec, NM 87410			STATE _	FEE 🛛	
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lo		
1220 S. St. Francis Dr., Santa Fe, NM 87505			F	EE	
	CES AND REPORTS ON WELL	S	7. Lease Name or Un	nit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Culpepper Martin		
I. Type of Well: Oil Well				8. Well Number 8B	
2. Name of Operator			9. OGRID Number		
Burlington Resources Oil Gas Company LP			14:	538	
3. Address of Operator			10. Pool name or Wi	ldcat	
P.O. Box 4289, Farmington, NM 87499-4289			Blanco MV / Basin DK		
4. Well Location			<u></u>		
Unit Letter O: 670	feet from the South	line and1965	feet from the	East line	
Section 19	Township 32N I	Range 12W	NMPM San Ju	an County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5855' GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
	• •		•		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
				AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲		
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
OTHER:   13 Describe proposed or comp	leted operations (Clearly state all		d give pertipent dates in	ncluding estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.	TR). SEE ROLL 1103. TO Main	pie Compietions. 71	aden wenoore diagrams	or proposed completion	
e. / • • • • • • • • • • • • • • • • • •					
6/4/13 Notified Brandon Po	owell/OCD to request permission to	o combine Plugs 1&	2. Verbal approval rec'	vd.	
The subject well was P&A'	d on 6/5/13 per the notification abo		report. OIL CON	S. DIV DIST. 3	
	Approved for plugging of we			O. DIA DIO 1. 2	
DNB WI	Liability under bond is retain		H-H	0.5 2013	
Spud Date:	Receipt of C-103 (Subsequen Plugging) which may be four		JOL	O. D 2012	
Spud Date.	page under forms	та (ш) ОСД WED ——			
	www.emnrd.state.us/ocd				
I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief.		
(1)	12			10/0	
SIGNATURÉ / MILLIE	College TITLE_	Staff Regulatory	Technician DATE _	1/3/13	
Type or print name Dollie L. Buss	se E-mail address: dollie	Lbusse@conoconhi	llips.com PHONE: 5	505-324-6104	
For State Use Only	2 man address. dome				
	/ <i>//</i> // De	puty Oil & Gas	s Inspector,	1-1-	
APPROVED BY: 026		District	<b>#3</b> D	ATE 7/5/13	
Conditions of Approval (if any):	A				
	ιγ				

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Burlington Resources
Culpepper Martin 8B

June 5, 2013 Page 1 of 1

670' FSL and 1965' FEL, Section 19, T-32-N, R-12-W San Juan County, NM Lease Number: Fee API #30-045-33120

Plug and Abandonment Report Notified NMOCD and BLM on 5/30/13

## Plug and Abandonment Summary:

- Plug #1 (combined #1&#2) with CR at 1560' spot 133 sxs (156.94 cf) Class B cement, squeeze 85 sxs (100.3 cf) below CR and leave 48 sxs (56.64 cf) top of CR to cover the Dakota, Mesaverde, Pictured Cliffs, Chacra and Fruitland top. Estimated TOC at 1311'.
- **Plug #3** with 133 sxs (156.94 cf) Class B cement inside casing from 555' to surface to cover the surface casing shoe.
- Plug #4 with 28 sxs Class B cement found cement at surface and install P&A marker.

## **Plugging Work Details:**

- 5/31/13 Rode rig and equipment to location. RU. Check well pressures: tubing 280 PSI, 4.5" casing and 7" casing 300 PSI and bradenhead 0 PSI. Blow well down. Pump 50 bbls to kill well. ND wellhead and NU kill spool. Pressure test pipe rams to 800 PSI and 1500 PSI, OK. Pull tubing hanger and install stripping rubber. TOH and tally 3 stands, 1 joints, collar (67 joints) J-55, EUE, 4.7#, 2-3/8" tubing, total 2032'. SI well. SDFD.
- 6/3/13 Bump test H2S equipment. Check well pressures: no tubing, casing 300 PSI and bradenhead 0 PSI. Pump 50 bbls of water to kill well. ND BOP and wellhead. RU Wireline Specialties. RIH and find free point at 1560'. Note: B. Powell, NMOCD approved procedure change. RIH with chemical cutter and cut 4.5" casing at 1560'. Pull 4.5" hanger casing free. RU San Juan Casing. TOH and LD 1 joint, 14', 12', 4' subs, 34 joints, 1 cut joint of 4.5", J-55, 10.5#, NU casing (35 joints total), 1 cut joint. RU 2-3/8" tubing equipment. TIH with 7" string mill to 1560'. SI well. SDFD.
- Bump test H2S equipment. Check well pressures: no tubing, casing 300 PSI and bradenhead 0 PSI. Pump 80 bbls of water to kill well. TIH with 7" DHS CR and set at 1560'. Pressure test tubing to 1000 PSI, Ok. Establish circulation out casing. Pressure test casing to 800 PSI, OK. RU Blue Jet Wireline. Ran CBL from 1560' to surface. Good cement to surface. Circulate with 1 bbl water, establish rate 3 bpm at 200 PSI. Spot plug #1 (#1 & #2 combined) with estimated TOC at 1311'. Establish circulation. Spot plug #3 with estimate TOC at surface. Dig out wellhead. SI well. SDFD.
- Bump test H2S equipment. Open up well; no pressures. RU High Desert. Cut off wellhead. Found cement at surface. Spot plug #4 and install P&A marker. RD and MOL.

Jim Morris, MVCI representative, was on location. John Durham, NMOCD representative, was on location.