Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS JUN 18 2013

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

NMSF 079090

6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Forn	n 3160-3 (APD) for suc	h proposalsigton Field U	iem⇒.
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator			8. Well Name and No. Navajo Lake # 103
(B) NW/NE	7401 Description) N, R06W, N.M.P.M.	Fracture Treat Recl New Construction Recc Plug and Abandon Tem	
If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment Metermined that the final site is ready for final inspective. Energen Resources repaired a shall Oli	formed or provide the Bond f the operation results in a monotices shall be filed only affection.)	No. on file with BLM/BIA. Requialtiple completion or recompletion er all requirements, including reclations well according to	red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once mation, have been completed, and the operator has the attached procedure. JUL 01 2013
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kirt Snyder		Title District Engir	eer
Signature	SPACE FOR FEDER	Date 6/14/2013 AL OR STATE OFFICE USE	
Approved by	O AOL I ON I LUEN	Title	Date
Conditions of approval, if any, are attached. Approval of this not the applicant holds legal or equitable title to those rights in the sul entitle the applicant to conduct operations thereon.		t Office	

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Completed Workover Procedure Navajo Lake #103 NE/4 Section 24, T32N, R05W

- 1. MIRU WSU. ND WH. NU BOP.
- 2. TOH w/2-3/8" tbg scana-log out of the hole and tally. Replace bad tubing.
- 3. TIH w/ RBP and set @ 2,000' MD.
- 4. TIH w/ Hornet Packer and set @ 200' MD. Pressure test between RBP and packer to 750 psi for 15 min. Shut valve on packer and pressure test top to 750 psi for 15 min.
- 5. Disassemble well head/casing head and evaluate. Hole in casing found at surface to 3 ft with visual inspection.
- 6. NU WH. MIRU wireline. Run CBL, MTT, and camera to evaluate casing integrity.
- 7. Cut top of 7" intermediate casing and remove slips.
- 8. Wash over and cut out, and back off 7" casing down to collar at 93' KB. PU and TIH w/ 2 new jts of 7" 23# K-55 csg. Screw into collar @ 93' KB.
- 9. ND BOP. NU WH. TIH down annulus w/ 3/4" tubing. Pump 3 bbls class G Neat cement at 15.6 ppg and fill to surface. POH w/ 3/4" tubing, top annulus off. Set slips. Cut 7" casing to desired height. Dress and re install casing head. Pressure test casing to 760 psi. Dropped to 720 psi in 30 min. Tested good.
- 10. TIH w/ on/off tool and latch hornet packer. Open valve and equalize. Release packer, TOH, and LD packer assembly. TIH and latch RBP. Equalize pressure. TOH w/ RBP and LD.
- 11. TIH with 2-3/8" tubing per Production Foreman specifications.
- 12. ND BOP, NU WH.
- 13. RDMO WSU. Turn well over to production.