Form 3160-5 (August 2007)

UNITED STATES DE BU

RECEIVED

FORM APPROVED OMB No. 1004-0137

EPARTMENT OF THE INTERIOR				
REAU OF LAND MANAGEMENT	JUL	12	2013	

Expires: July 31, 2010

			5. Lease Serial N		
		Farmington F	iald (Micc	SF-081	325
SUN	DRY NOTICES AND REPO	DRTS ON WELLS		ottee or Tribe Name	
	e this form for proposals t well. Use Form 3160-3 (A		, -		
					1/)
	IBMIT IN TRIPLICATE - Other ins	ructions on page 2.	7. If Unit of CA	/Agreement, Name and	
1. Type of Well	V 0 - W-11		9 Well Mense	Canyon La	rgo Unit
Oil Well 2	K Gas Well Other		8. Well Name ar	ng No. Canyon Larg	go Unit 86
2. Name of Operator Burling	ton Resources Oil & Gas	Company LP	9. API Well No.	30-39-05	237
3a. Address		3b. Phone No. (include area cod	e) 10. Field and Po	ool or Exploratory Area	
PO Box 4289, Farmington, NM 87499 (505) 326-9700			Ballard PC		
4. Location of Well (Footage, Sec., T.,R			11. Country or I	Parish, State	
Surface UL J (NV	NSE), 1850' FSL & 1650' F	EL, Sec. 35, T24N, R6V	V Rio	Arriba , l	New Mexico
12. CHECK 1	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE (OF NOTICE, REPOR	RT OR OTHER DA	ATA
TYPE OF SUBMISSION		TYPE C	OF ACTION		
X Notice of Intent	Acidize	Deepen	Production (Start/	Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	一	Other
	Change Plans	X Plug and Abandon	Temporarily Aban	ndon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	-	
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent det	nils, including estimated starting of	late of any proposed worl	k and approximate dur	ation thereof.
	onally or recomplete horizontally, give		•	•	
	vork will be performed or provide the				•
	ed operations. If the operation results Abandonment Notices must be filed of		-		
determined that the site is ready for		my arter an requirements, meruu	ing reciamation, have bee	in completed and the o	perator has
,	•				
-	equests permission to P&A	•		•	•
	isturbance site visit was he	d on 7/9/13 w/ Bob Swit	zer. The Re-Veget	tation Plan is att	ached. A
closed loop system will	be utilized for this P&A.				
Notify NMOCD 24 hrs prior to beginning operations		hrs	RCVD JL	<u>IL 18'13</u>	
		ng		NS.DIV.	
			DIST. 3		

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Kenny Davis	Title Staff Regulatory Te	chnician
Signature	Date	7/11/2013
THIS SPACE FOR FE	DERAL OR STATE OFFICE U	SE
Approved by Original Signed: Stephen Mason	Title	Date JUL 1 6 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ConocoPhillips **CANYON LARGO UNIT 86 (PC)** Expense - P&A

Lat 36° 16' 0.149" N

Long 107° 25' 57.756" W

Prepared by: Peer Reviwed by:

Kurtis Shaw Michelle Wilcox Date: Date: 04/15/13

Supervisor:

Ryan Frost

05/13/13

Twinned Location:

No

3003905237

Currently Surface Commingled:

No

Scope of Work:

P&A the wellbore and return the location to its natural condition.

Est. Rig Days:

Area:

26

Route:

656

Formation:

PC

Spud Date:

LOCATION:

API:

1850' FSL & 1650' FEL, Spot J, Section 35 -T 024N - R 006W

None

Est. Reservoir Pressure (psia):

300 (PC)

Well Failure Date:

Artificial lift on well (type):

N/A

Earthen Pit Required:

NO

H25:

0 ppm; Always Verify! this well has no known history of producing H2S. If while the rig is on location, H2S is suspected or encountered please contact Robert Ingram (324-5166) to evaluate for an H2S Contingency Plan and contact HSE H2S SPOC.

Special Requirements:

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up. Also, two 5-1/2" cement retainers, a CBL, a mill for 5-1/2" 15.5# casing, and a 2-3/8" workstring with tools to handle will be needed.

Contacts	Name	Office #	Cell#
PE Production Engineer	Kurtis Shaw	324-5193	215-3470
PE Backup	Michelle Wilcox	599-3460	405-517-0626
MSO	Mike Brown		609-3909
Lead	Ramon Florez	599-3479	320-2506
Area Foreman	Vance Roberts	599-3467	320-9567

Well History/Justification

The Canyon Largo Unit 86 was drilled and completed in March 1957 in the Pictured Cliffs. The wellbore includes 5-1/2" casing with 1-1/4" tubing. The well does not have any history of remedial work, slickline, or swabbing. In the past 11 years, the well has been unable to sustain production over 6 MCFD.

The well is currently producing 3 MCFD. Since the well is at the end of its life, we do not expect to gain any production through remedial work. RAM's forecast indicates that we are currently producing below our abandonment rate.

Recommendation

Economic analysis shows that at the current rate the well is not profitable. The well has been unprofitable every month of the past year. In addition, there are no possible remedial options. It is recommended to P&A the wellbore and return the location to its natural condition.

ConocoPhillips CANYON LARGO UNIT 86 Expense - P&A

Lat 36° 16' 0.149" N

Long 107° 25' 57.756" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.
- 6. TOOH and lay down the 1-1/4" tubing (per pertinent data sheet).

Rods: No Size: Length:
Tubing: Yes Size: 1-1/4" Length: 2065'
Packer: No Size: Length:

- 7. PU 4-3/4" bit and string mill on 2-3/8" EUE work string and round trip to 2045' or as deep as possible.
- 8. PU cement retainer for 5-1/2" 15.5# casing and set at 1995'. Pressure test tubing to 1000 psi. Pressure test casing to 800 psi. If casing does not test, then spot and tag subsequent plugs as necessary. Run CBL and adjust plugs accordingly.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

9. Plug 1 (Pictured Cliffs, 1895-1995', 17 Sacks Class B Cement)

Mix 17 sx Class B cement and spot insided the casing above the CR to isolate the Pictured Cliffs perforations and Pictured Cliffs formation top. PUH.

1801 1450

10. Plug 2 (Fruitland, Kirtland, and Ojo Alamo, 1455-1275', 42 Sacks Class B Cement)

Mix 42 sx Class B cement and spot a balanced plug inside the casing to isolate the Fruitland, Kirtland, and Ojo Alamo formation tops. PUH.


11. Plug 3 (Nacimiento, 1089-1189', 17 Sacks Class B Cement)


Mix It's Class B cement and spot a balanced plug inside the casing to isolate the Nacimiento formation top. POOH.

12. Plug 4 (Surface Shoe and Surface Plug, 0-170', 68 Sacks Class B Cement) Nacional 94'

Perforate 3 HSC holes at 170'. Establish good circulation out the bradenhead with water and circulate annulus clean. Mix 68 sx Class B cement and pump down production casing to circulate good cement out the bradenhead. Shut in the well and WOC.

13. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	to	notice	of
Intention to	Ah	andon	

Re: Permanent Abandonment Well: 86 Canyon Largo Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Fruitland/Kirtland/Ojo Alamo plug from 1851' 1450'.
- b) Place the Nacimiento/Surface plug from 170' to surface inside and outside the 5 ½" casing.

Note: Nacimiento top is 94'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.