Office • District I – (575) 393-6161	State of New Mexico		Form C-103
<u>=&gt;15(11001</u> (575)555 0101	Energy, Minerals and Natural Reso	ources	Revised August 1, 2011
. 1625 N. French Dr., Hobbs, NM 88240 • <u>District II</u> – (575) 748-1283		20.045	API NO.
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVIS	$ION = \frac{30-045-}{5}$	ate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		TATE  FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		VO9208	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK ATION FOR PERMIT" (FORM C-101) FOR SUCH		e Name or Unit Agreement Name
	Gas Well 🔲 Other		Number 0 2308-161 #147H
Name of Operator     WPX Energy Production LLC		9. OGR 120782	ID Number
3. Address of Operator			l name or Wildcat
P.O. Box 640 – Aztec, NM 87410 -	Phone 333-1808	<b>I</b>	Gallup/ Basin MC
4. Well Location			
Unit LetterI : 149	feet from the SOUTH line an	d <u>248</u> feet	from the _EASTline
Unit Letter L : 22	91feet from the SOUTH line and		from the WEST line
Section 16 Townsh		MPM Co	unty SAN JUAN
	11. Elevation (Show whether DR, RKB, R	T, GR, etc.)	
	6858'		Supplied to the state of the st
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	PLUG AND ABANDON  REMED CHANGE PLANS COMM	SUBSEQUE DIAL WORK ENCE DRILLING OF G/CEMENT JOB	RCVD MAY 16 '13
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passay AND TEST WH to 2500 psi for 10 min, gooding tanks	proposed completion or rester. RD and release Anto	completion.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of partial ASSY AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.	rtinent dates, including expression or restance of the test. RD and release Anter	DIST. 3 stimated date of starting any proposed work). completion.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos I <sup>st</sup> stage, 9453'-9503' N	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of partial ASSY AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.	rtinent dates, including expression or restance of the test. RD and release Anter	DIST. 3 stimated date of starting any proposed work). completion.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos Ist stage, 9453'-9503' N	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passes AND TEST WH to 2500 psi for 10 min, gooding tanks  C @ 3680' MD.  min. Good test.	rtinent dates, including expressed completion or retest. RD and release Anto	DIST. 3 stimated date of starting any proposed work). completion.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos I <sup>st</sup> stage, 9453'-9503' N	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of partial ASSY AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.	rtinent dates, including expressed completion or retest. RD and release Anto	DIST. 3 stimated date of starting any proposed work). completion.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos Ist stage, 9453'-9503' N  Spud Date:  2/20/13	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passive ASSY AND TEST WH to 2500 psi for 10 min, gooding tanks  C @ 3680' MD.  min. Good test.  AD with 24, 0.40" holes  Rig Release Date:	rtinent dates, including expressed completion or restest. RD and release Ante	Stimated date of starting any proposed work). completion.  CONFIDENTIAL
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos Ist stage, 9453'-9503' N  Spud Date:  2/20/13	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of partial ASSY AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.	rtinent dates, including expressed completion or restest. RD and release Ante	Stimated date of starting any proposed work). completion.  CONFIDENTIAL
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615'  4-15-13- Perf Mancos I <sup>st</sup> stage, 9453'-9503' N  Spud Date:  2/20/13  I hereby certify that the information as	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passes AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.  AD with 24, 0.40" holes  Rig Release Date:  3/  bove is true and complete to the best of my	rtinent dates, including exproposed completion or restest. RD and release Antology and the state of the state	stimated date of starting any proposed work). completion.  CONFIDENTIAL  ef.
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos Ist stage, 9453'-9503' N  Spud Date:  2/20/13	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passive ASSY AND TEST WH to 2500 psi for 10 min, gooding tanks  C @ 3680' MD.  min. Good test.  AD with 24, 0.40" holes  Rig Release Date:	rtinent dates, including expressed completion or restest. RD and release Ante	Stimated date of starting any proposed work). completion.  CONFIDENTIAL
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 – MIRU BASIN WL and run CBL, TO  4-2-13 – Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13-Run Defit test thru alpha sleeve 9615'  4-15-13- Perf Mancos I <sup>st</sup> stage, 9453'-9503' N  Spud Date:  2/20/13  I hereby certify that the information as	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passes AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.  AD with 24, 0.40" holes  Rig Release Date:  TITLE Permit Supry  E-mail address: larry.higgins@wp	rtinent dates, including expreposed completion or restest. RD and release Antology and the second se	stimated date of starting any proposed work). completion.  CONFIDENTIAL  ef.  5/16/13  NE: 333-1808
OTHER:  13. Describe proposed or completed ope SEE RULE 19.15.7.14 NMAC. Fo  3-20-13- RU Antelope and NU 4-1/16" FRAC  3-21-13 thru 3-31-13- Triple S Trucking haul  4-1-13 - MIRU BASIN WL and run CBL, TO  4-2-13 - Test 4-1/2" Prod CSG 1500 PSI for 35  4-3-13 thru 4-13-13- Preparing for HF  4-14-13- Run Defit test thru alpha sleeve 9615"  4-15-13- Perf Mancos Ist stage, 9453'-9503' N  Spud Date:  2/20/13  I hereby certify that the information a  SIGNATURE  Type or print name Larry Higgins	rations. (Clearly state all pertinent details, and give per Multiple Completions: Attach wellbore diagram of passes AND TEST WH to 2500 psi for 10 min, good ing tanks  C @ 3680' MD.  min. Good test.  AD with 24, 0.40" holes  Rig Release Date:  3/  bove is true and complete to the best of my  TITLE Permit Supry	rtinent dates, including expreposed completion or restest. RD and release Antology and the second se	stimated date of starting any proposed work). completion.  CONFIDENTIAL  ef.  5/16/13

## Chaco 3208-32P #147H - Page 2

<u>4-16-13</u>- Frac Mancos thru alpha sleeve @ 9615' and perfs 9453'-9503' stage with 167,840# 20/40 PSA Sand
Set flo-thru frac plug @ 9428' MD. Perf 2<sup>nd</sup> 9268'-9392', 24 total, 0.40" holes Frac Mancos 2<sup>nd</sup> stage with 168,840 # 20/40 PSA Sand
Set flo-thru frac plug @ 9244' MD.

Perf 3<sup>rd</sup> stage 9053'-9214',24, 0.40" holes. Frac Mancos 3<sup>rd</sup> stage with 167,100#, 20/40 PSA Sand

4-17-13- Set flo-thru frac plug @ 9035' MD. Perf 4<sup>th</sup> stage 8916'-9002'- with 24, 0.40" holes. Frac Mancos 4<sup>th</sup> stage with 168,156#, 20/40 PSA Sand Set flo-thru frac plug @ 8892' MD. Perf 5<sup>th</sup> stage 8486' -8620'-with 24, 0.40" holes. Frac Mancos 5<sup>th</sup> stage with 165,631#, 20/40 PSA Sand Set flo-thru frac plug @ 8600' MD. Perf 6<sup>th</sup> stage 8486' -8620'-with 24, 0.40" holes. Frac Mancos 6<sup>th</sup> stage with 165,870#, 20/40 PSA Sand Set flo-thru frac plug @ 8420' MD. Perf 7<sup>th</sup> stage 8255'-8405'- with 24, 0.40" holes. Frac Mancos 7<sup>th</sup> stage with 164,353#, 20/40 PSA Sand Set flo-thru frac plug @ 8180' MD. Perf 8<sup>th</sup> stage 7983'-8142'- with 24, 0.40" holes. Frac Mancos 8<sup>th</sup> stage with 166,884#, 20/40 PSA Sand Set flo-thru frac plug @ 7945' MD. Perf 9<sup>th</sup> stage 7740'-7906'- with 24, 0.40" holes. Frac Mancos 9<sup>th</sup> stage with 165,738#, 20/40 PSA Sand Set flo-thru frac plug @ 7630' MD. Perf 10<sup>th</sup> stage 7465'-7605'- with 24, 0.40" holes. Frac Gallup 10<sup>th</sup> stage with 172,171#, 20/40 PSA Sand 4-18-13- Set flo-thru frac plug @ 7444' MD. Perf 11<sup>th</sup> stage 7310'-7414'- with 24, 0.40" holes. Frac Gallup 11<sup>th</sup> stage with 167,254#, 20/40 PSA Sand Set flo-thru frac plug @ 7285' MD. Perf 12<sup>th</sup> stage 7133'-7252'- with 24, 0.40" holes. Frac Gallup 12<sup>th</sup> stage with 164,300#, 20/40 PSA Sand Set flo-thru frac plug @ 7090' MD. Perf 13<sup>th</sup> stage 6926'-7057'- with 24, 0.40" holes. Frac Gallup 13<sup>th</sup> stage with 164,501#, 20/40 PSA Sand Set flo-thru frac plug @ 6628' MD. Perf 14<sup>th</sup> stage 6660' -6822'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 209,041#, 20/40 PSA Sand Set flo-thru frac plug @ 6628' MD. Perf 15<sup>th</sup> stage 6444'-6598'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 204,644#, 20/40 PSA Sand Set flo-thru frac plug @ 6628' MD. Perf 16<sup>th</sup> stage 6551'-6368'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 204,644#, 20/40 PSA Sand Set flo-thru frac plug @ 6403' MD. Perf 16<sup>th</sup> stage 6551'-6368'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 206,215#, 20/40 PSA Sand Set flo-thru frac plug @ 6408' MD. Pe

4-19-13- Frac Gallup 17th stage with 206,738#, 20/40 PSA Sand

Set flo-thru frac plug @ 5928' MD. Perf 18<sup>th</sup> stage 5696'-5900'- with 24, 0.40" holes. Frac Gallup 18<sup>th</sup> stage with 204,906#, 20/40 PSA Sand Set 4-1/2" CIPB @ 4607'

4-20-13- MIRU HWS #6

4-21-13- test BOP

<u>4-22-13-</u> DO CIBP 4607' and DO flo thru Frac plug 5928', 6188', and 6403'

**4-23-13-** DO flo-thru frac plug @ 6628', 6860', 7090', 7285', 7444', 7630', 7945'

4-24-13 - DO flo-thru frac plug @ 8180', 8420',8660', 8892' and 9035'

4-25-13 - DO flo-thru frac plug @, 9244' and 9428'

4-26-13- First deliver Oil to sales

4-27-13 thru 5-6-13- Flow, test and C/O well PBTD 9663'

5-7-13- Land well at 5311' w/ 14.5' KB as follows, 1/2 MS, 170 jts total, 1 Jt 2.375" 4.7#, J55 8rnd tbg, 1.78" R-Nipple w/ no go, 2 Jts of 2.375" 4.7#, J55 8rnd tbg, Weatherford 4.5" Arrowset Production Pkr at 5209', 4.5"x 2.375" On/Off Tool, 1.81" SN, 4 Jts of 2.375"4.7#, J55 8rnd tbg, GLV #1 at 5081' w/ surface open at 460 psi, 17 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #2 at 4551' w/ surface open at 592 psi, 20 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #3 at 3927' w/ surface open at 620 psi. 20 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #4 at 3303' w/ surface open at 642 psi, 19 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #5 at 2714' w/ surface open at 661 psi, 20 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #6 at 2090' w/ surface open at 683 psi, 20 Jts of 2.375" 4.7#, J55 8rnd tbg, GLV #7 at 1467' w/ surface open at 700 psi, 47 Jts of 2.375" 4.7#, J55 8rnd tbg