Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 06

FORM APPROVED OMB No. 1004-0137

L	ease	Serial	No.	

Expires: July 31, 2010 \$794 \$F-080245

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
shandoned well. Hee Form 3160-3 (APD) for such proposals	

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3	(APD) for such proposals.		
SUBMIT IN TRIPLICATE - Other	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	Canyon Largo Unit		
Oil Well X Gas Well Oth	ner	8. Well Name and No.  Canyon Largo Unit 85	
2. Name of Operator	9. API Well No.		
Burlington Resources Oil & G	30-039-05472		
3a. Address	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499	(505) 326-9700	Ballard PC	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)  Surface  UL I (NESE), 1650' FSL & 990'	FEL, Sec. 13, T24N, R6W	11. Country or Parish, State Rio Arriba , New Mexico	
12. CHECK THE APPROPRIATE BOX(	ES) TO INDICATE NATURE OF N	OTICE, REPORT OR OTHER DATA	

TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
BP	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burlington Resources Oil & Gas Company LP requests permission to P&A the subject well per the attached procedure, current & proposed well bore schematics. The pre-disturbance site visit was held on 8/1/13 w/ a BLM Representative. The Re-Vegetation Plan is attached. A Closed Loop System will be utilized for this P&A.

OIL CONS. DIV DIST. 3 AUG 1 2 2013

Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)			
Kenny Davis	Title S	Staff Regulatory Technic	ian
Signature	Date		8/5/2013
THIS SPACE FOR FEI	DERAL OR	STATE OFFICE USE	
Approved by			
Original Signed: Stephen Mason		Title	DAUG 0 8 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant	t or certify		
that the applicant holds legal or equitable title to those rights in the subject lease whice entitle the applicant to conduct operations thereon.	Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

## ConocoPhillips CANYON LARGO UNIT 85 Expense - P&A

Lat 36° 18' 35.784" N

Long 107° 24' 50.256" W

## **PROCEDURE**

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and pump at least tubing capacity of water down tubing.
- 6. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.
- 7. TOOH with 1-1/4" tubing (per pertinent data sheet) and lay down.

Tubing: Yes Size: 1-1/4" Set Depth: 2176'

8. PU 2-3/8" EUE workstring and watermelon mill for 5-1/2" OD, 4.95" ID and round trip to the top of the perfs @ 2110' or as deep as possible.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

- 9. PU and set CR for 5-1/2" OD, 4.95" ID casing at 2060' on tubing. Load hole with water and circulate clean. Pressure test casing to 800 psi and tubing to 1000 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. TOOH with tubing.
- 10. RU wireline and run CBL from 2060' to surface and contact Rig Supervisor and Wells Engineer with results.
- 11. Plug 1 (Pictured Cliffs Perfs and Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo Formation Tops, 1480'-2060', 72 Sacks Class B Cement)

TIH with tubing. Mix 72 sxs Class B cement and spot a balanced plug inside the casing to isolate the Pictured Cliffs perforations and the Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo formation tops. POOH.

## 12. Plug 2 (Surface Shoe, 0-164', 67 Sacks Class B Cement)

Perforate 3 squeeze holes at 164'. Establish circulation out the bradenhead with water and circulate BH annulus clean. Mix 67 sxs Class B cement and pump down production casing to circulate good cement out the bradenhead. Shut in well and WOC.

13. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



