Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-045-29118
811 S. First St., Artesia, NM 88210	S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	tec NM 87410		STATE FEE S
District IV – (505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		•	CA#NM92466 NMNM014375
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Riggs
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 2
 Type of Well: Oil Well ☐ Gas Well ☒ Other Name of Operator Four Star Gas & Oil Company 			
2. Name of Operator Four Star Gas & On Company			9. OGRID Number 131994
3. Address of Operator			10. Pool name or Wildcat
ATTN: Regulatory Specialist 332 Road 3100 Aztec, New Mexico 87410		Basin Fruitland Coal	
4. Well Location			
	75 feet from the South line and	1640 feet from	n the West line
Section 4 Towns	- -	NMPM	County San Juan
Section			
	5732' GL	raib, m, on, ere	
12. Check Appropriate Box to		eport or Other	Data
• •	•		
NOTICE OF IN			SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS		RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE			
OTHER.		OTHER.	С
OTHER:	leted operations (Clearly state all)	OTHER:	nd give pertinent dates, including estimated date
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Co	ompletions: Attach wellbore diagram of
3/28/2013	ompletion.		RCVD MAY 1'13
MIRU.	·		-
WIRO.			OIL CONS. DIV.
4/1/2012			DIST. 3
4/1/2013	The B d advantage and a second		
POOH with 68 3/4" rods and LD pump. The B-1 adaptor hard to remove as well as hanger hold down pins. NU BOP's and fill BOP's with fluid tested to 1500 PSI. Held for 5 minutes, good test, bled off pressure. SWIFN.			
NO BOP'S and this BOP'S with fluid tested to 1500 PSI. Held for 5 minutes, good test, bled off pressure. Swifin.			
		, j	
4/2/2012	•	• '	
4/2/2013 Spotted in equipment to lay down tubin	ng POOH with 56 joints and laid down	tally tubing and loa	dod onto tubing float
Unload and tally tubing, PU and RIH wit			ued onto tubing noat.
Omodu and tany tubing, to and thir wit	in 50 joint, bit, bit sub, string noat. 5441	114.	
See attached pages for complete proce	dure and well bore diagram		
# Did not comply with were not approved prior	OCO Rules: 19.15.5.11, to performing the work.	19.15.7.14. A	(1)(a) and 19.15.7.14 A(1)(b) casing changes
Sand Date: 06/28/1994			
Spud Date: 06/28/1994	Rig Release Da	te:	
		<u> </u>	
I hereby certify that the information :	above is true and complete to the be	st of my knowledg	ge and belief.
A = A	Dol		,
SIGNATURE SPANE	TITLE Re	gulatory Specialist	DATE <u>4-30-/2</u>
/	1	101101	DIANTE SOS OCCUPA
Type or print name April E. Poh	E-mail address: A Depu	April Pohl@chevro	n.com PHONE:505-333-1941
For State Use Only APPROVED BY:	M. TITLE	District #	
Conditions of Approval (if any):	A/		DATE

4/3/2013

POOH with 50 Joints and LD scrapper, bit and bit sub.

PU RBP and RIH set RBP at 1050 FT, filled hole with fluid. Tested casing to 500 PSI, did not hold. Found a hole in the production casing. PU and RIH with RBP set at about 20 FT down in the well and tested from 20 FT to 1050 FT to 500 PSI held for 30 minutes. RIH with rods. RIH with 3/4" rods and LD all rods. SWIFN.

4/4/2013

POOH and LD 30 joints of tubing.

PU and RIH with 5.5" RBP set at 490 FT, Put 21 Ft of sand on top of RBP. POOH and LD setting tool.

PU and RIH with collar locator found collars at 27.15 FT POOh and LD tool.

4/5/2013

Had the one call done on the location. ND BOPs and NU night cap, RD lines from well head.

Spotted in rig and equipment, and RU rig and rig floor.

4/8/2013

Spotted in vac truck and equipment to dig around well head.

Cleared out dirt and rocks, difficult digging the rocks around well head to get down about ~5 FT.

4/9/2013

RU rig floor and made up tools to cut casing.

PU and RIH with 5.5" cutter, cut casing at 31 FT down hole. POOH with casing and LD cutter. PU and RIH with spire pulled 5.5" casing and LD same.

Had to clean out cement out from around surface casing to get down to good casing. Had to shut down because we need to have a vacuum truck get more

4/10/2013

Spotted in vacuum truck to excavate more dirt from around well head. Cut the 8 5/8" surface casing, welded on new 8 5/8" surface casing and tubing top flange. Back filled the hole. Capped surface casing, SWIFN.

4/11/2013

PU and RIH with 7.43" dress off tool, Dressed off the 5.5" casing at 31.5 FT. POOH and LD tools.

Moved equipment pout and moved equipment in and RU to run 5.5" casing.

PU casing patch and RIH tagged at 31 FT in and set down 10-K, pulled 60-K, left 40-K on it to set slips.

Cut 5.5" casing and dress off place 7 1/8" top flange on, tested void to 1500 PSI held for 10 minutes good test.

4/12/2013

Removed night cap on well, NU BOPs, and rig floor. Tested BOPs and casing patch to 500 PSI held for 5 minutes good test.

Unloaded tubing and loaded casing.

PU and RIH with retreving head and 15 joints wasned over RBP at 490 FT and latch onto the plug.

POOH with RBP and LD same.

PU and RIH with retrieving head to pull RBP at 1050 FT, was unable to get the plug to move up hole the plug is released but won't move.POOH with tubing and rack back.

4/15/2013

PU retrieving tool, Bumper Sub, 6- 3 3/8" Drill collars, RIH, Latch RBP @ 1050. Work fish, work free, POOH. Recovered RBP, RIH

w/ 6 DC's, POOH, LD same

PU & RIH w/ Muleshoe, SN, 45 jts 2 3/8" tbg.

Continue in hole w/ 12 jts, 4' pup jt 1 jt banding cap string to outside of tbg. Land tbg. Total of Muleshoe(18.38), SN (1.10), 57 jts 2 3/8, 4.7#, J55

yellowband tbg(1728.64), 4' pup j(4.22)t, slick j(28.90)t, EOT -1796.91, SN - 1778.53

RD Floor, Tongs, ND BOP's, NU WH, Test void to 2000 psi. Test good. Secure well, SDFN.

4/16/2013

Check well, SITP - 50 psi, SICP - 50 psi, Open well to flowback tank and bleed down.

PU Rod Handling tools, Install Radigan, pump tee, PU and RIH in singles w/ 2 x 1 1/4" x 14' x 14' 3" RHAC-Z pump (cx 613, Stabilizer bar, 2 - 1 1/4" x 25'

Sinker Bars, 68 - 3/4" x 25' sucker rods, Space out w/ 1 1/4" x 16' Polish Rod

Load and test tbg to 500 psi, bleed down and check pump action to 500 psi. Clamp well off.

RD Pump and lines, PU tools, Clean location, will have trucks in A.M. for rig move



Wellbore Schematic

